



## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>16 Jun 2022, 13:20:18</b>
Transaction Number	<b>36566486 (CC10008)</b>	Queue Number	<b>312309</b>



Chassis Number	<b>JTJBGMC9H2022270</b>
Engine Number	
Vehicle Class	<b>Car</b>
Manufacturer	<b>Lexus</b>
Model	<b>RX450 H</b>
Model Year	<b>2017</b>
Color	<b>White</b>
Mileage	<b>104008 Km</b>
Fuel Type	<b>Hybrid</b>
No. Of Cylinders	<b>6</b>
Specification	<b>GCC Specification</b>

DEFECT	REMARKS	
<b>01 Interior Condition</b>		<b>الحاله الداخليه</b>
01.A AC Condition	OK	المكيف
01.B Sun Visor	LEFT SIDE STAND MISSING	حاجب الشمس
01.C Roof Ceiling	PORTION LOOSE	بطانه السقف
01.D Mirror	VIEW MIRROR MINOR LOOSE	المرايا
01.E Other	CENTER CONSOLE BOX PORTION CRACKED	اخرى
<b>02 Seats Condition</b>		<b>المقاعد</b>
02.A Seat Condition	DRIVER SEAT HAVE MINOR CUT	حالة المقاعد
<b>03 Transmission Condition</b>		<b>الجير</b>
03.A Road Test	NOT CHECK	فحص علي الطريق
03.B Visual Gear Box Condition	OK	حالة الجير النظرى
03.C Gear Box Mount	MOUNT RUBBER CRACKED	كرسي الجير
<b>04 Suspension System</b>		<b>ممتص الصدمات</b>
04.A Arms	BOTH SIDE LOWER ARM BUSHES CRACKED	ازرع
04.B Ball Joint	BOOT CUT	مفصل كروي

DEFECT	REMARKS	
<b>05 Chassis Condition</b>		<b>النشاصي</b>
05.A Chassis	FRONT BOTH SIDE CHASSIS REAIRED RIGHT SIDE JOINT AREA DETACHED & MINOR DENT	النشاصيه
<b>06 Body</b>		<b>جسم المركبة</b>
06.A Sign of front accident		وجود مؤشر لحادث في المقدمة
06.B Other	FRONT BUMPER FRAME BULK HEAD FENDER FRAME RADIATOR SUPPORT REPAIRED	اخري
06.C Paint	BODY REPAINTED PORTION REPAIRED MINOR DENTS SCRATCHES ON BODY	الصبغ
06.D Fenders	FRONT BOTH SIDE REAR RIGHT SIDE REPAINTED PORTION REPAIRED	مدكار
06.E Doors	RIGHT SIDE DOOR PORTION REPAINTED	أبواب
06.F Sign of side accident		وجود مؤشر لحادث في الجانب
06.G Bonnet	REPAINTED REFITTED	غطاء المحرك
<b>07 Engine Condition</b>		<b>المحرك</b>
07.A Visual Engine Condition	MINOR OIL LEAK	حالة المحرك النظري
<b>08 Tires and Rims Condition</b>		<b>الاطارات</b>
08.A Front Tyre	BOTH SIDE 2020 WORN OUT	الاطار الامامي
08.B Rear Tyre	BOTH SIDE 2020	الاطار الخلفي

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

# Test Certificate



Vehicle  
Registration



✓ PASS

Plate Details :	5 39912 Abu Dhabi Private
Chassis No :	JTJBGMA9H2022270
Vehicle Make :	LEXUS
Vehicle Model :	RX 450H
Vehicle Class :	Light Vehicle
Body Type :	STATION
Fuel :	Benzene + Electricity
Color :	White
Drive Direction :	--
Dimensions : (H x W x L) :	-- x -- x --
Current Odometer :	104005 Kms.
Origin :	Japan
Model Year :	2017
Gear Type :	Automatic
Engine Size :	3500 CC
Engine No :	2GRK371988
Horse Power :	308
Axles No :	2
Cylinders :	6
No Of Doors :	4
No Of Seats :	5
G. V. W. :	2150 Kgs.
	2722 Kgs.

Certificate Number :	1-TAS-2022-16999232
Inspection Date :	14-06-2022
Certificate Print Date :	14-06-2022
Services :	Renewal Test
Vehicle Testing Partner :	Tasjeel
Vehicle Testing Center :	Tasjeel Al Aweer
Total Time Taken :	8 min 7 sec
Appointment Ref Number :	--
Start Time :	20:24
End Time :	20:33
Lane :	01
Token No. :	266
Attempt :	1
Prints No. :	1

## Parameter Readings

Service brake imbalance on front axle  
2 %

Service brake imbalance on rear axle  
16 %

Parking brake imbalance between LHS and RHS  
16 %

Vehicle on Petrol CO Reading  
0 %

Vehicle on Petrol HC Reading  
10 PPM VOL

## Inspection Remarks:

FRONT BOTH SIDE CHASSIS REPAIRED HAVING PASS CCM REPORT WORK-ORDER # 2022-06-12-2 / FRONT BOTH SIDE FENDER APRON & FENDER INNER MEMBER REPAIRED

## Payment Details

Inspection Performed by  
62439

Payment Method  
Cash

Transaction Number  
16999232

Service Fees  
AED 170 Collected on 14/06/2022

Parking Slot No  
--

Service Name  
Renewal Test

Attempt  
1

Received by  
Hussain Basha Akeel

- This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.
- Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالترخيص الفني للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص.

This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.

