



## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>31 Jul 2022, 13:46:30</b>
Transaction Number	<b>67867156 (CC10006)</b>	Queue Number	<b>312309</b>



Chassis Number	<b>WBAKB8107AC342896</b>
Engine Number	
Vehicle Class	<b>Car</b>
Manufacturer	<b>BMW</b>
Model	<b>750LI</b>
Model Year	<b>2010</b>
Color	<b>Black</b>
Mileage	<b>311649 Km</b>
Fuel Type	<b>Petrol</b>
No. Of Cylinders	<b>8</b>
Specification	<b>GCC Specification</b>

DEFECT	REMARKS	
<b>01 Engine Condition</b>		
<b>المحرك</b>		
01.A Visual Engine Condition	OIL LEAK & REFITTED	حالة المحرك النظري
01.B Mount	MOUNT BUSH CRACKED	كرسي
01.C Smoke	WHITE SMOKE	دخان
<b>02 Transmission Condition</b>		
<b>الجير</b>		
02.A Visual Gear Box Condition	OIL LEAK & REFITTED	حالة الجير النظري
02.B Road Test	NOT CHECK	فحص علي الطريق
02.C Gear Box Mount	MOUNT BUSH CRACKED	كرسي الجير
<b>03 Body</b>		
<b>جسم المركبة</b>		
03.A Fenders	PORTION REPAIRED,REPAINTED	مدكار
03.B Doors	REPAINTED,PORTION REPAIRED	أبواب
03.C Bonnet	PORTION REPAIRED,REPAINTED & REFITTED	غطاء المحرك
03.D Paint	BODY PORTION REPAIRED,REPAINTED & MINOR DENT SCRATCHES	الصبغ
03.E Floor	UNDER FLOOR CHASSIS FENDER FULLY COVERED & OILY CHECKED VISIBLE AREA	الارضية
03.F Windshield	REAR CURTAIN NOT WORKING ON MAIN SWITCH	زجاج

DEFECT	REMARKS	
<b>04 Interior Condition</b>		<b>الحاله الداخليه</b>
04.A AC Condition	OK	المكيف
04.B Door Panel	PORTION DAMAGED	لوحة بطانة الباب
04.C Power Window Switch	REAR BOTH SIDE CURTAIN NOT WORKING	مفتاح النافذه
<b>05 Seats Condition</b>		<b>المقاعد</b>
05.A Seat Condition	DRIVER SEAT PRTION DAMAGED	حالة المقاعد
<b>06 Tires and Rims Condition</b>		<b>الاطارات</b>
06.A Front Tyre	BOTH SIDE 2021	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2021	الاطار الخلفي
06.C Rims Condition	RIMS HAVE DENT SCRATCHES	حالة الجنوط
<b>07 Steering Condition</b>		<b>المقود</b>
07.A Steering Oil	OIL LEAK	زيت المقود
07.B Steering Boot	BOOT CUT	ربلة المقود
07.C Tie Rod End	BOOT CUT	مؤخرة الرودادت
07.D Axel	FRONT AXLE BOOT LEAK	اكسلات
<b>08 Suspension System</b>		<b>ممتص الصدمات</b>
08.A Ball Joint	BOOT CUT	مفصل كروي
08.B Arms	FRONT LOWER ARM BUSH CUT	ازرع
<b>09 Chassis Condition</b>		<b>الشاسي</b>
09.A Chassis	CHECKED VISIBLE AREA OK	الشاسيه
09.B Other	FOR RECHECK PROERLY REMOVE COVER & WASH UNDER FLOOR OILY	اخرى

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.