



TEST CERTIFICATE

| | | | |
|--------------------|------------------------------|------------------|------------------------------|
| Site Number | 840-Emirates Auctions | Transaction Date | 06 Oct 2021, 09:36:10 |
| Transaction Number | 75493250 (CC10006) | Queue Number | 312309 |



| | |
|----------------|--------------------------|
| Chassis Number | MROFX22G2E1126536 |
| Engine Number | |
| Vehicle Class | Heavy |
| Manufacturer | Toyota |
| Model | Hilux |
| Model Year | 2014 |
| Color | White |
| Mileage | 321631 N/A |

| DEFECT | REMARKS | |
|------------------------------------|---|-------------------------|
| 01 Interior Condition | | الاجزاء الداخلية |
| 01.A AC Condition | NOT WORKING | المكيف |
| 01.B Other | CONSOLE BOX NOT CLOSING & HOLDING CAP COVER MISSING | اخرى |
| 01.C Mirror | ADJUSTMENT MIRROR NOT WORKING | المرايا |
| 02 Seats Condition | | المقاعد |
| 02.A Other | INNER DOOR PADS LEATHER REPLACED | اخرى |
| 03 Lights | | الاضاءة |
| 03.A Warning Light | WARNING ON IN DISPLAY | ضوء تحذير |
| 03.B Head Light | HEAD LIGHT LENS FADED | الاضاءة الرئيسية |
| 04 Tires and Rims Condition | | الاطارات |
| 04.A Front Tyre | BOTH SIDE 2017 WORNOUT | الاطار الامامي |
| 04.B Rear Tyre | BOTH 2019 | الاطار الخلفي |
| 05 Body | | جسم المركبة |
| 05.A Fenders | FRONT FENDER FRAME ,BULK HEAD,RADIATOR SUPPORT REPAIRED&FENDER REPAINTED,REFITIED | مدكار |
| 05.B Paint | BODY PORTION REPAINTED&PORTION REPAIRED | الصبغ |
| 05.C Doors | DOOR REPAINTED & REPAIRED | أبواب |
| 05.D Bumper | REPAINTED | دعامية |
| 05.E Bonnet | REPAINTED,REFITIED | غطاء المحرك |

| DEFECT | REMARKS | |
|----------------------------------|---|---------------------|
| 05.F Pillars | FRONT LEFT A/PILLAR OUTER REPAIRED,REPAINTED | القوائم |
| 05.G Rusty | UNDER BODY PART ,CHASSIS ,FLOOR GETTING MINOR RUSTY | صدأ |
| 05.H Other | INTERIOR DIRTY | اخرى |
| 06 Wipers and Arms | | المساحات |
| 06.A Other | WORN OUT | اخرى |
| 07 Engine Condition | | المحرك |
| 07.A Other | OIL LEAK | اخرى |
| 07.B Mount | ENGINE MOUNT CUT | كرسي |
| 08 Transmission Condition | | الجير |
| 08.A Gear Box | OK | الجير |
| 08.B Gear Box Mount | GEAR MOUNT CUT | كرسي الجير |
| 09 Exhaust System | | نظام العادم |
| 09.A Other | REAR TAIL PIPE SHORT | اخرى |
| 10 Steering Condition | | المقود |
| 10.A Steering Oil | OIL LEAK | زيت المقود |
| 10.B Tie Rod | FRONT STABILIZER LINK BOOT CUT | رودات |
| 11 Chassis Condition | | الشاسي |
| 11.A Chassis | OK | الشاسيه |
| 12 Suspension System | | ممتص الصدمات |
| 12.A Shock Absorber | FRONT & REAR SHOCK ABSROBER WEAK | ممتص الصدمات |
| 12.B Arms | FRONT LOWER ARMS BUSHES CUT | ازرع |

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.