





### Test Certificate

Site Number	: 840-EMIRATES AUCTION	Plate Code	: 0
Transaction Number	: 20379545	Plate Category	: PRIVATE
Transaction Date	: 27 JUL 2020 10:33:05	Plate Number	: 122981 EA
Queue Number	: 200352	Import Doc. Ref.	:
Chassis Number	: 1N4AL2A99AC122981	Manufacturer/Model	: NISSAN/ALTIMA
Engine Number	:	Model Year	: 2010
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: BLACK
Service / Indicator	: DSC AUCTION		

### Statement of Vehicle Condition

Defect	Result	Remarks
AUTOMATIC TEST:		
13 Brake System		الفرامل
13.04 - Brake Test	Passed	فحص الفرامل
14 Exhaust Gas Test		الغاز العادم والكربون
14.01 - Exhaust Gas Test	Passed	فحص الغاز العادم-الكربون
16 Side Slip Test		فحص ميزانية الاطارات
16.01 - Side Slip Test	Passed	فحص ميزانية الاطارات
VISUAL TEST:		
01 Lights		الانوار
01.04 - Head Lights		الانوار الامامية LENS FADED/ TAIL LIGHT BOTH CRACKED & PARTLY BROKEN
02 Steering And Suspension System		عجلة القيادة ونظام التوصيلات
02.04 - Steering Ball Joints, Boots		وصلات عمود عجلة القيادة
02.13 - Stub Axle Assemblies, Boots		المحور
03 Brake System		نظام الفرامل
03.01 - Brake Efficiency Front Wheels Left And Right Hands		قوة فرامل المحور الامامي BRAKE PAD WORNOUT/ROTOR DISC RUSTY
04 Tires Rims		الاطارات والعجلات
04.01 - Front Left And Right Hands Tires		الاطارات الامامية DOT 0618 5115/INCOMPLETE RIM CENTER CAP
05 Body		الهيكل
05.02 - Paint		الصبغ DENT/SCRATCHES/FADED/Front RIGHT POWER WINDOW NOT WORKING & REAR VIEW MIRROR FADED
05.03 - Doors		الابواب FRONT & REAR DOOR/DOOR PILLAR/ROOF/LEFT SIDE QUARTER PANEL REPAIRED
05.05 - Bumpers		الدعامية FRONT & REAR BUMPER FRONT LEFT FENDER/RADIATOR FRAME REPAIRED/PARTLY DAMAGED
05.07 - Floor		الارضية FLOOR & REINFORCEMENT DENT/LEFT SIDE RUNNING BOARD REPAIRED
05.08 - Chassis (Frame)		الشاصبية REAR BOTH CHASSIS END/REAR BUMPER SUPPORT & CRASH BOX DENT



### Test Certificate

Site Number	: 840-EMIRATES AUCTION	Plate Code	: 0
Transaction Number	: 20379545	Plate Category	: PRIVATE
Transaction Date	: 27 JUL 2020 10:33:05	Plate Number	: 122981 EA
Queue Number	: 200352	Import Doc. Ref.	:
Chassis Number	: 1N4AL2A99AC122981	Manufacturer/Model	: NISSAN/ALTIMA
Engine Number	:	Model Year	: 2010
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: BLACK
Service / Indicator	: DSC AUCTION		

### Statement of Vehicle Condition

06 General Items		الإشياء العامة
06.12 - Seats Condition And Seats Fixing	INTERIOR/COMPONENT/DASHBOARD PARTLY WORNOUT/REAR CAMERA NOT WORKING	المقاعد وحالتها وتثبيتها
06.14 - Transmission Condition	LEVER RELEASE BUTTON & PARKING BRAKE NOT WORKING	حالة ناقل الحركة
06.16 - Engine Condition, Smoke	OIL LEAK	حالة المحرك - الدخان
07 Remarks		ملاحظات
07.04 - Others	188512 KM	ملاحظات اخرى
09 Auction		الفحص الكامل
09.02 - Need Wheel Alignment		بحاجة الى ميزانية العجلات
09.14 - Sign Of Front Accident		أثر حادث في مقدمة المركبة
09.15 - Sign Of Rear Accident		أثر حادث في مؤخرة المركبة
09.16 - Sign Of Side Accident		أثر حادث في جوانب المركبة
09.18 - A/C Not Cooling		عطل في المكيف
09.24 - Digital Display Damaged/Warning Lights	WARNING LIGHTS ON/CONSOLE BOX MIS ALIGN	عطل في لوحة التحكم الالكتروني
09.25 - Body Repainted		أثر صيغ في المركبة
The Test Certificate Shows the test Result at the time of inspection only. Tasjeel is not responsible for any hidden defects.		

# Test Certificate



FAILED

Possession Certificate : 64299163	
Chassis No :	1N4AL2A99AC122981
Vehicle Make :	NISSAN
Vehicle Model :	ALTIMA
Vehicle Class :	Light Vehicle
Body Type :	SALOON
Fuel :	Benzene
Color :	Black carbon
Drive Direction :	--
Dimensions : (H x W x L) -- x -- x --	
Current Odometer :	188513 Kms.
Origin : United States	Model Year : 2010
Gear Type : --	Engine Size : 3500 CC
Engine No : qr25874769x	Horse Power : 175
Axles No : 2	Cylinders : 4
No Of Doors : 4	No Of Seats : 5
G. V. W. : 2100 Kgs.	Empty Weight : 1000 Kgs.

Certificate Number :	5-TAS-2020-12251173
Inspection Date :	29-07-2020
Certificate Print Date :	29-07-2020
Services :	Registration Test
Vehicle Testing Partner :	Tasjeel
Vehicle Testing Center :	Tasjeel Emirates Auction
Total Time Taken :	14 min 51 sec
Appointment Ref Number :	--
Start Time : 9:40	End Time : 9:55
Lane : 01	Token No. : 2
Attempt : 1	Prints No : 1

## Parameter Readings

Service brake imbalance on front axle 5 %	Service brake imbalance on rear axle 15 %	Parking brake imbalance between LHS and RHS 13 %	Vehicle on Petrol CO Reading 0.01 %
--	--	---	--

Vehicle on Petrol HC Reading  
12 PPM VOL

## Inspection Findings

Defects	Issue	Severity
Dip beams( Low Beams) headlight clean both side lens faded	Unsecure	Major
Bumper change rear both side crash box damage	Others (Major)	Major
Warning triangle	Missing	Major
Paint repaint body portion faded	Totally faded	Major

Discrepancies	Old Value	New Value	Verified
Engine Size Discrepancy in Engine Size	3500	2500	

## Inspection Remarks:

rear both side frame member end dent FRONT & REAR DOOR/DOOR PILLAR/ROOF/LEFT SIDE QUARTER PANEL REPAIRED