

# Test Certificate



Vehicle  
Registration



✓ PASS

Plate Details :	--
Chassis No :	MRODX6CD9G0200532
Vehicle Make :	TOYOTA
Vehicle Model :	HILUX
Vehicle Class :	Light Vehicle
Body Type :	PICK-UP
Fuel :	Benzene
Color :	White
Drive Direction :	--
Dimensions : (H x W x L)	-- x -- x --
Current Odometer :	294928 Kms.
Origin : Thailand	Model Year : 2016
Gear Type : Manual	Engine Size : 1800 CC
Engine No : 2TR8869693	Horse 162
Axles No : 2	Power :
No Of 4	Cylinders : 4
Doors :	No Of Seats : 6
G. V. W. : 2700 Kgs.	Empty 1692 Kgs.
	Weight :

Certificate Number :	5-TAS-2022-18189954
Inspection Date :	26-11-2022
Certificate Print Date :	26-11-2022
Services :	Registration Test
Vehicle Testing Partner :	Tasjeel
Vehicle Testing Center :	Tasjeel Al Aweer
Total Time Taken :	9 min 4 sec
Appointment Ref Number :	--
Start Time : 17:08	End Time : 17:17
Lane : 02	Token No. : 268
Attempt : 1	Prints No : 1

## Carbon footprint



Keep protecting Dubai environment

## Estimated Vehicle Consumption (Rate in 12 Months)

32769 KM	2329 L	7942 AED	5.6 ton
Distance per year	Fuel consumed per year	Fuel cost per year	Carbon footprint per year

## Parameter Readings

Service brake imbalance on front axle 16 %	Service brake imbalance on rear axle 8 %	Parking brake imbalance between LHS and RHS 14 %	Vehicle on Petrol CO Reading 0 %
Vehicle on Petrol HC Reading 28 PPM VOL			

## Inspection Findings

Discrepancies	Old Value	New Value	Verified
Engine Size Discrepancy in Engine Size	1800	2700	

Inspection Remarks: UNDERNEATH MINOR RUSTY DO RUST COATING ASAP , REGISTERED PERSONAL NAME

## Payment Details

Inspection Performed by 31339	Payment Method Cash	Transaction Number 18189954	Service Fees AED 170 Collected on 26/11/2022
Parking Slot No --	Service Name Registration Test	Attempt 1	Received by Sittu Paloth Sreesan Paloth

- This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.
- Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالترخيص الفني للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص.

This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.





## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>16 Nov 2022, 14:52:00</b>
Transaction Number	<b>58291913 (CC10009)</b>	Queue Number	<b>623128</b>



Chassis Number	<b>MR0DX6CD9G0200532</b>
Engine Number	
Vehicle Class	<b>Car</b>
Manufacturer	<b>Toyota</b>
Model	<b>Hilux</b>
Model Year	<b>2016</b>
Color	<b>White</b>
Mileage	<b>294926 Km</b>
Fuel Type	<b>Petrol</b>
No. Of Cylinders	<b>4</b>
Specification	<b>GCC Specification</b>

DEFECT	REMARKS	
<b>01 Engine Condition</b>		
<b>المحرك</b>		
01.A Visual Engine Condition	MINOR OIL LEAK	حالة المحرك النظري
01.B Mount	MOUNT RUBBER CUT	كرسي
<b>02 Transmission Condition</b>		
<b>الجير</b>		
02.A Visual Gear Box Condition	OIL LEAK	حالة الجير النظري
02.B Road Test	NOT CHECK	فحص علي الطريق
02.C DIFFERENTIAL	OIL LEAK	الدفرنشيل
<b>03 Body</b>		
<b>جسم المركبة</b>		
03.A Paint	BODY MINOR DENT DENT SCRATCHES , PORTION RUSTY	الصبغ
03.B Roof	PORTION RUSTY HOLE	السقف
03.C Rusty	UNDER FLOOR PARTS CHASSIS RUSTY	صدأ
03.D Bumper	REAR BUMPER FRAME RUSTY WEAK .MISALIGN	دعامية
03.E Bonnet	BONNE HAVE MINOR DENT	غطاء المحرك
<b>04 Steering Condition</b>		
<b>المقود</b>		
04.A Tie Rod End	BOOT CUT	مؤخرة الرودادات
04.B Steering Boot	BOOT CUT	ربلة المقود

DEFECT	REMARKS	
<b>05 Tires and Rims Condition</b>		<b>الاطارات</b>
05.A Rear Tyre	BOTH SIDE 2021,	الاطار الخلفي
05.B Front Tyre	BOTH SIDE 2021,	الاطار الامامي
<b>06 Chassis Condition</b>		<b>الشاسي</b>
06.A Chassis	CHASSIS FRAME REAR CROSS MEMBER RUSTY WEAK	الشاسيه
<b>07 Suspension System</b>		<b>ممتص الصدمات</b>
07.A Arms	LOWER ARM BUSHES CUT	ازرع
07.B Ball Joint	BOOT CUT	مفصل كروي
<b>08 Interior Condition</b>		<b>الحاله الداخليه</b>
08.A AC Condition	NOT WORKING	المكيف
08.B Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.