



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	12 May 2022, 15:28:03
Transaction Number	54747461 (CC10008)	Queue Number	312309



Chassis Number	MR0EW12G0C3016305
Engine Number	
Vehicle Class	Heavy
Manufacturer	Toyota
Model	Hilux
Model Year	2012
Color	White
Mileage	635270 Km
Fuel Type	Petrol
No. Of Cylinders	4
Specification	GCC Specification

DEFECT	REMARKS	
01 Lights		الاضاءة
01.A Warning Light	WARNING LIGHT ON IN DISPLAY	ضوء تحذير
01.B Head Light	LEFT SIDE LOW BEAM NOT WORKING	الاضاءة الرئيسية
02 Interior Condition		الحاله الداخليه
02.A Dash Board	DISPLAY SCREEN CRACKED&CONSOLE BOX DAMAGED	لوحة القيادة
02.B Steering Wheel and control buttons	HORN NOT WORKING	عجلة القيادة وازرار التحكم
02.C AC Condition	LOW COOLING	المكيف
03 Body		جسم المركبة
03.A Rusty	UNDER BODY PARTS, SUSPENSION , CHASSIS ,FLOOR GETTING RUSTY, PORTION HOLE	صدأ
03.B Other	FRONT FENDER FRAME ,BULK HEAD ,BUMPER FRAME ,RADIATOR SUPPORT REPAIRED	اخرى
03.C Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENT,SCRATCHES,PORTION RUSTY	الصبغ
03.D Sign of front accident		وجود مؤشر لحادث في المقدمة
04 Chassis Condition		النشاصي
04.A Chassis	FRONT LEFT SIDE CHASSIS END, BODY MOUNT, CROSS	النشاصيه

DEFECT	REMARKS	
MEMBER REPAIRED		
05 Transmission Condition		الجير
05.A Road Test	NOT CHECK	فحص علي الطريق
05.B Visual Gear Box Condition	REFITTED	حالة الجير النظرى
05.C Gear Box Mount	BUSH CUT	كرسي الجير
06 Suspension System		ممتص الصدمات
06.A Arms	LOWER ARM BUSHES CRACKED	ازرع
06.B Leaf Spring	BOTH SIDE BUSHES CRACKED & LEAF GETTING RUSTY	
07 Engine Condition		المحرك
07.A Visual Engine Condition	SHAKING , OIL LEAK, REFITTED	حالة المحرك النظرى
07.B Mount	BUSHES CUT	كرسي
08 Seats Condition		المقاعد
08.A Seat Condition	DRIVER SEAT CUT	حالة المقاعد

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

Test Certificate



Vehicle
Registration



X FAILED

Transfer Certificate :	66481042
Chassis No :	MROEW12GOC3016305
Vehicle Make :	TOYOTA
Vehicle Model :	HILUX
Vehicle Class :	Light Vehicle
Body Type :	PICK-UP
Fuel :	Benzene
Color :	White
Drive Direction :	--
Dimensions : (H x W x L) :	-- x -- x --
Current Odometer :	635271 Kms.
Origin :	Thailand
Model Year :	2012
Gear Type :	Manual
Engine Size :	2700 CC
Engine No :	7310707
Horse Power :	202
Axles No :	2
Cylinders :	4
No Of Doors :	4
No Of Seats :	5
G. V. W. :	Empty Weight : 1595 Kgs. 2431 Kgs.

Certificate Number :	5-TAS-2022-16765770
Inspection Date :	17-05-2022
Certificate Print Date :	17-05-2022
Services :	Registration Test
Vehicle Testing Partner :	Tasjeel
Vehicle Testing Center :	Tasjeel Al Aweer
Total Time Taken :	9 min 9 sec
Appointment Ref Number :	--
Start Time :	9:32
End Time :	9:41
Lane :	02
Token No. :	135
Attempt :	1
Prints No :	1

Parameter Readings

Service brake imbalance on front axle	Service brake imbalance on rear axle	Parking brake imbalance between LHS and RHS	Vehicle on Petrol CO Reading
8 %	11 %	22 %	0.39 %
Vehicle on Petrol HC Reading			
234 PPM VOL			

Inspection Findings

Defects	Issue	Severity
Engine	Oil leaking continuously	Major
Fire extinguisher (for commercial)	Missing	Major
Warning triangle	Missing	Major
Dip beams(Low Beams) headlight	Busted bulb	Major
Springs (leaf/coil) and shackle pin replace leaf spring bushes/rear	Worn-out bushes	Major
Safety Sign Stickers (for commercial) fix weight&capacity,driving comment&give way stickers	Missing	Major
Gear/Differential	Oil leaking continuously	Major
Frame (Body) repair body dents&re paint rusty portions	Others (Major)	Major
First Aid Box/Medical kit (commercial)	Missing	Major

Inspection Remarks:

Front bumper,bumper frame,bulk head,fender frames repaired,front left side crash box dent.Body minor dents&scratches.Chassis &under body components getting rusty.

Payment Details

Inspection Performed by	Payment Method	Transaction Number	Service Fees
--	Cash	16765770	AED 170 Collected on 17/05/2022
Parking Slot No	Service Name	Attempt	Received by
--	Registration Test	1	Sittu Paloth Sreesan Paloth

1 This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.

2 Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالتريخيص الفني للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية تريخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص.

This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any



purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.