

TEST CERTIFICATE

Site Number
Transaction Number

840-Emirates Auctions

94982056 (CC10008)

Transaction Date

26 May 2023, 16:28:08

Queue Number 727858

Chassis Number

MHFYX59G188005477

Engine Number

Vehicle Class

Car

Manufacturer

Toyota

Model

Fortuner

Model Year

2008

Color

Silver

Mileage

252618 Km

Fuel Type

Petrol

таот туро

Specification

No. Of Cylinders

GCC Specification

DEFECT REMARKS

01.A Road Test	NOT CHECK	فحص علي الطريق
01.B Gear Box Mount	CUT	كرسي الجير
01.C Visual Gear Box	JERKING	حالة الجير النظرى
Condition		

O2 Body

	02.A Bumper	دعامية
FITTED	02.B Fenders	مدكار
D,PORTION	02.C Doors	أبواب
	02.D Windshield	زجاج
ED	02.E Bonnet	غطاء المحرك
	02.F Trunk	صندوق
ED,MINOR N FADED	02.G Paint	الصبغ

O3 Tires and Rims Condition الاطارات

03.A Front Tyre	BOTH SIDE 2021	الاطار الامامي
03.B Rear Tyre	BOTH SIDE 2021	الاطار الخلفي

DEFECT	REMARKS	
04 Lights		الاضاءة
04.A Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
04.B Head Light	RIGHT SIDE PORTION DAMAGED	الاضاءة الرئيسية
05 Interior Condition		الحاله الداخليه
05.A AC Condition	ОК	المكيف
05.B Other	FRONT LEFT SIDE CUP CONSOLE BOX DAMAGED	اخري
06 Steering Condition		المقود
06.A Steering Boot	BOOT CUT	ربلة المقود
07 Suspension System		ممتص الصدمات
07.A Other	STABLIZER LINK BOOT CUT	اخري
08 Chassis Condition		الشاصي
08.A Chassis	CHASSIS FRAME GETTING RUSTY	الشاسيه
09 Engine Condition		المحرك
09.A Mount	CUT	کرسي
09.B Visual Engine Condition	OIL LEAK	حالة المحرك النظرى

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate,
 Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.