



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	17 May 2022, 12:39:19
Transaction Number	89012071 (CC10008)	Queue Number	312309



Chassis Number	JM7GH32F3B1208497
Engine Number	
Vehicle Class	Car
Manufacturer	Mazda
Model	6
Model Year	2011
Color	Grey
Mileage	199556 Km
Fuel Type	Petrol
No. Of Cylinders	4
Specification	GCC Specification

DEFECT	REMARKS	
01 Lights		الاضاءة
01.A Warning Light	WARNING LIGHT ON IN DISPLAY	ضوء تحذير
01.B Head Light	LENS FADED	الاضاءة الرئيسية
01.C Brake Light	NOT WORKING	نور الفرامل
02 Interior Condition		الحاله الداخليه
02.A Dash Board	PORTION DAMAGED	لوحة القيادة
02.B Roof Light	CONSOLE BOX MISSING & RIGHT SIDE NOT WORKING	أنارة السقف
02.C AC Condition	OK & GRILL ADJUSTMENT BUTTON MISSING	المكيف
02.D Other	CENTER CONSOLE BOX DAMAGED	اخرى
02.E Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
03 Suspension System		ممتص الصدمات
03.A Ball Joint	UPPER BOOT CUT	مفصل كروي
03.B Shock Absorber	FRONT LEFT SIDE & REAR RIGHT SIDE SHOCK ABSORBER LEAK	ممتص الصدمات
03.C Arms	REAR CONTROL ARM BUSH CRACKED	ازرع
04 Body		جسم المركبة

DEFECT	REMARKS	
04.A Sign of front accident		وجود مؤشر لحادث في المقدمة
04.B Sign of back accident		وجود مؤشر لحادث في الخلف
04.C Floor	REAR COMPARTMENT REPAIRED	الارضية
04.D Bumper	REAR DAMAGED	دعامية
04.E Paint	BODY TOTALY REPAINTED EXCEPT ROOF& PORTION REPAIRED,MINOR DENT SCRATCHES	الصبغ
04.F Fenders	REAR LEFT SIDE HAVE DENT	مدكار
05 Tires and Rims Condition		الاطارات
05.A Rear Tyre	BOTH SIDE 2018	الاطار الخلفي
05.B Front Tyre	BOTH SIDE 2018	الاطار الامامي
06 Engine Condition		المحرك
06.A Visual Engine Condition	REFITTED	حالة المحرك النظري
07 Transmission Condition		الجير
07.A Visual Gear Box Condition	REFITTED	حالة الجير النظري
07.B Road Test	NOT CHECK	فحص علي الطريق
08 Seats Condition		المقاعد
08.A Seat Condition	SEATS HAVE EXTRA COVER	حالة المقاعد
09 Chassis Condition		الشاسي
09.A Chassis	FRONT RIGHT SIDE CHASSIS MINOR BEND & REAR BOTH SIDE CHASSIS EXTENTION REPAIRED	الشاسيه

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

Test Certificate



Vehicle
Registration



X FAILED

Plate Details :	R 26421 Dubai Private
Chassis No :	JM7GH32F3B1208497
Vehicle Make :	MAZDA
Vehicle Model :	6
Vehicle Class :	Light Vehicle
Body Type :	SALOON
Fuel :	Benzene
Color :	Silver
Drive Direction :	--
Dimensions : (H x W x L) :	-- x -- x --
Current Odometer :	199557 Kms.
Origin :	Japan
Model Year :	2011
Gear Type :	Automatic
Engine Size :	2500 CC
Engine No :	LF11052922
Horse Power :	--
Axles No :	2
Cylinders :	4
No Of Doors :	4
No Of Seats :	5
G. V. W. :	Empty Weight : 1200 Kgs. 1650 Kgs.

Retest can be done only in Dubai

Certificate Number :	5-TAS-2022-16820323
Inspection Date :	23-05-2022
Certificate Print Date :	23-05-2022
Services :	Registration Test
Vehicle Testing Partner :	Tasjeel
Vehicle Testing Center :	Tasjeel Al Aweer
Total Time Taken :	11 min 56 sec
Appointment Ref Number :	--
Start Time :	9:35
End Time :	9:47
Lane :	03
Token No. :	116
Attempt :	1
Prints No. :	1

Parameter Readings

Service brake imbalance on front axle 25 %	Service brake imbalance on rear axle 15 %	Parking brake imbalance between LHS and RHS 13 %	Vehicle on Petrol CO Reading 0.4 %
Vehicle on Petrol HC Reading 78 PPM VOL			

Inspection Findings

Defects	Issue	Severity
Warning triangle	Missing	Major
Stop lamps fix stop lamp	Bulb busted	Major
Fender repair rear left side fender dent & rear bumper	Others (Major)	Major

Inspection Remarks: rear both side frame member /rear compartment/back panel repaired old

Payment Details

Inspection Performed by 59460	Payment Method Cash	Transaction Number 16820323	Service Fees AED 170 Collected on 23/05/2022
Parking Slot No --	Service Name Registration Test	Attempt 1	Received by Bajurdeen Abdul Gafoor

i This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.

i Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالترخيص الفني للمركبة. لا يعتمد بهذه الشهادة لأي عمليات أخرى بما في ذلك أعراض البيع أو الشراء خلاف عملية ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص.



This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.