





### Test Certificate

Site Number	: 840-EMIRATES AUCTION	Plate Code	: 0
Transaction Number	: 27732126	Plate Category	: PRIVATE
Transaction Date	: 10 JUL 2021 14:58:15	Plate Number	: 008302 EA
Queue Number	: 366509	Import Doc. Ref.	:
Chassis Number	: KNAE551C9J6008302	Manufacturer/Model	: KIA/STINGER
Engine Number	:	Model Year	: 2018
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: WHITE
Service / Indicator	: DSC AUCTION		

### Statement of Vehicle Condition

Defect	Result	Remarks
AUTOMATIC TEST:		
13 Brake System		الفرامل
13.04 - Brake Test	Passed	فحص الفرامل
14 Exhaust Gas Test		الغاز العادم والكربون
14.01 - Exhaust Gas Test	Passed	فحص الغاز العادم-الكربون
16 Side Slip Test		فحص ميزانية الاطارات
16.01 - Side Slip Test	Passed	فحص ميزانية الاطارات
VISUAL TEST:		
04 Tires Rims		الاطارات والعجلات
04.01 - Front Left And Right Hands Tires		الاطارات الامامية TIRES 2018 /2019 & INNER SIDE WALL CRACKS
05 Body		الهيكل
05.02 - Paint		الصنع BODY & BUMPER SCRATCH
05.04 - Fenders		المدكار FRONT RIGHT FENDER FRAME REPAIRED
05.05 - Bumpers		الدعامية FRONT BUMPER SUPPORT FRAME REPAIRED
05.08 - Chassis (Frame)		الشاصية FRONT BOTH SIDE FRAME MEMBER END DENT
05.09 - Front And Rear Windshields		الزجاج الامامي والخلفي FRONT WINDSHIELD REPLACED
05.12 - Side Safety Frame		الواقيات الجانبية BULKHEAD /RADIATOR SUPPORT REPAIRED
06 General Items		الاشياء العامة
06.14 - Transmission Condition	OK	حالة ناقل الحركة
06.16 - Engine Condition, Smoke	OIL LEAK	حالة المحرك - الدخان
07 Remarks		ملاحظات
07.04 - Others	43158 KM /BONNET REFITTED	ملاحظات اخرى
09 Auction		الفحص الكامل
09.02 - Need Wheel Alignment		بحاجة الى ميزانية العجلات
09.14 - Sign Of Front Accident		أثر حادث في مقدمة المركبة
09.16 - Sign Of Side Accident		أثر حادث في جوانب المركبة
09.24 - Digital Display Damaged/Warning Lights	STEERING /TMPS & TRACTION LIGHT ON	عطل في لوحة التحكم الالكتروني
09.25 - Body Repainted	BODY PORTIONS REPAIRED	أثر صنع في المركبة



### Test Certificate

Site Number	: 840-EMIRATES AUCTION	Plate Code	: 0
Transaction Number	: 27732126	Plate Category	: PRIVATE
Transaction Date	: 10 JUL 2021 14:58:15	Plate Number	: 008302 EA
Queue Number	: 366509	Import Doc. Ref.	:
Chassis Number	: KNAE551C9J6008302	Manufacturer/Model	: KIA/STINGER
Engine Number	:	Model Year	: 2018
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: WHITE
Service / Indicator	: DSC AUCTION		

#### Statement of Vehicle Condition

The Test Certificate Shows the test Result at the time of inspection only.  
Tasjeel is not responsible for any hidden defects.

شهادة الفحص تظهر نتيجة الفحص وقت الفحص فقط  
تسجيل غير مسئولة عن العيوب الخفية

# Test Certificate



Vehicle  
Registration



✓ PASS

Change possession :	65493348
Chassis No :	KNAE551C9J6008302
Vehicle Make :	KIA
Vehicle Model :	STINGER
Vehicle Class :	Light Vehicle
Body Type :	SALOON
Fuel :	Benzene
Color :	White
Drive Direction :	--
Dimensions : (H x W x L) :	-- x -- x --
Current Odometer :	43158 Kms.
Origin :	South Korea
Model Year :	2018
Gear Type :	--
Engine No :	G6DPHA92...
Engine Size :	3300 CC
Axles No :	2
Horse Power :	--
No Of Doors :	4
Cylinders :	6
No Of Seats :	5
G. V. W. :	1850 Kgs.
Empty Weight :	1350 Kgs.

Certificate Number :	5-TAS-2021-14606643
Inspection Date :	12-07-2021
Certificate Print Date :	12-07-2021
Services :	Registration Test
Vehicle Testing Partner :	Tasjeel
Vehicle Testing Center :	Tasjeel Emirates Auction
Total Time Taken :	16 min 5 sec
Appointment Ref Number :	--
Start Time :	16:40
End Time :	16:56
Lane :	01
Token No. :	13
Attempt :	1
Prints No. :	1

## Carbon footprint



Keep protecting Dubai environment

## Vehicle Consumption ( last 12 Months )

16798 KM	1729 L	2801 AED	4.2 ton
Distance per year	Fuel consumed per year	Fuel cost per year	Carbon footprint per year

## Parameter Readings

Service brake imbalance on front axle 4 %	Service brake imbalance on rear axle 1 %	Parking brake imbalance between LHS and RHS 3 %	Vehicle on Petrol CO Reading 0.02 %
Vehicle on Petrol HC Reading 25 PPM VOL			

## Inspection Remarks:

FRONT BOTH SIDE FRAME MEMBER END DENT /FRONT BUMPER SUPPORT FRAME REPAIRED FRONT RIGHT FENDER FRAME REPAIRED/REAR LEFT TIRE INNER SIDE WALL CRACK

## Payment Details

Inspection Performed by 59460	Payment Method VTP Credit Account	Transaction Number 14606643	Service Fees AED 170 Collected on 12/07/2021
Parking Slot No --	Service Name Registration Test	Attempt 1	Received by Raul Canceran Galang

- This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.
- Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص. المؤسسة غير مسئولة عن العيوب الغير مرئية و الفحص الفني يتم ظاهريا طبقا لقانون السير و المرور 21 لسنة 1995

This certificate is valid for one transaction only for 30 days from the date of inspection. Company not responsible for any hidden defects and inspection done-According to Traffic law No., 21 year 1995

