



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	07 Sep 2021, 10:21:35
Transaction Number	67666602 (CC10006)	Queue Number	312309



Chassis Number	JTHBL46F385084296
Engine Number	
Vehicle Class	Car
Manufacturer	Lexus
Model	LS 460
Model Year	2008
Color	Silver
Mileage	210171

DEFECT	REMARKS	
01 Body		جسم المركبة
01.A Fenders	PORTION REPAIRED & REPAIRED	مدكار
01.B Paint	BODY TOTALY PORTION REPAIRED , REPAINTED & DENTS ,SCRATCHES ON BODY	الصبغ
01.C Doors	PORTION REPAINTED & REPAIRED	أبواب
01.D Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.E Floor	UNDER FLOOR COVER PORTION DAMAGED & DENTS	الارضية
01.F Bonnet	REPAIRED & REPAINTED	غطاء المحرك
01.G Other	FRONT FENDER FRAME, BUMPER FRAME , RADITOR SUPPORT , BULK HEAD REPAIRED	اخرى
02 Chassis Condition		الشاسي
02.A Chassis	FRONT LEFT SIDE REPAIRED & RIGHT SIDE SLIGHTLY BEND	الشاسيه
03 Engine Condition		المحرك
03.A Other	OIL LEAK	اخرى
04 Seats Condition		المقاعد
04.A Other	OK	اخرى
05 Transmission Condition		الجير
05.A Gear Box	OIL LEAK	الجير
05.B Propeller Shaft	POPELLAR SHAFT RUBBER CRACKED	ناقل الحركة

DEFECT	REMARKS	
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2021	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2021	الاطار الخلفي
07 Wipers and Arms		المساحات
07.A Other	WORN OUT	اخرى
08 Lights		الاضاءة
08.A Head Light	OK	الاضاءة الرئيسية
08.B Other	OK	اخرى
09 Brake Condition		الفرامل
09.A Caliber Brake	GETTING RUSTY	جهاز الفرامل
10 Suspension System		ممتص الصدمات
10.A Arms	FRONT BOTH SIDE LOWER ARMS BUSHES CUT	ازرع
11 Steering Condition		المقود
11.A Steering Boot	BOOT CUT & LEAKING	ريشة المقود
12 Interior Condition		الاجزاء الداخلية
12.A Other	FRONT RIGHT SIDE SEAT BELT NOT WORKING	اخرى
12.B Mirror	OK	المرايا
12.C AC Condition	OK	المكيف

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

Test Certificate



Vehicle
Registration



X FAILED

Change possession :	65629639
Chassis No :	JTHBL46F385084296
Vehicle Make :	LEXUS
Vehicle Model :	LS 460
Vehicle Class :	Light Vehicle
Body Type :	SALOON
Fuel :	Benzene
Color :	Lead
Drive Direction :	--
Dimensions : (H x W x L) :	-- x -- x --
Current Odometer :	338239 Kms.
Origin :	Japan
Model Year :	2008
Gear Type :	--
Engine Size :	5000 CC
Engine No :	NIL
Horse Power :	385
Axles No :	2
Cylinders :	8
No Of Doors :	4
No Of Seats :	5
G. V. W. :	1984 Kgs.
	2400 Kgs.

Certificate Number :	5-TAS-2021-14968900
Inspection Date :	08-09-2021
Certificate Print Date :	08-09-2021
Services :	Registration Test
Vehicle Testing Partner :	Tasjeel
Vehicle Testing Center :	Tasjeel Al Aweer
Total Time Taken :	15 min 13 sec
Appointment Ref Number :	--
Start Time :	14:25
End Time :	14:40
Lane :	03
Token No. :	1714
Attempt :	1
Prints No :	1

Parameter Readings

Service brake imbalance on front axle	Service brake imbalance on rear axle	Parking brake imbalance between LHS and RHS	Vehicle on Petrol CO Reading
13 %	12 %	15 %	0 %
Vehicle on Petrol HC Reading			
0 PPM VOL			

Inspection Findings

Defects	Issue	Severity
Front Seat belts front right seat belt defective	Defective	Major
Engine repair engine oil leak	Oil leaking continuously	Major
Steering Boots and Ball Joints change steering rubber boot	Worn-out or missing boot(s) (Major)	Major

Discrepancies	Old Value	New Value	Verified
Engine Size Discrepancy in Engine Size	5000	4600	
Paint Changed Color	Lead	Gray	

Inspection Remarks:

FRONT LEFT SIDE CHASSIS REPAIRED& RIGHT SIDE CHASSIS END REPAIRED. C.C.M OK W/O # 20151122-016 BULK HEAD CROSS MEMBER BUMPER FRAME,FENDER,BONNET REPAIRED

Payment Details

Inspection Performed by	Payment Method	Transaction Number	Service Fees
62424	Cash	14968900	AED 170 Collected on 08/09/2021
Parking Slot No	Service Name	Attempt	Received by
--	Registration Test	1	Abdul Rasheed Hussain

1 This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.

2 Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالترخيص الفني للمركبة. لا يعتمد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص

This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.

