



## TEST CERTIFICATE

Site Number **840-Emirates Auctions** Transaction Date **20 May 2022, 12:03:47**  
 Transaction Number **13813014 (CC10008)** Queue Number **312309**



Chassis Number **JN8FY15Y7AX580433**  
 Engine Number  
 Vehicle Class **Car**  
 Manufacturer **Nissan**  
 Model **Patrol**  
 Model Year **2010**  
 Color **Blue**  
 Mileage **220188 Km**  
 Fuel Type **Petrol**  
 No. Of Cylinders **6**  
 Specification **GCC Specification**

DEFECT	REMARKS	
<b>01 Interior Condition</b>		<b>الحاله الداخليه</b>
01.A AC Condition	REAR AC NOT WORKING	المكيف
01.B Dash Board	DASHBAORD DAMAGED	لوحة القيادة
01.C Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
<b>02 Lights</b>		<b>الاضاءة</b>
02.A Warning Light	WARNING LIGHT ON IN DISPLAY	ضوء تحذير
02.B Fog light	NOT WORKING	كشاف الضباب
<b>03 Body</b>		<b>جسم المركبة</b>
03.A Pillars	RIGHT SIDE A/B/PILLAR & LEFT SIDE C/PILLAR ,QUATER PANEL ,ROCKER PANEL REPAIRED	القوائم
03.B Paint	BODY TOTALY REPAINTED & PORTION REPAIRED,MINOR DENT,SCRATCHES	الصبغ
03.C Fenders	FRONT FENDER REFITTED	مدكار
03.D Bonnet	REFITTED	غطاء المحرك
03.E Door Handle &Lock	REAR RIGHT SIDE DOOR NOT OPENING FOR RECHECK	مقابض الأبواب والأقفال
<b>04 Transmission Condition</b>		<b>الجير</b>

DEFECT	REMARKS	
04.A Road Test	NOT CHECK	فحص علي الطريق
04.B Visual Gear Box Condition	OPEN,REFITTED,MINOR OIL LEAK	حالة الجير النظرى
04.C DIFFERENTIAL	FRONT DIFFERENTIAL SIGN OF MINOR OIL LEAK	الدفرنشيل
<b>05 Engine Condition</b>		<b>المحرك</b>
05.A Visual Engine Condition	OPEN,REFITTED	حالة المحرك النظرى
05.B Mount	MOUNT RUBBER CUT	كرسي
<b>06 Chassis Condition</b>		<b>الشاسي</b>
06.A Chassis	REAR BOTH SIDE CHASSIS ARCH BULGDE & LEFT SIDE MINOR DENT	الشاسيه
<b>07 Suspension System</b>		<b>ممتص الصدمات</b>
07.A Arms	REAR CONTROL ARM MOUNT REWELDED	ازرع
<b>08 Steering Condition</b>		<b>المقود</b>
08.A Steering Oil	OIL LEAK	زيت المقود
<b>09 Tires and Rims Condition</b>		<b>الاطارات</b>
09.A Front Tyre	BOTH SIDE 2017 CRACKED , EXPIRED	الاطار الامامي
09.B Rear Tyre	BOTH SIDE 2017 CRACKED , EXPIRED	الاطار الخلفي
09.C Spare Tire & Tools	MISSING	الاطار الاحتياطي و العدة
<b>10 Wipers and Arms</b>		<b>المساحات</b>
10.A Wiper Arm & Blade	REAR WIPPER MISSING	ازرع المساحات والشفرات
<b>11 Seats Condition</b>		<b>المقاعد</b>
11.A Seat Condition	FRONT SEAT SIDE COVER LOOSE EDGE BROKEN & REAR SEAT MISSING	حالة المقاعد

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

# Test Certificate



Vehicle  
Registration



X FAILED

Plate Details :	--
Chassis No :	JN8FY15Y7AX580433
Vehicle Make :	NISSAN
Vehicle Model :	PATROL
Vehicle Class :	Light Vehicle
Body Type :	STATION
Fuel :	Benzene
Color :	Blue, Gray
Drive Direction :	--
Dimensions : (H x W x L) :	-- x -- x --
Current Odometer :	220189 Kms.
Origin : Japan	Model Year : 2010
Gear Type : Manual	Engine Size : 3500 CC
Engine No : tb48062320	Horse Power : --
Axles No : 2	Cylinders : 6
No Of Doors : 4	No Of Seats : 5
G. V. W. : 2000 Kgs.	Empty Weight : 1600 Kgs.

Certificate Number :	5-TAS-2022-16814162
Inspection Date :	22-05-2022
Certificate Print Date :	22-05-2022
Services :	Registration Test
Vehicle Testing Partner :	Tasjeel
Vehicle Testing Center :	Tasjeel Al Aweer
Total Time Taken :	11 min 58 sec
Appointment Ref Number :	--
Start Time : 14:13	End Time : 14:25
Lane : 03	Token No. : 200
Attempt : 1	Prints No : 1

## Parameter Readings

Service brake imbalance on front axle 5 %	Service brake imbalance on rear axle 4 %	Parking brake imbalance between LHS and RHS 17 %	Vehicle on Petrol CO Reading 0 %
Vehicle on Petrol HC Reading 0 PPM VOL			

## Inspection Findings

Defects	Issue	Severity
Tire change all tires crack & old 1317	Others (Major)	Major
Doors and Locks remove all door pillar cover & biding for recheck	Others (Major)	Major

Inspection Remarks: rear both side chassis bulged

## Payment Details

Inspection Performed by 59460	Payment Method VTP Credit Account	Transaction Number 16814162	Service Fees AED 170 Collected on 22/05/2022
Parking Slot No --	Service Name Registration Test	Attempt 1	Received by Bajurdeen Abdul Gafoor

1 This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.

2 Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالتسجيل الفنى للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص



This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.