







Test Certificate

Site Number : 840-EMIRATES AUCTION Plate Code : 0

Transaction Number : 21086647 Plate Category : PRIVATE

Transaction Date : 13 SEP 2020 12:17:23 Plate Number : 029681 EA

Queue Number : 220800

Chassis Number : JTMHU09JXA4029681 Manufacturer/Model : TOYOTA/LAND CRUISER

Engine Number :

Model Year : 2010

Import Doc. Ref.

Vehicle Class : LIGHT VEHICLE Vehicle Color : WHITE

Service / Indicator : DSC AUCTION

Statement of Vehicle Condition

			Statement of Vehicle Condition
Defect	Result	Remarks	
AUTOMATIC TEST:			
13 Brake System			فر امل
13.04 - Brake Test	Passed		حص الفر امل
14 Exhaust Gas Test			لخاز العادم والكربون
14.01 - Exhaust Gas Test	Passed		حص الغاز العادم-الكربون
VISUAL TEST:			
01 Lights			لانوار
01.02 - Tail Lights		RIGHT CRACK	لانوار الخلفية
01.04 - Head Lights		BOTH SIDE FADED	لانوار الامامية
02 Steering And Suspension System			عجلة القيادة ونظام التوصيلات
02.10 - Ties Rods, Bushes, Center Link, Left And Right		TIE ROD END BOOT CRACK	بلات ذراع التوجيه
02.13 - Stub Axle Assemblies, Boots		FRONT AXLE OIL LEAK	محور
03 Brake System			ظام الفرامل
03.01 - Brake Efficiency Front Wheels Left And Right Hands		BRAKE PADS WORN OUT	وة فرامل المحور الامامي
04 Tires Rims			لاطارات والعجلات
04.01 - Front Left And Right Hands Tires		TIRES 2017 & 2018 & FRONT RIGHT CRACK	لاطارات الامامية
04.07 - Rims		WHEEL NUT INCOMPLETE	رنجات
05 Body			هيكل
05.08 - Chassis (Frame)		CHASSIS /SUSPENSION & UNDER BODY COMPONENTS GETTING RUSTY	شاصية
05.09 - Front And Rear Windshields		FRONT SPOT DOT	نرجاج الامامي والخلفي
06 General Items			لاشياء العامة
06.13 - Exhaust System		EXHAUST MODIFIED WITH HEADERS	ظام العادم
06.14 - Transmission Condition		OIL LEAK	بالة ناقل الحركة
06.16 - Engine Condition, Smoke		ENGINE OIL LEAK & RADIATOR UPPER PORTION CRACK	بالة المحرك - الدخان
07 Remarks			لاحظات
07.04 - Others		89256 KM	للحظات اخرى
09 Auction			لفحص الكامل





Test Certificate

840-EMIRATES AUCTION Plate Code Site Number

Transaction Number 21086647 Plate Category **PRIVATE** Transaction Date 13 SEP 2020 12:17:23 Plate Number 029681 EA

Queue Number 220800

Manufacturer/Model Chassis Number JTMHU09JXA4029681 : TOYOTA/LAND CRUISER

Engine Number

Model Year 2010

Import Doc. Ref.

Vehicle Class Vehicle Color WHITE LIGHT VEHICLE

Service / Indicator DSC AUCTION

Statement of Vehicle Condition

ثر صبغ في المركبة 09.25 - Body Repainted **BODY PORTION REPAINTED**

The Test Certificate Shows the test Result at the time of inspection only.

Tasjeel is not responsible for any hidden defects.

شهادة الفحص تظهر نتيجة الفحص وقت الفحص فقط


تسجيل غير مسئولة عن العيوب الخفية

Test Certificate









Possession Certificate: 64582530

Chassis No: JTMHU09JXA4029681

Vehicle Make: TOYOTA

Vehicle Model: LAND CRUISER

Vehicle Class: Light Vehicle

Body Type: STATION

Fuel: Benzene

Color: White

Drive Direction: -Dimensions: (H x W x L) --x--x--

Current Odometer: 89257 Kms.

Origin: Japan
Gear Type: --

Engine No : GRA140114

Axles No : 2

G. V. W. : 3121 Kas.

No Of Doors: 4

Model Year :
Engine Size :

Engine Size: 4000 CC

Horse Power: 413

Cylinders: 6

No Of Seats: 7

2010

Empty Weight: 2638 Kgs.

Certificate Number: 5-TAS-2020-12551630

 Inspection Date :
 15-09-2020

 Certificate Print Date :
 15-09-2020

 Services :
 Registration Test

Vehicle Testing Partner: Tasjeel

Vehicle Testing Center: Tasjeel Emirates Auction

Total Time Taken: 8 min 21 sec

Appointment Ref Number : --

 Start Time:
 9:45

 Lane:
 01

 Attempt:
 1

End Time: 9:54
Token No.: 4
Prints No: 1

Parameter Readings

Service brake imbalance on front axle

10 %

Service brake imbalance on rear axle 8 %

Parking brake imbalance between LHS and RHS 8 % Vehicle on Petrol CO Reading

0.1%

Vehicle on Petrol HC Reading 125 PPM VOL

Inspection Findings

Defects	Issue	Severity
Tire FRONT RIGHT SIDE CRACK	Cracked	Major
Dip beams (Low Beams) headlight CLEAN BOTH SIDE LENS FADED	Unsecure	Major
Engine REPAIR RADIATOR UPPER COVER CRACK	Others (Major)	Major

Inspection Remarks: CHASSIS / SUSPENSION & UNDER BODY COMPONENTS GETTING RUSTY / EXHAUST MODIFIED

Payment Details

 Inspection Performed by
 Payment Method
 Transaction Number
 Service Fees

 59460
 VTP Credit Account
 12551630
 AED 170 Collected on 15/09/2020

 Parking Slot No
 Service Name
 Attempt
 Received by

 - Registration Test
 1
 Raul Canceran Galang

• This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.

🖲 Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص. المؤسسة غير مسئولة عن العيوب الغير مرئية و الفحص الفني يتم ظاهريا طبقا

TASIEEL

لقانون السير و المرور أ2 لسنة 1995 This certificate is valid for one transaction only for 30 days from the date of inspection. Company not responsible for any hidden defects and inspection done-According to Traffic law No., 21 year 1995