



TEST CERTIFICATE

| | | | |
|--------------------|------------------------------|------------------|------------------------------|
| Site Number | 840-Emirates Auctions | Transaction Date | 04 Aug 2022, 14:37:29 |
| Transaction Number | 93022734 (CC10006) | Queue Number | 312309 |



| | |
|------------------|--------------------------|
| Chassis Number | 1N4AL3AP2GN328421 |
| Engine Number | |
| Vehicle Class | Car |
| Manufacturer | Nissan |
| Model | Altima |
| Model Year | 2016 |
| Color | Silver |
| Mileage | 143477 Miles |
| Fuel Type | Petrol |
| No. Of Cylinders | 4 |
| Specification | USA Imported |

| DEFECT | REMARKS | |
|------------------------------|--|------------------------|
| 01 Lights | | الاضاءة |
| 01.A Warning Light | WARNING LIGHT ON DISPLAY | ضوء تحذير |
| 01.B Fog light | LEFT SIDE NOT WORKING | كشاف الضباب |
| 02 Interior Condition | | الحالة الداخلية |
| 02.A AC Condition | OK | المكيف |
| 02.B Mirror | VIEW MIRROR MINOR FADED | المرآيا |
| 02.C Air Bag | DAMAGED | وسائد هوائية |
| 03 Body | | جسم المركبة |
| 03.A Fenders | REPAINTED,PORTION REPAIRED | مدكار |
| 03.B Paint | BODY PORTION REPAIRED , REPAINTED & MINOR DENT ,SCRATCHES | الصبغ |
| 03.C Doors | REAR RIGHT SIDE PORTION REPAINTED | أبواب |
| 03.D Bonnet | REPAINTED,REFITTED | غطاء المحرك |
| 03.E Trunk | PORTION REPAIRED,REPAINTED | صندوق |
| 03.F Bumper | MISALIGN,PORTION CRACKED | دعامية |
| 03.G Other | FRONT BMPER FRAME BULK HEAD FENDER FRAME RADIATOR SUPPORT REPAIRED | اخرى |

| DEFECT | REMARKS | |
|------------------------------------|---|---------------------|
| 04 Engine Condition | | المحرك |
| 04.A Visual Engine Condition | MINOR OIL LEAK & REFITTED | حالة المحرك النظري |
| 05 Transmission Condition | | الجير |
| 05.A Visual Gear Box Condition | MINOR OIL LEAK & REFITTED,JERKING | حالة الجير النظري |
| 05.B Road Test | NOT CHECK | فحص علي الطريق |
| 06 Suspension System | | ممتص الصدمات |
| 06.A Ball Joint | BOOT CRACKED | مفصل كروي |
| 06.B Other | STABILIZER LINK BOOT CRACKED | اخرى |
| 06.C Arms | LOWER ARM BUSHES CRACKED | ازرع |
| 07 Steering Condition | | المقود |
| 07.A Tie Rod End | BOOT CUT | مؤخرة الرودات |
| 08 Tires and Rims Condition | | الاطارات |
| 08.A Front Tyre | BOTH SIDE 2021 CRACKED & WORN OUT | الاطار الامامي |
| 08.B Rear Tyre | BOTH SIDE 2021 | الاطار الخلفي |
| 09 Chassis Condition | | الشاسي |
| 09.A Chassis | REAR BOTH SIDE CHASSIS EXTENSION REPAIRED | الشاسيه |

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

Test Certificate



Vehicle
Registration



✗ FAILED

| | |
|--------------------------|----------------------------|
| Plate Details : | 12 35145 Abu Dhabi Private |
| Chassis No : | 1N4L3AP2GN328421 |
| Vehicle Make : | NISSAN |
| Vehicle Model : | ALTIMA |
| Vehicle Class : | Light Vehicle |
| Body Type : | SALOON |
| Fuel : | Benzene |
| Color : | Silver |
| Drive Direction : | -- |
| Dimensions : (H x W x L) | -- x -- x -- |
| Current Odometer : | 230903 Kms. |
| Origin : United States | Model Year : 2016 |
| Gear Type : Automatic | Engine Size : 3500 CC |
| Engine No : NONE | Horse 182 |
| Axles No : 2 | Power : |
| No Of 4 | Cylinders : 4 |
| Doors : | No Of Seats : 5 |
| G. V. W. : 2268 Kgs. | Empty 1450 Kgs. |
| | Weight : |

| | | | |
|---------------------------|---------------------|--------------|-------|
| Certificate Number : | 5-TAS-2022-17379341 | | |
| Inspection Date : | 10-08-2022 | | |
| Certificate Print Date : | 10-08-2022 | | |
| Services : | Registration Test | | |
| Vehicle Testing Partner : | Tasjeel | | |
| Vehicle Testing Center : | Tasjeel Al Aweer | | |
| Total Time Taken : | 20 min 47 sec | | |
| Appointment Ref Number : | -- | | |
| Start Time : | 9:51 | End Time : | 10:12 |
| Lane : | 01 | Token No. : | 110 |
| Attempt : | 1 | Prints No. : | 1 |

Parameter Readings

| | | | |
|---------------------------------------|--------------------------------------|---|------------------------------|
| Service brake imbalance on front axle | Service brake imbalance on rear axle | Parking brake imbalance between LHS and RHS | Vehicle on Petrol CO Reading |
| 10 % | 0 % | 6 % | 0 % |
| Vehicle on Petrol HC Reading | | | |
| 2 PPM VOL | | | |

Inspection Findings

| Defects | Issue | Severity |
|--|--------------------------------------|----------|
| Warning triangle NOT FOUND | Missing | Major |
| Bumper REPAIR REAR BUMPER MIS ALIGN&FADED | Unsecure | Major |
| Front Registration plate FIX PROPERLY FRONT PLATE NUMBER | Improper position | Major |
| Engine CHANGE TOP ENGINE MOUNTING CRACK | Worn out rubber mountings | Major |
| Front Seat belts CHANGE FRONT LEFT SIDE SEAT BELT | Defective | Major |
| Wiper arms, Blades, Washer CHANGE WIPER BALDE WORN | Damaged or bend wiper arm(s) (Major) | Major |
| Seats REPAIR DRIVER SEAT WORN&CUT | Others (Major) | Major |

Inspection Remarks:

MINOR BODY DENTS/MINOR LOWER ARN BUSH&FRT INN LEFT SIDE AXLE BOOT & LEFT SIDE TAIL LAMP LENS /CRACK/ FRONT BUMPER/BULKHEAD/&REAR BOTH SIDE CHASSIS EXTENSION END/ REAR BACK PANEL&QUARTER PANEL REPAIRED

Payment Details

| | | | |
|-------------------------|--------------------|--------------------|---------------------------------|
| Inspection Performed by | Payment Method | Transaction Number | Service Fees |
| -- | VTP Credit Account | 17379341 | AED 170 Collected on 10/08/2022 |
| Parking Slot No | Service Name | Attempt | Received by |
| -- | Registration Test | 1 | Bajurdeen Abdul Gafoor |

1 This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.

1 Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالترخيص الفني للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أعراض البيع أو الشراء خلاف عملية ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص.



This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.