



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	14 Aug 2022, 17:00:04
Transaction Number	51733406 (CC10008)	Queue Number	312309



Chassis Number	5TDBY64A8CS060701
Engine Number	
Vehicle Class	Car
Manufacturer	Toyota
Model	Sequoia
Model Year	2012
Color	Grey
Mileage	90221 Km
Fuel Type	Petrol
No. Of Cylinders	8
Specification	GCC Specification

DEFECT	REMARKS	
01 Body		جسم المركبة
01.A Fenders	RIGHT SIDE BOTH PORTION REPAIRED , REPAINTED & REFITTED	مدكار
01.B Doors	RIGHT SIDE BOTH PORTION REPAIRED REPAINTED	أبواب
01.C Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENT,SCRATCHES	الصبغ
01.D Trunk	PORTION REPAIRED,REPAINTED	صندوق
01.E Bonnet	SHOCK WEAK	غطاء المحرك
01.F Sign of front accident		وجود مؤشر لحادث في المقدمة
01.G Rusty	CHASSIS UNDER BODY ,SUNPENSION PARTS GETTING RUSTY.	صدأ
01.H Bumper	FRONT RADIATOR SUPPORT BULKHEAD ASSEMBLY DENT .BUMPER GRILL CRACKED.	دعامية
02 Transmission Condition		الجير
02.A Road Test	NOT CHECK	فحص علي الطريق
02.B Visual Gear Box Condition	SIGN OF OIL LEAK	حالة الجير النظري
03 Tires and Rims Condition		الاطارات

DEFECT	REMARKS	
03.A Front Tyre	BOTH SIDE 2020/2019,WORN OUT	الاطار الامامي
03.B Spare Tire &Tools	WORN OUT PUNCTURE.	الاطار الاحتياطي و العدة
03.C Other	REAR LEFT ONE WHEEL NUT MISSING.	اخري
03.D Rear Tyre	BOTH SIDE 2019 RIGHT SIDE WORN OUT	الاطار الخلفي
04 Battery Condition		حالة البطارية
04.A Battery bracket	MISSING	حامل البطارية
05 Interior Condition		الحاله الداخليه
05.A AC Condition	OK	المكيف
06 Engine Condition		المحرك
06.A Smoke	WHITE SMOKE	دخان
06.B Visual Engine Condition	SIGN OF OIL LEAK	حالة المحرك النظري
07 Lights		الاضاءة
07.A Tail Light	LEFT SIDE CRACKED	الانارة
07.B Fog light	FADED	كشاف الضباب
08 Chassis Condition		الشاسي
08.A Chassis	OK	الشاسيه
09 Suspension System		ممتص الصدمات
09.A Shock Absorber	SHOCK ABSORBER LEAKING .	ممتص الصدمات

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.