



## TEST CERTIFICATE

|                    |                       |                  |                       |
|--------------------|-----------------------|------------------|-----------------------|
| Site Number        | 840-Emirates Auctions | Transaction Date | 20 Sep 2021, 16:07:39 |
| Transaction Number | 82216855 (CC10006)    | Queue Number     | 312309                |



|                |                   |
|----------------|-------------------|
| Chassis Number | 5TBBV54127S478060 |
| Engine Number  |                   |
| Vehicle Class  | Heavy             |
| Manufacturer   | Toyota            |
| Model          | Tundra            |
| Model Year     | 2007              |
| Color          | White             |
| Mileage        | 383032            |

| DEFECT                      | REMARKS   |             |
|-----------------------------|---|-------------|
| <b>01 Chassis Condition</b> |   | الشاشي      |
| 01.A Chassis                | CHASSIS FRAME COMPLETELY RUSTY  | الشاشيه     |
| <b>02 Body</b>              |   | جسم المركبة |
| 02.A Fenders                | FRONT RIGHT SIDE REPAIRED & REPAINTED                                 | مدكار       |
| 02.B Doors                  | FRONT RIGHT SIDE REPAINTED  | أبواب       |
| 02.C Paint                  | PORTION REPAIRED, REPAINTED & DENTS, SCRATCHES ON BODY                | الصبغ       |
| 02.D Rusty                  | UNDER BODY PARTS, FLOORING , SUSPENTION , CHASSIS FRAME GETTING RUSTY | صدأ         |
| 02.E Bumper                 | REPAINTED   | دعامية      |
| 02.F Bonnet                 | PORTION REPAINTED   | غطاء المحرك |
| 02.G Roof                   | INNER COVER REAR DAMAGED  | السقف       |
| <b>03 Engine Condition</b>  |   | المحرك      |
| 03.A Other                  | OK  | اخرى        |
| <b>04 Exhaust System</b>    |   | نظام العادم |
| 04.A Modification           | MODIFIED & NOISY  | تعديلات     |
| 04.B Other                  | WELDED & REPAIRED   | اخرى        |
| <b>05 Wipers and Arms</b>   |   | المساحات    |
| 05.A Other                  | WORN OUT  | اخرى        |

| DEFECT                             | REMARKS   |                         |
|------------------------------------|---|-------------------------|
| <b>06 Tires and Rims Condition</b> |   | <b>الاطارات</b>         |
| 06.A Front Tyre                    | BOTH SIDE 2017 CRACKED                                      | الاطار الامامي          |
| 06.B Rear Tyre                     | BOTH SIDE 2017 CRACKED                                      | الاطار الخلفي           |
| <b>07 Lights</b>                   |   | <b>الاضاءة</b>          |
| 07.A Head Light                    | OK  | الاضاءة الرئيسية        |
| 07.B Other                         | OK  | اخرى                    |
| <b>08 Interior Condition</b>       |   | <b>الاجزاء الداخلية</b> |
| 08.A Mirror                        | OK  | المرايا                 |
| 08.B Other                         | FRONT RIGHT SIDE GLASS WINDOW NOT WORKING ( CONTROL SWITCH) | اخرى                    |
| 08.C AC Condition                  | A/C NOT COOLING   | المكيف                  |

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

# Test Certificate



Vehicle  
Registration



X FAILED

|                            |                                       |
|----------------------------|---------------------------------------|
| Plate Details :            | --                                    |
| Chassis No :               | 5TBBV54127S478060                     |
| Vehicle Make :             | TOYOTA                                |
| Vehicle Model :            | TUNDRA                                |
| Vehicle Class :            | Light Vehicle                         |
| Body Type :                | PICK-UP                               |
| Fuel :                     | Benzene                               |
| Color :                    | White, Black                          |
| Drive Direction :          | --                                    |
| Dimensions : (H x W x L) : | -- x -- x --                          |
| Current Odometer :         | 383032 Kms.                           |
| Origin :                   | United States                         |
| Model Year :               | 2007                                  |
| Gear Type :                | --                                    |
| Engine Size :              | 3500 CC                               |
| Engine No :                | NIL                                   |
| Horse Power :              | 381                                   |
| Axles No :                 | 2                                     |
| Cylinders :                | 8                                     |
| No Of Doors :              | 4                                     |
| No Of Seats :              | 5                                     |
| G. V. W. :                 | Empty Weight : 2440 Kgs.<br>3175 Kgs. |

|                           |                     |
|---------------------------|---------------------|
| Certificate Number :      | 5-TAS-2021-15078855 |
| Inspection Date :         | 23-09-2021          |
| Certificate Print Date :  | 23-09-2021          |
| Services :                | Registration Test   |
| Vehicle Testing Partner : | Tasjeel             |
| Vehicle Testing Center :  | Tasjeel Al Aweer    |
| Total Time Taken :        | 15 min 52 sec       |
| Appointment Ref Number :  | --                  |
| Start Time :              | 10:33               |
| End Time :                | 10:49               |
| Lane :                    | 01                  |
| Token No. :               | 117                 |
| Attempt :                 | 1                   |
| Prints No :               | 1                   |

## Parameter Readings

|                                       |                                      |   |                              |
|---------------------------------------|--------------------------------------|---|------------------------------|
| Service brake imbalance on front axle | Service brake imbalance on rear axle | Parking brake imbalance between LHS and RHS | Vehicle on Petrol CO Reading |
| 18 %                                  | 12 %                                 | 14 %  | 0.33 %                       |
| Vehicle on Petrol HC Reading          |                                      |   |                              |
| 154 PPM VOL                           |                                      |   |                              |

## Inspection Findings

| Defects  | Issue           | Severity |
|--|-----------------|----------|
| Spare Tire<br>FIX SPARE TIRE   | Missing (Major) | Major    |
| Bumper<br>FIX FRONT BUMPER SUPPORT / MISSING   | Others (Major)  | Major    |
| Direction-indicator lamps<br>FIX FRONT BOTH SIDE ORIGINAL INDICATOR LIGHT / MODIFIED | Defective       | Major    |

| Discrepancies                          | Old Value | New Value | Verified |
|--|-----------|-----------|----------|
| Engine Size Discrepancy in Engine Size | 3500      | 5700      |          |

Inspection Remarks: BULK HEAD REPAIRED , CHASSIS & UNDER BODY GETTING RUSTY / BODY MINOR SCRATCH & DENT /

## Payment Details

|   |                                   |                                |   |
|---|-----------------------------------|--------------------------------|---|
| Inspection Performed by<br>8008085<br>74792 | Payment Method<br>Cash            | Transaction Number<br>15078855 | Service Fees<br>AED 170 Collected on 23/09/2021 |
| Parking Slot No<br>--                       | Service Name<br>Registration Test | Attempt<br>1                   | Received by<br>Sittu Paloth Sreesan Paloth      |

- This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.
- Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالترخيص الفني للمركبة. لا يعتمد بهذه الشهادة لتي عمليات أخرى بما في ذلك أعراض البيع أو الشراء خلاف عملية ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص.

This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.

