





### Test Certificate

Site Number	: 840-EMIRATES AUCTION	Plate Code	: 0
Transaction Number	: 26106148	Plate Category	: PRIVATE
Transaction Date	: 06 MAY 2021 10:04:36	Plate Number	: 761283 EA
Queue Number	: 330392	Import Doc. Ref.	:
Chassis Number	: 4T1BE46K28U761283	Manufacturer/Model	: TOYOTA/CAMRY
Engine Number	:	Model Year	: 2008
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: WHITE
Service / Indicator	: DSC AUCTION		

### Statement of Vehicle Condition

Defect	Result	Remarks
AUTOMATIC TEST:		
13 Brake System		الفرامل
13.04 - Brake Test	Passed	فحص الفرامل
14 Exhaust Gas Test		الغاز العادم والكربون
14.01 - Exhaust Gas Test	Passed	فحص الغاز العادم-الكربون
VISUAL TEST:		
02 Steering And Suspension System		عجلة القيادة ونظام التوصيلات
02.15 - Suspension Crack Or Bend, Bushes		التوصيلات
02.16 - Engine Mounting		كراسي المحرك
03 Brake System		نظام الفرامل
03.01 - Brake Efficiency Front Wheels Left And Right Hands		قوة فرامل المحور الامامي
04 Tires Rims		الاطارات والعجلات
04.01 - Front Left And Right Hands Tires		الاطارات الامامية
04.07 - Rims		الرنجات
05 Body		الهيكل
05.02 - Paint		الصيغ
05.07 - Floor		الارضية
05.08 - Chassis (Frame)		الشاصية
06 General Items		الاشياء العامة
06.01 - Wiper Blades		ماسحات الزجاج الامامي
06.04 - Horn		الزامور
06.12 - Seats Condition And Seats Fixing		المقاعد وحالتها وتثبيتها
06.14 - Transmission Condition		حالة ناقل الحركة
06.16 - Engine Condition, Smoke		حالة المحرك - الدخان
06.21 - Battery Condition		حالة البطارية
07 Remarks		ملاحظات
07.04 - Others		ملاحظات اخرى
09 Auction		الفحص الكامل



### Test Certificate

Site Number	: 840-EMIRATES AUCTION	Plate Code	: 0
Transaction Number	: 26106148	Plate Category	: PRIVATE
Transaction Date	: 06 MAY 2021 10:04:36	Plate Number	: 761283 EA
Queue Number	: 330392	Import Doc. Ref.	:
Chassis Number	: 4T1BE46K28U761283	Manufacturer/Model	: TOYOTA/CAMRY
Engine Number	:	Model Year	: 2008
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: WHITE
Service / Indicator	: DSC AUCTION		

### Statement of Vehicle Condition

09.02 - Need Wheel Alignment		بحاجة الى ميزانية العجلات
09.14 - Sign Of Front Accident	FENDER FRAMES/ BULKHEAD REPAIRED/ HOOD REPAIRED/ FENDERS REFITTED	أثر حادث في مقدمة المركبة
09.16 - Sign Of Side Accident		أثر حادث في جوانب المركبة
09.18 - A/C Not Cooling		عطل في المكيف
09.24 - Digital Display Damaged/Warning Lights	TPMS/ MAINTENANCE REQD LIGHTS ON	عطل في لوحة التحكم الالكتروني
09.25 - Body Repainted	BODY PORTIONS REPAINTED	أثر صيغ في المركبة
<p>The Test Certificate Shows the test Result at the time of inspection only. Tasjeel is not responsible for any hidden defects.</p> <p style="text-align: right;">شهادة الفحص تظهر نتيجة الفحص وقت الفحص فقط تسجيل غير مسئول عن العيوب الخفية</p>		

# Test Certificate



Vehicle  
Registration



✓ PASS

Plate Details :	--
Chassis No :	4T1BE46K28U761283
Vehicle Make :	TOYOTA
Vehicle Model :	CAMRY
Vehicle Class :	Light Vehicle
Body Type :	SALOON
Fuel :	Benzene
Color :	White
Drive Direction :	--
Dimensions : (H x W x L) :	-- x -- x --
Current Odometer :	199717 Kms.
Origin :	Japan
Model Year :	2008
Gear Type :	--
Engine Size :	1500 CC
Engine No :	NIL
Horse Power :	162
Axles No :	2
Cylinders :	4
No Of Doors :	4
No Of Seats :	5
G. V. W. :	Empty Weight : 1620 Kgs. 1753 Kgs.

Certificate Number :	5-TAS-2021-14159119
Inspection Date :	08-05-2021
Certificate Print Date :	08-05-2021
Services :	Registration Test
Vehicle Testing Partner :	Tasjeel
Vehicle Testing Center :	Tasjeel Emirates Auction
Total Time Taken :	14 min 24 sec
Appointment Ref Number :	--
Start Time :	14:07
End Time :	14:21
Lane :	01
Token No. :	15
Attempt :	1
Prints No :	1

## Carbon footprint



Thank you! You are environment protector

## Estimated Vehicle Consumption (Rate last 12 Months)

22008 KM	1236 L	2003 AED	3.0 ton
Distance per year	Fuel consumed per year	Fuel cost per year	Carbon footprint per year

## Parameter Readings

Service brake imbalance on front axle	Service brake imbalance on rear axle	Parking brake imbalance between LHS and RHS	Vehicle on Petrol CO Reading
7 %	13 %	13 %	0.02 %

## Vehicle on Petrol HC

Reading  
60 PPM VOL

## Inspection Findings

Discrepancies	Old Value	New Value	Verified
Engine Size Discrepancy in Engine Size	1500	2500	

## Inspection Remarks:

FRT B/S CHASSIS REPAIRED AS PER QUICK REGISTRATION CCM W/O # 103513 DATED 01-26-2015/ FENDER FRAMES/ BULKHEAD REPAIRED/ BODY MINOR SCRATCHES & DENTS/ FIX BATTERY BRACKET ASAP

## Payment Details

Inspection Performed by	Payment Method	Transaction Number	Service Fees
74791	VTP Credit Account	14159119	AED 170 Collected on 08/05/2021
Parking Slot No	Service Name	Attempt	Received by
--	Registration Test	1	Raul Canceran Galang

1 This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.

2 Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص. المؤسسة غير مسؤولة عن العيوب الغير مرئية و الفحص الفني يتم ظاهريا طبقا لقانون السير و المرور 21 لسنة 1995

This certificate is valid for one transaction only for 30 days from the date of inspection. Company not responsible for any hidden defects and inspection done-According to Traffic law No., 21 year 1995

