



## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>17 Oct 2021, 17:57:22</b>
Transaction Number	<b>32909480 (CC10006)</b>	Queue Number	<b>312309</b>



Chassis Number	<b>JMYLRH77W4Z705077</b>
Engine Number	
Vehicle Class	<b>Car</b>
Manufacturer	<b>Mitsubishi</b>
Model	<b>Pajero</b>
Model Year	<b>2004</b>
Color	<b>Red</b>
Mileage	<b>0 Km</b>
Fuel Type	<b>Petrol</b>
No. Of Cylinders	<b>4</b>
Specification	<b>GCC Specification</b>

DEFECT	REMARKS	
<b>01 Body</b>		<b>جسم المركبة</b>
01.A Paint	BODY PORTION REPAINTED,PORTION REPAIRED	الصبغ
01.B Fenders	REPAINTED,PORTION REPAIRED	مدكار
01.C Doors	REPAINTED	أبواب
01.D Bonnet	REPAINTED	غطاء المحرك
01.E Trunk	REAR TRUNK INNER MATTING MISSING&TRUNK DOOR DENT	صندوق
01.F Bumper	REPAINTED,SCRATCHES	دعامية
<b>02 Chassis Condition</b>		<b>الشاصي</b>
02.A Chassis	OK	الشاسيه
<b>03 Engine Condition</b>		<b>المحرك</b>
03.A Engine Condition	OIL LEAK&MISFIRE	حالة المحرك
03.B Smoke	BLACK	دخان
<b>04 Transmission Condition</b>		<b>الجير</b>
04.A Road Test	NOT CHECK	فحص علي الطريق
04.B Gear Box	OIL LEAK&JARK	الجير

DEFECT	REMARKS	
<b>05 Exhaust System</b>		<b>نظام العادم</b>
05.A Other	EXHAUST PIPE REWELDED	اخرى
<b>06 Tires and Rims Condition</b>		<b>الاطارات</b>
06.A Front Tyre	BOTH SIDE 2018	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2018	الاطار الخلفي
<b>07 Wipers and Arms</b>		<b>المساحات</b>
07.A Wiper Arm &Blade	WORN OUT	ازرع المساحات والشفرات
<b>08 Interior Condition</b>		<b>الحاله الداخليه</b>
08.A Power Window Switch	FRONT RIGHT NOT WORKING FROM MAIN SWITCH	مفتاح النافذه

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.