







## Test Certificate

Site Number 840-EMIRATES AUCTION Plate Code : 0

: PRIVATE **Transaction Number** 26083020 Plate Category Transaction Date 05 MAY 2021 13:49:04 Plate Number : 423849 EA

330399 Queue Number

Chassis Number JN8BY15Y0XX423849 Manufacturer/Model : NISSAN/PATROL

Engine Number

Model Year 1999 Vehicle Color

Import Doc. Ref.

Vehicle Class LIGHT VEHICLE

Service / Indicator DSC AUCTION

nt of Vehicle Condition

**GREEN** 

		•	Statement of Vehicle Condition	
Defect	Result	Remarks		
AUTOMATIC TEST:				
14 Exhaust Gas Test			غاز العادم والكربون	
14.01 - Exhaust Gas Test	Passed		حص الغاز العادم-الكربون	
VISUAL TEST:				
02 Steering And Suspension System			مجلة القيادة ونظام التوصيلات	
02.01 - Steering Box Oil, Adjust, Change		OIL LEAK	يت صندوق عجلة القيادة	
02.08 - Power Steering Pump		PRESSURE HOSE OIL LEAK	مضخة الهيدرولكية للمقود	
02.11 - Shock Absorbers		ALL SHOCK ABSORBER REPLACED	خمد الصدمات	
04 Tires Rims			لاطارات والعجلات	
04.01 - Front Left And Right Hands Tires		TIRES 2018	لاطارات الامامية	
05 Body			هيكل	
05.02 - Paint		BODY SCRATCH & DENT & PAINT PARTL FADED & PARTLY RUSTY	صبغ ٢	
05.05 - Bumpers		FRONT BUMPER REPLACED & SUPPORT FRAME REPAIRED	دعامية ٢	
05.06 - Roof		SUN ROOF MALFUNCTION	سقف	
05.08 - Chassis (Frame)		REAR RIGHT SIDE CHASSIS MINOR BULGED	شاصية	
05.09 - Front And Rear Windshields		FRONT WINDSHIELD REPLACED	زجاج الامامي والخلفي	
05.12 - Side Safety Frame		LEFT MIDDLE BODY MOUNTING BRACKE DENT	واقيات الجانبية ET	
06 General Items			لاشياء العامة	
06.12 - Seats Condition And Seats Fixing		INTERIOR PARTLY WORN OUT	مقاعد وحالتها وتثبيتها	
06.13 - Exhaust System		EXHAUST RE-WELDED	ظام العادم	
06.14 - Transmission Condition		GEAR NOT CHECK	بالة ناقل الحركة	
06.16 - Engine Condition, Smoke		ENGINE RE-FITTED &WHITE SMOKE & N PULLING POWER /DRIVE BELT LOOSE & NOISY	-	
06.21 - Battery Condition		BATTERY DEAD	عالة البطارية	
07 Remarks			الدطات	
07.04 - Others		KILOMETER NO READING / BONNET DAMPER WEAK	لاحظات اخرى	
09 Auction			لفحص الكامل	





## Test Certificate

Site Number : 840-EMIRATES AUCTION Plate Code : 0

Transaction Number : 26083020 Plate Category : PRIVATE

Transaction Date : 05 MAY 2021 13:49:04 Plate Number : 423849 EA

Queue Number : 330399

Chassis Number : JN8BY15Y0XX423849 Manufacturer/Model : NISSAN/PATROL

Engine Number : Model Year : 1999

Vehicle Class : LIGHT VEHICLE Vehicle Color : GREEN

Service / Indicator : DSC AUCTION

Statement of Vehicle Condition

09.02 - Need Wheel Alignment

Import Doc. Ref.

ريب زيت المحرك OIL LEAK مريب زيت المحرك OIL LEAK

09.18 - A/C Not Cooling

اثر صبغ في المركبة BODY PORTIONS REPAINTED

The Test Certificate Shows the test Result at the time of inspection only.

Tasjeel is not responsible for any hidden defects.

شهادة الفحص تظهر نتيجة الفحص وقت الفحص فقط

تسجيل غير مسئولة عن العيوب الخفية

## **Test Certificate**









Change possession: 65107769

Chassis No: JN8BY15Y0XX423849

Vehicle Make: NISSAN
Vehicle Model: PATROL

Vehicle Class: Light Vehicle

Body Type: STATION

Fuel: Benzene
Color: Green

Drive Direction: --

Dimensions: (H x W x L) --x--x--

Current Odometer: --

Origin: Japan I Gear Type: --

**Engine No :** TB45024913

Axles No: 2
No Of Doors: 4
G. V. W.:

3100 Kgs.

Model Year: 1999

Engine Size: 4800 CC
Horse Power: --

Cylinders: 6
No Of Seats: 7

rear axle

7%

Empty Weight: 2305 Kgs.

Service brake imbalance on

 Inspection Date :
 08-05-2021

 Certificate Print Date :
 08-05-2021

 Services :
 Registration Test

5-TAS-2021-14158963

Vehicle Testing Partner: Tasjeel

Vehicle Testing Center: Tasjeel Emirates Auction

Total Time Taken: 11 min 33 sec

Certificate Number:

Appointment Ref Number : --

 Start Time: 13:53

 Lane: 01

 Attempt: 1

End Time: 14:05
Token No.: 13

Prints No: 1

#### Parameter Readings

Service brake imbalance on front axle

6%

Vehicle on Petrol HC

Reading 135 PPM VOL Parking brake imbalance between LHS and RHS

Vehicle on Petrol CO Reading

0.63 %

# Inspection Findings

Defects	Issue	Severity	
Rear registration plate lamps FIX NUMBER PLATE LIGHTS NOT WORKING	Bulb busted	Major	
Odometer Reading	No Reading	Major	
Stop lamps FIX BOT SIDE STOP LAMPS MALFUNCTION	Bulb busted	Major	
Warning triangle	Missing	Major	
Steering Box REPAIR OIL LEAK & CLEAN	Continuous or excessive oil leak Major		

Discrepancies	Old Value	New Value	Verified
Engine Size Discrepancy in Engine Size	4800	4500	

### Inspection Remarks:

REAR RIGHT SIDE CHASSIS MINOR BULGED/ LEFT MIDDLE BODY MOUNTING BRACKET DENT/ BUMPER SUPPORT FRAME REPAIRED/ BODY MINOR SCRATCHES & DENTS/ PAINT PORTIONS MINOR FADED

## **Payment Details**

 Inspection Performed by 74791
 Payment Method VTP Credit Account
 Transaction Number 14158963
 Service Fees AED 170 Collected on 08/05/2021

 Parking Slot No - Service Name Registration Test
 Attempt Received by Raul Canceran Galang

- 1 This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.
- Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.
   Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.
   هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحول. المؤسسة غير مسئولة عن العيوب الغير مرئية و الفحص الفني يتم ظاهريا طبقا

