



TEST CERTIFICATE

| | | | |
|--------------------|------------------------------|------------------|------------------------------|
| Site Number | 840-Emirates Auctions | Transaction Date | 19 Apr 2022, 15:04:45 |
| Transaction Number | 49660685 (CC10006) | Queue Number | 312309 |



| | |
|------------------|--------------------------|
| Chassis Number | 1GKS28E35BR277914 |
| Engine Number | |
| Vehicle Class | Car |
| Manufacturer | GMC |
| Model | Yukon |
| Model Year | 2011 |
| Color | White |
| Mileage | 107290 Km |
| Fuel Type | Petrol |
| No. Of Cylinders | 8 |
| Specification | GCC Specification |

| DEFECT | REMARKS | |
|----------------------------------|--|------------------------|
| 01 Transmission Condition | | الجير |
| 01.A Visual Gear Box Condition | SIGN OF MINOR OIL LEAK | حالة الجير النظري |
| 01.B Road Test | NOT CHECK | فحص علي الطريق |
| 01.C DIFFERENTIAL | REAR MINOR LEAK | الدفرنشل |
| 02 Body | | جسم المركبة |
| 02.A Paint | PORTION REPAIRED, REPAINTED & DENTS, SCRATCHES ON BODY | الصبغ |
| 02.B Fenders | PORTION REPAIRED, REPAINTED & RFITTED | مدكار |
| 02.C Bonnet | PORTION REPAIRED, REPAINTED | غطاء المحرك |
| 03 Engine Condition | | المحرك |
| 03.A Smoke | WHITE SMOKE | دخان |
| 03.B Visual Engine Condition | SIGN OF MINOR OIL LEAK & MISFIRING, ABNORMAL NOISY | حالة المحرك النظري |
| 04 Interior Condition | | الحاله الداخليه |
| 04.A AC Condition | OK | المكيف |
| 04.B Power Window Switch | REAR BOTH SIDE NOT WORKING | مفتاح النافذه |
| 04.C Dash Board | PORTION DAMAGED | لوحة القيادة |

| DEFECT | REMARKS | |
|------------------------------------|--|--------------------------|
| 05 Lights | | الاضاءة |
| 05.A Tail Light | REAR BOTH SIDE COVER CRACKED | الانارة |
| 05.B Fog light | NOT WORKING | كشاف الضباب |
| 05.C Head Light | RIGHT SIDE LOW BEAM NOT WORKING | الاضاءة الرئيسية |
| 06 Tires and Rims Condition | | الاطارات |
| 06.A Spare Tire &Tools | MISSING | الاطار الاحتياطي و العدة |
| 06.B Front Tyre | BOTH SIDE 2019 | الاطار الامامي |
| 06.C Rear Tyre | BOTH SIDE 2019 | الاطار الخلفي |
| 07 Chassis Condition | | الشاصي |
| 07.A Chassis | CHASSIS FRAME RUSTY & PORTION RUST PROOFED | الشاسيه |
| 08 Steering Condition | | المقود |
| 08.A Other | STABILIZER LINK BOOT CUT | اخرى |
| 09 Brake Condition | | الفرامل |
| 09.A Hand Brake | NOT WORKING | فرامل اليد |

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

Test Certificate



Vehicle
Registration



X FAILED

| | |
|----------------------------|--------------------------|
| Plate Details : | -- |
| Chassis No : | 1GKS28E35BR277914 |
| Vehicle Make : | GMC |
| Vehicle Model : | YUKON |
| Vehicle Class : | Light Vehicle |
| Body Type : | STATION |
| Fuel : | Benzene |
| Color : | White |
| Drive Direction : | -- |
| Dimensions : (H x W x L) : | -- x -- x -- |
| Current Odometer : | 107295 Kms. |
| Origin : United States | Model Year : 2011 |
| Gear Type : Automatic | Engine Size : 4200 CC |
| Engine No : NIL | Horse Power : 409 |
| Axles No : 2 | Cylinders : 8 |
| No Of Doors : 5 | No Of Seats : 8 |
| G. V. W. : 3175 Kgs. | Empty Weight : 1850 Kgs. |

| | |
|---------------------------|---------------------|
| Certificate Number : | 5-TAS-2022-16713265 |
| Inspection Date : | 08-05-2022 |
| Certificate Print Date : | 08-05-2022 |
| Services : | Registration Test |
| Vehicle Testing Partner : | Tasjeel |
| Vehicle Testing Center : | Tasjeel Al Aweer |
| Total Time Taken : | 11 min 54 sec |
| Appointment Ref Number : | -- |
| Start Time : 17:23 | End Time : 17:35 |
| Lane : 02 | Token No. : 330 |
| Attempt : 2 | Prints No : 1 |

Inspection Findings

| Defects | Issue | Severity |
|--|---------------------------------------|----------|
| Suspension kit replace front suspension bushes,shock absorber bushes,stablizer link rod bushes | Others (Major) | Major |
| Park and Tail lamps right side lense crack | Lens cracked, broken or faded (Major) | Major |
| Tire replace front both side tires | Worn out tread tire | Major |

Inspection Remarks: Front bumper,bulk head,fenders repaired

Payment Details

| | | | |
|----------------------------------|-----------------------------------|--------------------------------|--|
| Inspection Performed by 71051 | Payment Method Cash | Transaction Number 16713265 | Service Fees AED 70 Collected on 08/05/2022 |
| Parking Slot No -- | Service Name Registration Test | Attempt 2 | Received by Hussain Basha Akeel |

i This is to acknowledge the receipt of AED 70 (in words: Seventy Dirhams Only.), towards the above service.

i Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالترخيص الفني للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص.



This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.