







Test Certificate

Site Number 840-EMIRATES AUCTION Plate Code 0

Transaction Number 22345320 Plate Category PRIVATE Transaction Date 16 NOV 2020 10:33:20 Plate Number 3245 EA

Queue Number 248971

Chassis Number SJAAB1ZV7HC013245 Manufacturer/Model : BENTLEY/BENTAYGA

Engine Number

Model Year 2017

Import Doc. Ref.

Vehicle Class LIGHT VEHICLE Vehicle Color WHITE

Service / Indicator DSC AUCTION

Statement of Vehicle Condition

		Statement of Vehicle Condition	
Defect	Result	Remarks	
AUTOMATIC TEST:			
13 Brake System			الفر امل
13.04 - Brake Test	Passed		فحص الفر امل
14 Exhaust Gas Test			الغاز العادم والكربون
14.01 - Exhaust Gas Test	Passed		فحص الغاز العادم-الكربون
16 Side Slip Test			فحص ميزانية الاطارات
16.01 - Side Slip Test	Passed		فحص ميزانية الاطارات
VISUAL TEST:			
02 Steering And Suspension System			عجلة القيادة ونظام التوصيلات
02.15 - Suspension Crack Or Bend, Bushes		FRONT SUSPENSION RE-FITTED	التويصلات
04 Tires Rims			الاطارات والعجلات
04.01 - Front Left And Right Hands Tires		TIRES 2016 DRY& CRACKS	الاطارات الامامية
05 Body			الهيكل
05.02 - Paint		BODY & BUMPER MINOR SCRATCH	الصبغ
05.05 - Bumpers		FRONT BUMPER SUPPORT & CRASH BOX RE-FITTED	الدعامية
05.08 - Chassis (Frame)		FRONT SIDE FRAME MEMBER END REPAIRED	الشاصية
05.12 - Side Safety Frame		FRONT RIGHT FENDER FRAME & BULKHEAD REPAIRED	الواقيات الجانبية
06 General Items			الاشياء العامة
06.14 - Transmission Condition		ОК	حالة ناقل الحركة
06.16 - Engine Condition, Smoke		ENGINE OIL PAN RE-FITTED & OIL STAIN	حالة المحرك - الدخان
07 Remarks			ملاحظات
07.04 - Others		47940 KM BONNET & FRONT FENDERS RE-FITTED	ملاحظات اخرى
09 Auction			القحص الكامل
09.02 - Need Wheel Alignment			بحاجة الى ميزانية العجلات
09.14 - Sign Of Front Accident			أثر حادث في مقدمة المركبة
09.23 - Air Bag Damaged		BOTH SIDE CURTAIN AIR BAG DEPLOYED & CUT	المخدة الهوائية لا تعمل
09.24 - Digital Display Damaged/Warning Light	s	WARNING LIGHT ON	عطل في لوحة التحكم الالكتروني





Test Certificate

Site Number : 840-EMIRATES AUCTION Plate Code :

Transaction Number : 22345320 Plate Category : PRIVATE

Transaction Date : 16 NOV 2020 10:33:20 Plate Number : 3245 EA

Queue Number : 248971

Chassis Number : SJAAB1ZV7HC013245 Manufacturer/Model : BENTLEY/BENTAYGA

Engine Number :

Vehicle Class

Model Year : 2017
LIGHT VEHICLE Vehicle Color : WHITE

Import Doc. Ref.

Service / Indicator : DSC AUCTION

Statement of Vehicle Condition

09.25 - Body Repainted BODY PORTIONS REPAINTED قرّ صبغ في المركبة

The Test Certificate Shows the test Result at the time of inspection only.

Tasjeel is not responsible for any hidden defects.

شهادة الفحص تظهر نتيجة الفحص وقت الفحص فقط تسجيل غير مسئولة عن العيوب الخفية

Test Certificate









Transfer Certificate: 64513755 SJAAB1ZV7HC013245 Chassis No: Vehicle Make: BENTLEY Vehicle Model: BENTAYGA Vehicle Class: Light Vehicle **Body Type:** STATION Fuel: Benzene Color: White **Drive Direction:** Dimensions: (H x W x L) --x--x--**Current Odometer:** 47942 Kms. Origin: United King.. Model Year: 2017 6000 CC Gear Type: **Engine Size:** Engine No: DDBB003151 **Horse Power:** Axles No: Cylinders: No Of Doors: 4 No Of Seats: 5 G. V. W. : Empty Weight: 2400 Kgs.

Certificate Number: 5-TAS-2020-13016304 Inspection Date: 21-11-2020 Certificate Print Date : 21-11-2020 Services: Registration Test Vehicle Testing Partner: Tasjeel Vehicle Testing Center: Tasjeel Emirates Auction Total Time Taken: 6 min 6 sec Appointment Ref Number: --Start Time: 17:13 End Time: 17:19 Lane: Token No.: 9 01 Attempt : 1 Prints No: 1

Carbon footprint



Thank you! You are environment protector

Estimated Vehicle Consumption (Rate last 12 Months)



year



per year



Fuel cost per year

Carbon footprint per year

Parameter Readings

Vehicle on Petrol HC

Reading 46 PPM VOL

Service brake imbalance on front axle 10 %

Service brake imbalance on rear axle 4%

Parking brake imbalance between LHS and RHS 4%

Vehicle on Petrol CO Reading 0%

Payment Details

Inspection Performed by 59460

Parking Slot No

Payment Method VTP Credit Account **Service Name**

Registration Test

Inspection Remarks: front right side fender frame, bulk head, side frame member end repaired

Transaction Number 13016304 **Attempt**

Service Fees AED 170 Collected on 21/11/2020

Received by Raul Canceran Galana

1 This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.

Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص. المؤسسة غير مسئولة عن العيوب الغير مرئية و الفحص الفني يتم ظاهريا طبقا لقانون السير و المرور 21 لسنة 1995



This certificate is valid for one transaction only for 30 days from the date of inspection. Company not responsible for any hidden defects and inspection done-According to Traffic law No., 21 year 1995