




TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	26 Sep 2022, 13:35:22
Transaction Number	30614131 (CC10006)	Queue Number	596026



Chassis Number	JTDEPRAE9LJ007396
Engine Number	
Vehicle Class	Car
Manufacturer	Toyota
Model	Corolla
Model Year	2020
Color	Silver
Mileage	44374 Miles
Fuel Type	Petrol
No. Of Cylinders	4
Specification	USA Imported

DEFECT	REMARKS	
01 Body		جسم المركبة
01.A Bonnet	REFITTED	غطاء المحرك
01.B Fenders	FRONT BOTH SIDE REFITTED,REAR LEFT SIDE QUARTER PANEL REPAIRED.	مدكار
01.C Roof	ROOF & ROOF RAIL REPAIRED	السقف
01.D Sign of side accident		وجود مؤشر لحادث في الجانب
01.E Pillars	DOOR PILLARS REPAIRED.	القوائم
01.F Other	FRONT BUMPER FRAME ,FENDER FRAME ,BULKHEAD ,RADIATOR SUPPORT REPAIRED.	اخرى
01.G Bumper	MISALIGN	دعامية
01.H Sign of front accident		وجود مؤشر لحادث في المقدمة
01.I Paint	BODY TOTALY REPAINTED,EXCEPT TRUNK & PORTION REPAIRED,MINOR DENT ,SCRATCHES	الصبغ
02 Interior Condition		الحالة الداخلية
02.A Air Bag	DAMAGED	وسائد هوائية
02.B AC Condition	OK	المكيف
02.C Roof Ceiling	LOOSE	بطانه السقف
03 Chassis Condition		الشاصي

DEFECT	REMARKS	
03.A Chassis	FRONT LEFT SIDE CHASSIS ALIGN REPAIRED, OUTER MINOR DENT.	الشاسيه
04 Engine Condition		المحرك
04.A Visual Engine Condition	REFITTED MINOR OIL LEAK	حالة المحرك النظرى
05 Suspension System		ممتص الصدمات
05.A Arms	FRONT LEFT LOWER ARM HEATED REPAIRED, DENT.	ازرع
05.B Suspension Subframe	REFITTED.	
06 Tires and Rims Condition		الاطارات
06.A Rear Tyre	BOTH SIDE 2020	الاطار الخلفي
06.B Front Tyre	BOTH SIDE 2020	الاطار الامامي
07 Transmission Condition		الجير
07.A Visual Gear Box Condition	REFITTED OIL LEAK.	حالة الجير النظرى
07.B Road Test	NOT CHECK	فحص علي الطريق

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

Test Certificate



Vehicle
Registration



✓ PASS

Custom Certificate :	13037545
Chassis No :	JTDEPRAE9LJ007396
Vehicle Make :	TOYOTA
Vehicle Model :	COROLLA
Vehicle Class :	Light Vehicle
Body Type :	SALOON
Fuel :	Benzene
Color :	Silver
Drive Direction :	Left Hand Side
Dimensions : (H x W x L)	-- x -- x --
Current Odometer :	71413 Kms.
Origin : Japan	Model Year : 2020
Gear Type : Automatic	Engine Size : 2000 CC
Engine No : NIL	Horse --
Axles No : 2	Power :
No Of 4	Cylinders : 4
Doors :	No Of Seats : 5
G. V. W. : 2000 Kgs.	Empty 1600 Kgs.
	Weight :

Certificate Number :	5-TAS-2022-17708430		
Inspection Date :	25-09-2022		
Certificate Print Date :	25-09-2022		
Services :	Registration Test		
Vehicle Testing Partner :	Tasjeel		
Vehicle Testing Center :	Tasjeel Al Aweer		
Total Time Taken :	13 min 36 sec		
Appointment Ref Number :	--		
Start Time :	16:44	End Time :	16:58
Lane :	02	Token No. :	195
Attempt :	1	Prints No. :	1

Carbon footprint



Thank you! You are environment protector

Estimated Vehicle Consumption (Rate in 12 Months)

60 KM	5 L	17 AED	0.1 ton
Distance per year	Fuel consumed per year	Fuel cost per year	Carbon footprint per year

Parameter Readings

Service brake imbalance on front axle 0 %	Service brake imbalance on rear axle 7 %	Parking brake imbalance between LHS and RHS 3 %	Vehicle on Petrol CO Reading 0.05 %
Vehicle on Petrol HC Reading 96 PPM VOL			

Inspection Findings

Discrepancies	Old Value	New Value	Verified
Engine Size Discrepancy in Engine Size	2000	1800	

Inspection Remarks:

BULKHEAD RADIATOR FRAME FENDER FRAME LEFT SIDE WHEEL ARCH LEFT SIDE C PILLAR QUARTER PANEL OLD REPAIRED

Payment Details

Inspection Performed by 3104	Payment Method Cash	Transaction Number 17708430	Service Fees AED 170 Collected on 25/09/2022
Parking Slot No --	Service Name Registration Test	Attempt 1	Received by Sittu Paloth Sreesan Paloth

1 This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.

2 Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالتسجيل الفنى للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص.

This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.

