



## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>06 Mar 2023, 17:03:31</b>
Transaction Number	<b>75925181 (CC10013)</b>	Queue Number	<b>682611</b>



Chassis Number	<b>1C4BJWFG4GL128795</b>
Engine Number	
Vehicle Class	<b>Car</b>
Manufacturer	<b>Jeep</b>
Model	<b>Wrangler</b>
Model Year	<b>2016</b>
Color	<b>Green</b>
Mileage	<b>90176 Km</b>
Fuel Type	<b>Petrol</b>
No. Of Cylinders	<b>6</b>
Specification	<b>Imported</b>

DEFECT	REMARKS	
<b>01 Body</b>		<b>جسم المركبة</b>
01.A Bonnet	MODIFIED & REFITTED, RIGHT SIDE SAFETY LOCK MISSING	غطاء المحرك
01.B Fenders	REFITTED	مدكار
01.C Paint	BODY PORTION REPAINTED PORTION REPAIRED MINOR DENT SCRATCHES	الصبغ
01.D Bumper	FRONT BUMPER FRAME BOLT MISSING	دعامية
01.E Floor	ALL BODY MOUNT MISALIGN	الارضية
01.F Windshield	REPLACED	زجاج
01.G Other	FRONT ALL ASSEMBLY REFITTED	اخرى
<b>02 Interior Condition</b>		<b>الحالة الداخلية</b>
02.A AC Condition	OK, GRILL PORTION LOOSE	المكيف
02.B Sun Visor	LEFT SIDE STAND DAMAGED & COVER MIRROR MISSING	حاجب الشمس
02.C Mirror	LEFT SIDE VIEW MIRROR NOT WORKING	المرايا
02.D Dash Board	MINOR WORN OUT	لوحة القيادة
<b>03 Tires and Rims Condition</b>		<b>الاطارات</b>
03.A Front Tyre	BOTH SIDE 2019	الاطار الامامي
03.B Rear Tyre	BOTH SIDE 2019	الاطار الخلفي

DEFECT	REMARKS	
<b>04 Transmission Condition</b>		<b>الجير</b>
04.A Road Test	NOT CHECK	فحص علي الطريق
04.B Propeller Shaft	REFITTED, MISALIGN	ناقل الحركة
04.C Gear Box Mount	MOUNT BRACKET BOLT MISSING	كرسي الجير
04.D Visual Gear Box Condition	REFITTED	حالة الجير النظري
<b>05 Suspension System</b>		<b>ممتص الصدمات</b>
05.A Other	STABILIZER LINK BOOT CUT	اخرى
05.B Suspension Subframe	CENTER CROSS MUMBER BEND	
05.C Arms	BEND, MISALIGN	ازرع
05.D Ball Joint	BOOT CUT	مفصل كروي
05.E Shock Absorber	SHOCK ABSORBER & FRONT SUSPENSION MODIFIED	ممتص الصدمات
<b>06 Steering Condition</b>		<b>المقود</b>
06.A Steering Oil	OIL LEAK	زيت المقود
06.B Other	IDLER ARM BUSH CRACK & SHOCK BEND	اخرى
<b>07 Engine Condition</b>		<b>المحرك</b>
07.A Visual Engine Condition	REFITTED,SHAKING, ABNORMAL NOISY	حالة المحرك النظري
07.B Other	TOP COVER MISSING	اخرى
<b>08 Lights</b>		<b>الاضاءة</b>
08.A Warning Light	WARNING LIGHT ON IN DISPLAY	ضوء تحذير
<b>09 Chassis Condition</b>		<b>الشاسي</b>
09.A Chassis	FRONT LEFT SIDE CHASSIS REPAIRED , PORTION DENT,S	الشاسيه
09.B Chassis Number	MANUFACTURER STICKER MISSING	رقم القاعدة
<b>10 Exhaust System</b>		<b>نظام العادم</b>
10.A Other	BEND	اخرى

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

# Test Certificate



Vehicle  
Registration



X FAILED

Transfer Certificate :	65064712
Chassis No :	1C4BJWFG4GL128795
Vehicle Make :	JEEP
Vehicle Model :	WRANGLER
Vehicle Class :	Light Vehicle
Body Type :	STATION
Fuel :	Benzene
Color :	Green
Drive Direction :	--
Dimensions : (H x W x L)	-- x -- x --
Current Odometer :	90177 Kms.
Origin : United States	Model Year : 2016
Gear Type : Manual	Engine Size : 4000 CC
Engine No : NIL	Horse : 285
Axles No : 2	Power :
No Of : 4	Cylinders : 6
Doors :	No Of Seats : 5
G. V. W. : 2412 Kgs.	Empty : 2164 Kgs.
	Weight :

Certificate Number :	5-TAS-2023-18993422		
Inspection Date :	10-03-2023		
Certificate Print Date :	10-03-2023		
Services :	Registration Test		
Vehicle Testing Partner :	Tasjeel		
Vehicle Testing Center :	Tasjeel Al Aweer		
Total Time Taken :	8 min 24 sec		
Appointment Ref Number :	--		
Start Time :	10:41	End Time :	10:50
Lane :	03	Token No. :	130
Attempt :	1	Prints No. :	1

## Parameter Readings

Service brake imbalance on front axle	Service brake imbalance on rear axle	Parking brake imbalance between LHS and RHS	Vehicle on Petrol CO Reading
2 %	1 %	1 %	1.33 %
Vehicle on Petrol HC Reading			
1 PPM VOL			

## Inspection Findings

Defects	Issue	Severity
Bonnet fix bonnet lock damage	Others (Major)	Major
Stop lamps fix both side	Bulb busted	Major

## Inspection Remarks:

FRONT BOTH SIDE CHASSIS HEATED REPAIRED & HAVE PASSED CCM REPORT W/O NO-20180221-008. extra light for off road use only

## Payment Details

Inspection Performed by	Payment Method	Transaction Number	Service Fees
6831	VTP Credit Account	18993422	AED 170 Collected on 10/03/2023
Parking Slot No	Service Name	Attempt	Received by
--	Registration Test	1	Hussain Basha Akeel

1 This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.

2 Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالتسجيل الفنى للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص



This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.