





Test Certificate

Site Number	: 840-EMIRATES AUCTION	Plate Code	: 0
Transaction Number	: 27874581	Plate Category	: PRIVATE
Transaction Date	: 15 JUL 2021 15:54:09	Plate Number	: 58734 EA
Queue Number	: 372163	Import Doc. Ref.	:
Chassis Number	: WBAZV8107BLL58734	Manufacturer/Model	: BMW/X5
Engine Number	:	Model Year	: 2011
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: SILVER
Service / Indicator	: DSC AUCTION		

Statement of Vehicle Condition

Defect	Result	Remarks
AUTOMATIC TEST:		
13 Brake System		الفرامل
13.04 - Brake Test	Passed	فحص الفرامل
14 Exhaust Gas Test		الغاز العادم والكربون
14.01 - Exhaust Gas Test	Passed	فحص الغاز العادم-الكربون
16 Side Slip Test		فحص ميزانية الاطارات
16.01 - Side Slip Test	Passed	فحص ميزانية الاطارات
VISUAL TEST:		
02 Steering And Suspension System		عجلة القيادة ونظام التوصيلات
02.13 - Stub Axle Assemblies, Boots		المحور
		FRONT AXLE OIL LEAK
04 Tires Rims		الاطارات والعجلات
04.01 - Front Left And Right Hands Tires		الاطارات الامامية
		TIRES 2019 /2020
05 Body		الهيكل
05.02 - Paint		الصبغ
		BODY MINOR SCRATCH & DENT
05.04 - Fenders		المدكار
		REAR LEFT SIDE QUARTER PANEL & DOOR PILLAR REPAIRED
05.07 - Floor		الارضية
		BACK PANEL REPAIRED
05.08 - Chassis (Frame)		الشاصية
		REAR LEFT SIDE FRAME MEMBER JOINTS REPAIRED
06 General Items		الاشياء العامة
06.12 - Seats Condition And Seats Fixing		المقاعد وحالتها وتثبيتها
		INTERIOR PARTLY WORN OUT
06.14 - Transmission Condition		حالة ناقل الحركة
		OK
06.16 - Engine Condition, Smoke		حالة المحرك - الدخان
		ENGINE WHITE SMOKE & VIBRATION /OIL LEAK & OIL PAN REFITTED
07 Remarks		ملاحظات
07.04 - Others		ملاحظات اخرى
		148063 KM
09 Auction		الفحص الكامل
09.01 - Steering Oil Leaking		تهريب زيت صندوق عجلة القيادة
		STEERING RACK OIL LEAK
09.02 - Need Wheel Alignment		بحاجة الى ميزانية العجلات
09.15 - Sign Of Rear Accident		أثر حادث في مؤخرة المركبة
09.16 - Sign Of Side Accident		أثر حادث في جوانب المركبة



Test Certificate

Site Number	: 840-EMIRATES AUCTION	Plate Code	: 0
Transaction Number	: 27874581	Plate Category	: PRIVATE
Transaction Date	: 15 JUL 2021 15:54:09	Plate Number	: 58734 EA
Queue Number	: 372163	Import Doc. Ref.	:
Chassis Number	: WBAZV8107BLL58734	Manufacturer/Model	: BMW/X5
Engine Number	:	Model Year	: 2011
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: SILVER
Service / Indicator	: DSC AUCTION		

Statement of Vehicle Condition

09.25 - Body Repainted	BODY PORTIONS REPAINTED	أثر صيغ في المركبة
<p>The Test Certificate Shows the test Result at the time of inspection only. Tasjeel is not responsible for any hidden defects.</p> <p>شهادة الفحص تظهر نتيجة الفحص وقت الفحص فقط تسجيل غير مسئول عن العيوب الخفية</p>		

Test Certificate



Vehicle
Registration



✓ PASS

Possession Certificate : 65530139

Chassis No : WBAZV8107BLL58734

Vehicle Make : BMW

Vehicle Model : X5

Vehicle Class : Light Vehicle

Body Type : STATION

Fuel : Benzene

Color : Silver

Drive Direction : --

Dimensions : (H x W x L) -- x -- x --

Current Odometer : 148065 Kms. x

Origin : Germany Model Year : 2011

Gear Type : -- Engine Size : 4400 CC

Engine No : NONE Horse Power : 408

Axles No : 2 Cylinders : 8

No Of Doors : 4 No Of Seats : 4

G. V. W. : Empty Weight : 1970 Kgs.
2800 Kgs.

Certificate Number : 5-TAS-2021-14635808

Inspection Date : 17-07-2021

Certificate Print Date : 17-07-2021

Services : Registration Test

Vehicle Testing Partner : Tasjeel

Vehicle Testing Center : Tasjeel Emirates Auction

Total Time Taken :
16 min 6 sec

Appointment Ref Number : --

Start Time : 10:34

End Time : 10:50

Lane : 01

Token No. : 2

Attempt : 1


Prints No : 1

Carbon footprint



Your immediate action to protect Dubai environment is required

Estimated Vehicle Consumption (Rate last 12 Months)



Parameter Readings

Service brake imbalance on front axle
7 %

Service brake imbalance on rear axle
7 %

Parking brake imbalance between LHS and RHS
7 %

Vehicle on Petrol CO Reading
0.02 %

Vehicle on Petrol HC Reading
14 PPM VOL

Inspection Remarks:

REAR LEFT SIDE FRAME MEMBER JOINTS REPAIRED REAR LEFT SIDE QUARTER PANEL & DOOR PILLAR REPAIRED BACK PANEL REPAIRED



Odometer Record
Replace Events Date

21/02/2021

Payment Details

Inspection Performed by
59460

Payment Method
VTP Credit Account

Transaction Number
14635808

Service Fees
AED 170 Collected on 17/07/2021

Parking Slot No
--

Service Name
Registration Test

Attempt
1

Received by
Raul Canceran Galang

1 This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.

1 Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص. المؤسسة غير مسؤولة عن العيوب الغير مرئية و الفحص الفني يتم ظاهريا طبقا لقانون السير و المرور 21 لسنة 1995

This certificate is valid for one transaction only for 30 days from the date of inspection. Company not responsible for any hidden defects and inspection done-According to Traffic law No., 21 year 1995

