

TEST CERTIFICATE

Site Number
Transaction Number

840-Emirates Auctions 10028286 (CC10009) Transaction Date

20 Nov 2022, 12:05:10

Queue Number 626509

Chassis Number

JN8AZ2NC5E9351826

Infiniti

Engine Number

Manufacturer

Vehicle Class Car

Model QX 80

Model Year 2014

Color Grey

Mileage 165624 Miles

Fuel Type Petrol

No. Of Cylinders

Specification Imported

DEFECT REMARKS

O1 Interior Condition الحاله الداخلية

O1.A AC Condition OK

O1.B Other GEAR LEVER SHIFT LOCK MISSING

02.A Front TyreBOTH SIDE 2019 CRACKEDIllumination02.B Rear TyreBOTH SIDE 2019 CRACKEDIllumination

جسم المركبة جسم المركبة عند المركبة عند

O3.A Paint BODY REPAINTED PORTION REPAIRED , MINOR DENTS الصبغ

SCRATCHES

وجود مؤشر لحادث في الجانب وجود مؤشر لحادث في الجانب

O3.C Other FRONT BUMPER FRAME BULK HEAD FENDER FRAME

RADIATOR SUPPORT REPAIRED

صداً UNDER FLOOR PARTS CHASSIS GETTING RUSTY

وجود مؤشر لحادث في المقدمة وجود مؤشر لحادث في المقدمة

غطاء المحرك REFITTED REPAIRED REPAINTED

مدكار 03.G Fenders FRONT REFITTED RAR LEFT SIDE REPAINTED

أبواب 03.H Doors LEFT SIDE DOOR REPAINTED , REFITTED

DEFECT	REMARKS	
04 Engine Condition		المحرك
04.A Visual Engine Condition	OIL LEAK REFITTED, ABNORMAL NOISY	حالة المحرك النظرى
04.B Mount	MOUNT RUBBER CUT	كرسي
04.C Smoke	BLACK SMOKE	دخان
05 Steering Condition		المقود
05.A Steering Oil	MINOR OIL LEAK	زيت المقود
05.B Tie Rod End	BOOT CUT	مؤخرة الرودات
06 Transmission Condition		الجير
06.A Visual Gear Box Condition	OIL LEAK REFITTED , JERKING	حالة الجير النظرى
06.B Gear Box Mount	MOUNT RUBBER CUT	كرسي الجير
06.C Road Test	NOT CHECKED	فحص علي الطريق
07 Suspension System		ممتص الصدمات
07.A Other	STABILIZER LINK BOOT CUT	اخري
07.B Arms	LOWER ARM BUSHES CUT	ازرع
07.C Ball Joint	BOOT CUT	مفصل كروي
08 Lights		الاضاءة
08.A Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
08.B Head Light	LENS AFDED	الاضاءة الرئيسية
09 Chassis Condition		الشاصي
09.A Chassis	FRONT RIGHT SIDE CHASSIS OUTER MOUNT AREA REPAIRED	الشاسيه
10 Seats Condition		المقاعد
10.A Seat Condition	PORTION CRACKED	حالة المقاعد

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate,
 Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

Test Certificate







✓ PASS

Plate Details:	V 49385 Dubai Private		
Chassis No:	JN8AZ2NC5E9351826		
Vehicle Make :	INFINITI		
Vehicle Model:	80 QX		
Vehicle Class:	Light Vehicle		
Body Type:	STATION		
Fuel:	Benzene		
Color:	Gray		
Drive Direction:			
Dimensions : (H x W x L)	xx		
Current Odometer:	266541 Kms.		
Origin: Japan	Model Year: 2014		
Gear Type: Automatic	Engine Size: 5600 CC		
Engine No: NIL	Horse 400		
Axles No: 2	Power :		
No Of 4	Cylinders: 8		
Doors :	No Of Seats: 8		
G. V. W.: 2500 Kgs.	Empty 2000 Kgs.		
	Weight:		

Certificate Number :		1-TAS-2022-18124924			
Inspection Date :		17-11-2022			
Certificate Print Date :		17-11-2022			
Services :		Renewal Test			
Vehicle Testing Partner:		Tasjeel			
Vehicle Testing Center:		Tasjeel Al Aweer			
Total Time Taken:		6 min 32 sec			
Appointm Number :	ent Ref				
Start	17:21		End Time:	17:27	
Time :		_	Token No.:	247	
Lane :	02	_	Prints No:	1	
Attempt :	: 1				

Carbon footprint



Your immediate action to protect Dubai environment is required

Estimated Vehicle Consumption (Rate in 12 Months)



Distance per

year

18960 L
Fuel consumed
per year



64654 AED
Fuel cost per
year
year
Fuel cost per
year
per year

Parameter Readings

Service brake imbalance on front axle rear axle between LHS and RHS 27 % 27 % 29 % 0.47 %

Parking brake imbalance between LHS and RHS 39 % 0.47 %

Inspection Remarks:

Reading 177 PPM VOL

FRONT RIGHT SIDE CHASSIS, BODY MOUNT BRACKET REPAIRED/DENT PASS WITH C.C.M REPORT-2022-04-13-4,REPAIRED&DENT,FRONT RIGHT SIDE BULK HEAD FENDER FRAME RPAIRED.UNDER MINOR OIL WETNESS, CHASSIS/UNDER PARTS MINOR RUSTY./minor engine oil leak

Payment Details

Inspection Performed by
34600Payment MethodTransaction NumberService Fees34600Cash18124924AED 170 Collected on 17/11/2022Parking Slot No
--Service Name
Renewal TestAttemptReceived by
Bajurdeen Abdul Gafoor

- 1 This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.
- Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.
 تستخدم هذه الشهادة حصرا في العمليات الخاصة بالترخيص الفني للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية
 ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال

ons.
تستخدم هذه الشهادة حص ترخيص المركبة. لا تتحمل 30. يوم من تاريخ الفحص

This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.