



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	19 Oct 2022, 17:54:09
Transaction Number	80955299 (CC10010)	Queue Number	608445



Chassis Number	JTMHU09J894015077
Engine Number	
Vehicle Class	Car
Manufacturer	Toyota
Model	Land Cruiser
Model Year	2009
Color	Gold
Mileage	144613 Km
Fuel Type	Petrol
No. Of Cylinders	6
Specification	GCC Specification

DEFECT	REMARKS	
01 Interior Condition		الحاله الداخليه
01.A AC Condition	LOW COOLING	المكيف
01.B Dash Board	REFITTED.	لوحة القيادة
01.C Sunroof	NOT WORK.	فتحت سقف
01.D Mirror	REAR VIEW MIRROR LOOSE.	المرايا
01.E Power Window Switch	REAR RIGHT SIDE NOT WORK.	مفتاح النافذه
02 Transmission Condition		الجير
02.A Road Test	NOT CHECK	فحص علي الطريق
02.B Visual Gear Box Condition	REFITTED.	حالة الجير النظري
03 Tires and Rims Condition		الاطارات
03.A Rear Tyre	BOTH SIDE 2018 & CRACKED ,WORN OUT	الاطار الخلفي
03.B Spare Tire &Tools	SPARE TIRE BRACKET MISSING.	الاطار الاحتياطي و العدة
03.C Front Tyre	BOTH SIDE 2018 & CRACKED	الاطار الامامي
04 Body		جسم المركبة
04.A Vehicle Model	BODY MODIFIED & SHAPE CHANGED TO NEW MODEL	طرز المركبة
04.B Floor	UNDER BODY SUSPENSION PARTS RUSTPROOF COATED.	الارضية

DEFECT	REMARKS	
04.C Pillars	RIGHT SIDE C/D/PILLAR QUATER PANEL WHEEL ARCH REPAIRED	القوائم
04.D Paint	BODY REPAINTED PORTION REPAIRED , MINOR DENT SCRATCHES	الصبغ
04.E Doors	REFITTED	أبواب
04.F Trunk	REFITTED	صندوق
05 Seats Condition		المقاعد
05.A Seat Belt	FRONT RIGHT SIDE NOT WORKING	حزام الأمان
06 Engine Condition		المحرك
06.A Visual Engine Condition	REFITTED OIL LEAK.	حالة المحرك النظري
07 Suspension System		ممتص الصدمات
07.A Shock Absorber	LEAK.	ممتص الصدمات
07.B Arms	LOWER ARM BUSHES CRACK.	ازرع
08 Chassis Condition		الشاسي
08.A Chassis	CHASSIS FRAME COMPLETE THICK RUSTPROOFED ,STILL RUSTY.	الشاسيه

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

Test Certificate



Vehicle
Registration



X FAILED

Plate Details :	--
Chassis No :	JTMHU09J894015077
Vehicle Make :	TOYOTA
Vehicle Model :	LAND CRUISER
Vehicle Class :	Light Vehicle
Body Type :	STATION
Fuel :	Benzene
Color :	Golden
Drive Direction :	--
Dimensions : (H x W x L)	-- x -- x --
Current Odometer :	144618 Kms.
Origin : Japan	Model Year : 2009
Gear Type : Automatic	Engine Size : 5700 CC
Engine No : 5689914	Horse 413
Axles No : 2	Power :
No Of 4	Cylinders : 6
Doors :	No Of Seats : 8
G. V. W. : 2883 Kgs.	Empty 2638 Kgs.
	Weight :

Certificate Number :	5-TAS-2022-17917953		
Inspection Date :	22-10-2022		
Certificate Print Date :	22-10-2022		
Services :	Registration Test		
Vehicle Testing Partner :	Tasjeel		
Vehicle Testing Center :	Tasjeel Al Aweer		
Total Time Taken :	18 min 36 sec		
Appointment Ref Number :	--		
Start Time :	9:51	End Time :	10:10
Lane :	02	Token No. :	106
Attempt :	1	Prints No. :	1

Parameter Readings

Service brake imbalance on front axle	Service brake imbalance on rear axle	Parking brake imbalance between LHS and RHS	Vehicle on Petrol CO Reading
1 %	1 %	4 %	0 %

Vehicle on Petrol HC Reading
23 PPM VOL

Inspection Findings

Defects	Issue	Severity
Stop lamps FIX RIGHT BRAKE LIGHT	Defective	Major
Park and Tail lamps FIX REAR RIGHT SIDE PARK LIGHT	Defective	Major
Rear registration plate lamps FIX NUMBER PLATE LIGHT	Defective	Major
Spare Tire KEEP SPARE TIRE	Missing (Major)	Major

Discrepancies	Old Value	New Value	Verified
Engine Size Discrepancy in Engine Size	5700	4000	

Inspection Remarks: FRONT BUMPER FRAME REPAIRED/CHASSIS RUSTY & RUST PROOFED

Payment Details

Inspection Performed by 34600	Payment Method Cash	Transaction Number 17917953	Service Fees AED 170 Collected on 22/10/2022
Parking Slot No --	Service Name Registration Test	Attempt 1	Received by Sittu Paloth Sreesan Paloth

1 This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.

2 Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالترخيص الفني للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص

This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.

