



## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>16 Nov 2022, 11:27:55</b>
Transaction Number	<b>7778848 (CC10009)</b>	Queue Number	<b>623127</b>



Chassis Number	<b>MR0DX6CD8G0010978</b>
Engine Number	
Vehicle Class	<b>Car</b>
Manufacturer	<b>Toyota</b>
Model	<b>Hilux</b>
Model Year	<b>2016</b>
Color	<b>White</b>
Mileage	<b>173106 Km</b>
Fuel Type	<b>Petrol</b>
No. Of Cylinders	<b>4</b>
Specification	<b>GCC Specification</b>

DEFECT	REMARKS	
<b>01 Tires and Rims Condition</b>		<b>الاطارات</b>
01.A Front Tyre	BOTH SIDE 2020	الاطار الامامي
01.B Rear Tyre	BOTH SIDE 2020	الاطار الخلفي
<b>02 Engine Condition</b>		<b>المحرك</b>
02.A Smoke	MINOR BLACK SMOKE	دخان
02.B Mount	MOUNT RUBBER CRACKED	كرسي
02.C Visual Engine Condition	MINOR OIL LEAK	حالة المحرك النظري
<b>03 Steering Condition</b>		<b>المقود</b>
03.A Steering Oil	MINOR OIL LEAK	زيت المقود
03.B Tie Rod End	BOOT CUT	مؤخرة الرودادات
<b>04 Body</b>		<b>جسم المركبة</b>
04.A Paint	BODY PORTION REPAINTED MINOR DENTS SCRATCHES ON BODY	الصبغ
04.B Rusty	UNDER FLOOR PARTS CHASSIS GETTING RUSTY	صدأ
<b>05 Transmission Condition</b>		<b>الجير</b>
05.A Visual Gear Box Condition	MINOR OIL LEAK	حالة الجير النظري

DEFECT	REMARKS	
05.B Road Test	NOT CHECKED	فحص علي الطريق
05.C Gear Box Mount	MOUNT RUBBER CRACKED	كرسي الجير
<b>06 Chassis Condition</b>		<b>الشاسي</b>
06.A Chassis	CHASSIS FRAME REAR CROSSMEMBER RUSTY WEAK	الشاسيه
<b>07 Interior Condition</b>		<b>الحاله الداخليه</b>
07.A AC Condition	OK	المكيف
<b>08 Suspension System</b>		<b>ممتص الصدمات</b>
08.A Arms	LOWER ARM BUSHES CUT	ازرع
08.B Ball Joint	BOOT CUT	مفصل كروي
08.C Leaf Spring	BUSHES WORN OUT	

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

# Test Certificate



Vehicle  
Registration



PENDING

Plate Details :	--
Chassis No :	MR0DX6CD8G0010978
Vehicle Make :	TOYOTA
Vehicle Model :	HILUX
Vehicle Class :	Light Vehicle
Body Type :	PICK-UP
Fuel :	Benzene
Color :	White
Drive Direction :	--
Dimensions : (H x W x L)	-- x -- x --
Current Odometer :	173110 Kms.
Origin : Thailand	Model Year : 2016
Gear Type : Manual	Engine Size : 1800 CC
Engine No : 2tr8872003	Horse 162
Axles No : 2	Power :
No Of 4	Cylinders : 4
Doors :	No Of Seats : 6
G. V. W. : 2700 Kgs.	Empty 2292 Kgs.
	Weight :

Not allowed to be used as an official Doc

**⚠ Please communicate with the inspection supervisor at the same testing center in order to complete your transaction**

Certificate Number :	5-TAS-2022-18193950		
Inspection Date :	28-11-2022		
Certificate Print Date :	28-11-2022		
Services :	Registration Test		
Vehicle Testing Partner :	Tasjeel		
Vehicle Testing Center :	Tasjeel Al Aweer		
Total Time Taken :	11 min 8 sec		
Appointment Ref Number :	--		
Start Time :	10:12	End Time :	10:23
Lane :	02	Token No. :	117
Attempt :	1	Prints No. :	1

## Parameter Readings

Service brake imbalance on front axle	Service brake imbalance on rear axle	Parking brake imbalance between LHS and RHS	Vehicle on Petrol CO Reading
6 %	2 %	14 %	0 %

Vehicle on Petrol HC Reading  
0 PPM VOL

## Inspection Findings

Defects	Issue	Severity
Safety Sign Stickers (for commercial) <b>FIX REAR GOIVE WAY STICKER&amp;KEEP 2KILO GRAM FIRE CYLINDER</b>	Missing	Major
Weight and Capacity Sticker <b>FIX FRONT BOTH SIDE DOOR WEIGHTCAPACITY&amp;NUMBER OF PASSENGER</b>	Not available on both front doors	Major
Park and Tail lamps <b>repair right side tail lamp&amp;repair front left side park lamp</b>	Defective	Major

## Pending Defect for Fixing

Issue
Safety Sign Stickers (for commercial)
Weight and Capacity Sticker
Park and Tail lamps

Inspection result will be fail automatically in case the pending defects were not repaired within 4 calendar days

Discrepancies	Old Value	New Value	Verified
Engine Size Discrepancy in Engine Size	1800	2700	

Inspection Remarks: CHASSIS&FLOOR MINOR RUSTY/FRONT BUMPER MINOR MIS ALIGN

## Payment Details

Inspection Performed by 30544 3104	Payment Method Cash	Transaction Number 18193950	Service Fees AED 170 Collected on 28/11/2022
Parking Slot No --	Service Name Registration Test	Attempt 1	Received by Sittu Paloth Sreesan Paloth

This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.



❗ Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

