



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	27 Jun 2022, 17:44:13
Transaction Number	63933049 (CC10006)	Queue Number	312309



Chassis Number	WBSDE91021GJ20678
Engine Number	
Vehicle Class	Car
Manufacturer	BMW
Model	M5
Model Year	2001
Color	Grey
Mileage	001 Km
Fuel Type	Petrol
No. Of Cylinders	8
Specification	GCC Specification

DEFECT	REMARKS	
01 Interior Condition		الحاله الداخليه
01.A Odometer reading	READING NOT SHOWING	قراءة عداد المسافات
01.B Power Window Switch	REAR LEFT SIDE SWITCH DAMAGED	مفتاح النافذه
01.C Roof Ceiling	CHANGED	بطانه السقف
01.D Dash Board	DAMAGED, BUTTONS MISSING	لوحة القيادة
02 Body		جسم المركبة
02.A Paint	BODY TOTALLY REPAINTED PORTION REPAIRED , MINOR DENTS SCRATCHES ON BODY (VEHICLE COLOR CHANGED FRONT SILVER GRAY)	الصبغ
02.B Sign of front accident		وجود مؤشر لحادث في المقدمة
02.C Floor	FLOOR PORTION REPAIRED	الارضية
02.D Pillars	REAR BOTH SIDE C/ PILLAR OUTER REPAIRED REPAINTED	القوائم
02.E Other	FRONT BUMPER FRAME BULK HEAD FENDER FRAME RADIATOR SUPPORT REPAIRED	اخرى
03 Tires and Rims Condition		الاطارات
03.A Front Tyre	BOTH 2017 CRACKED EXPIRED	الاطار الامامي
03.B Rear Tyre	BOTH 2016 CRACKED EXPIRED	الاطار الخلفي

DEFECT	REMARKS	
04 Engine Condition		المحرك
04.A Visual Engine Condition	MINOR OIL LEAK REFITTED , ABNORMAL NOISY	حالة المحرك النظري
04.B Mount	MOUNT RUBBER CRACKED	كرسي
05 Transmission Condition		الجير
05.A Road Test	NOT CHECKED	فحص علي الطريق
05.B Visual Gear Box Condition	MINOR OIL LEAK , REFITTED	حالة الجير النظري
05.C Gear Box Mount	MOUNT RUBBER CRACKED	كرسي الجير
06 Suspension System		ممتص الصدمات
06.A Arms	LOWER ARM BUSHES CRACKED	ازرع
06.B Ball Joint	BOOT CUT	مفصل كروي
06.C Other	STABILIZER LINK BOOT CUT	اخرى
07 Chassis Condition		الشاسي
07.A Chassis	FRONT BOTH SIDE CHASSIS REPAIRED	الشاسيه
07.B Chassis Number	DOOR STICKER FADED	رقم القاعدة
08 Steering Condition		المقود
08.A Tie Rod End	BOOT CUT	مؤخرة الروداد

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

Test Certificate



Vehicle
Registration



X FAILED

Possession Certificate :	66001469
Chassis No :	WBSDE91021GJ20678
Vehicle Make :	BMW
Vehicle Model :	M5
Vehicle Class :	Light Vehicle
Body Type :	SALOON
Fuel :	Benzene
Color :	Gray
Drive Direction :	--
Dimensions : (H x W x L)	-- x -- x --
Current Odometer :	--
Origin : Germany	Model Year : 2001
Gear Type : Automatic	Engine Size : 4900 CC
Engine No : 60162361	Horse 507
Axles No : 2	Power :
No Of 4	Cylinders : 8
Doors :	No Of Seats : 5
G. V. W. : 2100 Kgs.	Empty 1600 Kgs.
	Weight :

Certificate Number :	5-TAS-2022-17100522
Inspection Date :	28-06-2022
Certificate Print Date :	28-06-2022
Services :	Registration Test
Vehicle Testing Partner :	Tasjeel
Vehicle Testing Center :	Tasjeel Al Aweer
Total Time Taken :	9 min 47 sec
Appointment Ref Number :	--
Start Time : 16:09	End Time : 16:19
Lane : 02	Token No. : 191
Attempt : 1	Prints No : 1

Parameter Readings

Service brake imbalance on front axle	Service brake imbalance on rear axle	Parking brake imbalance between LHS and RHS	Vehicle on Petrol CO Reading
2 %	9 %	11 %	0.45 %
Vehicle on Petrol HC Reading			
103 PPM VOL			

Inspection Findings

Defects	Issue	Severity
Tire change all crack & worn out	Cracked	Major
Odometer Reading	No Reading	Major

Inspection Remarks: front both side chassis , fender frame , bulk head repaired // old // under neat oil wetnss //

Payment Details

Inspection Performed by	Payment Method	Transaction Number	Service Fees
32858 71051	Cash	17100522	AED 170 Collected on 28/06/2022
Parking Slot No	Service Name	Attempt	Received by
--	Registration Test	1	Hussain Basha Akeel

- This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.
- Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالتريخيص الفني للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية تريخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص



This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.