



TEST CERTIFICATE

Site Number **840-Emirates Auctions** Transaction Date **02 Jun 2022, 16:03:02**
 Transaction Number **35900649 (CC10008)** Queue Number **312309**



Chassis Number **JTGHJ01J563008757**
 Engine Number
 Vehicle Class **Car**
 Manufacturer **Toyota**
 Model **Land Cruiser**
 Model Year **2006**
 Color **Antique white**
 Mileage **563332 Km**
 Fuel Type **Petrol**
 No. Of Cylinders **8**
 Specification **GCC Specification**

DEFECT	REMARKS	
01 Body		جسم المركبة
01.A Paint	BODY TOTALLY REPAINTED & PORTION REPAIRED,MINOR DENT,SCRATCHES,PORTION RUSTY	الصبغ
01.B Fenders	FRONT FENDER REFITTED	مدكار
01.C Bonnet	REFITTED,1 BOLT MISSING & SHOCK WEAK	غطاء المحرك
01.D Door Handle &Lock	REAR BOTH SIDE OUTER LOCK HANDLE DAMAGED	مقابض الأبواب والأقفال
01.E Other	FRONT FENDER FRAME ,BULK HEAD,BUMPER FRAME RADIATOR SUPPORT REPAIRED & FRONT FENDER FRAME CRACKED,HOLE	اخرى
01.F Rusty	UNDER BODY PARTS & SUSPENTION, FLOOR, CHASSIS RUSTY,WEAK HOLE	صدأ
01.G Floor	RIGHT SIDE RUNNING BOARD REPAIRED	الارضية
02 Interior Condition		الحالة الداخلية
02.A AC Condition	NOT COOLING	المكيف
02.B Steering Wheel and control buttons	WORN OUT & HORN NOT WORKING	عجلة القيادة وازرار التحكم
02.C Roof Ceiling	PORTION LOOSE	بطانة السقف
02.D Audio	REAR RIGHT SIDE DOOR SPEAKER COVER MISSING	صوتيات
02.E Door Panel	PORTION DAMAGED	لوحة بطانة الباب

DEFECT	REMARKS	
02.F Dash Board	LEATHER PORTION LOOSE	لوحة القيادة
02.G Power Window Switch	REAR BOTH SIDE WINDOW GLASS ADJUSTMENT HANDLE MISSING	مفتاح النافذه
03 Transmission Condition		الجير
03.A Road Test	NOT CHECK	فحص علي الطريق
03.B Visual Gear Box Condition	REFITTED	حالة الجير النظرى
03.C Gear Box Mount	MOUNT BUSH CRACKED	كرسي الجير
04 Brake Condition		الفرامل
04.A Hand Brake	WEAK	فرامل اليد
05 Engine Condition		المحرك
05.A Mount	MOUNT MODIFIED	كرسي
05.B Smoke	WHITE SMOKE	دخان
05.C Visual Engine Condition	ENGINE MODIFIED TO V8 ENGINE	حالة المحرك النظرى
06 Tires and Rims Condition		الاطارات
06.A Spare Tire & Tools	SPARE TIRE MISSING	الاطار الاحتياطي و العدة
06.B Front Tyre	BOTH SIDE 2018	الاطار الامامي
06.C Rear Tyre	BOTH SIDE 2018/2020	الاطار الخلفي
07 Suspension System		ممتص الصدمات
07.A Ball Joint	BOOT CRACKED	مفصل كروي
07.B Other	STABLIZER LINK BOOT CUT	اخرى
07.C Arms	FRONT LOWER ARM BUSH CRACKED	ازرع
08 Steering Condition		المقود
08.A Tie Rod End	BOOT CUT	مؤخرة الروداد
09 Lights		الاضاءة
09.A Head Light	RIGHT SIDE LOW BEAM NOT WORKING	الاضاءة الرئيسية
10 Seats Condition		المقاعد
10.A Seat Condition	REAR SEATS LOOSE,BOLT MISSING & NOT FIXED PROPERLY	حالة المقاعد
11 Exhaust System		نظام العادم
11.A Other	EXHAUST MODIFIED	اخرى
12 Chassis Condition		الشاسي
12.A Chassis	CHASSIS FRAME RUSTY & PORTION RUST PROOFED	الشاسيه

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.



condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

Test Certificate



Vehicle
Registration



X FAILED

Plate Details :	--
Chassis No :	JTGHJ01J563008757
Vehicle Make :	TOYOTA
Vehicle Model :	LAND CRUISER
Vehicle Class :	Light Vehicle
Body Type :	STATION
Fuel :	Benzene
Color :	White
Drive Direction :	--
Dimensions : (H x W x L)	-- x -- x --
Current Odometer :	563332 Kms.
Origin : Japan	Model Year : 2006
Gear Type : Manual	Engine Size : 5700 CC
Engine No : 0712934	Horse : 295
Axles No : 2	Power :
No Of : 4	Cylinders : 6
Doors :	No Of Seats : 7
G. V. W. : 2909 Kgs.	Empty : 2300 Kgs.
	Weight :

Certificate Number :	5-MUT-2022-16797890		
Inspection Date :	19-05-2022		
Certificate Print Date :	19-05-2022		
Services :	Registration Test		
Vehicle Testing Partner :	Al Mutakamela Vehicle Testing LLC		
Vehicle Testing Center :	Al Mutakamela Vehicle Testing Alaweer		
Total Time Taken :	15 min 36 sec		
Appointment Ref Number :	--		
Start Time :	16:06	End Time :	16:21
Lane :	02	Token No. :	241
Attempt :	1	Prints No. :	1

Parameter Readings

Service brake imbalance on front axle
9 %

Service brake imbalance on rear axle
8 %

Parking brake imbalance between LHS and RHS
24 %

Vehicle on Petrol CO Reading
0.71 %

Vehicle on Petrol HC Reading
1585 PPM VOL

Inspection Findings

Defects	Issue	Severity
Battery FIX BATTERY CLAMP	Unsecure	Major
Engine ENGINE MOUNTING MODIFIED	Mounting modified or repositioned	Major
Spare Tire	Missing (Major)	Major
Fender REPAIR FRONT LEFT SIDE FENDER INNER DAMAGE & REPAIR REAR RIGHT SIDE QUARTER PANEL RUSTY / HOLE	Damaged	Major
Seats FIX PROPERLY REAR SEATS	Loose mounting bolts or nuts	Major
Exhaust pipes and silencers muffler FIX ORIGINAL EXHAUST (HEADERS)	Modified	Major
Vehicle Floor CLEAN STEAM WASH UNDER FLOOR & FRONT TO REAR CHASSIS FRAME MUDDY / OILY	Others (Major)	Major
Engine ENGINE MODIFIED TO HIGHER CAPACITY, FIX ORIGINAL	Modified	Major
Doors and Locks CHANGE REAR BOTH SIDE DOORS OUTER HANDLE DAMAGE	Unsecure	Major
Bumper REPAIR REAR BUMPER SUPPORT RUSTY	Others (Major)	Major
Vehicle on Petrol HC Reading	HC reading more than 800ppm	Major
Gear/Differential REPAIR UNDER OIL LEAK	Oil leaking continuously	Major
Vehicle on Petrol HC Reading	HC reading more than 800ppm	Major

Discrepancies	Old Value	New Value	Verified
Seats Incorrect Number of Seats	7	5	
Engine Size Discrepancy in Engine Size	5700	4500	

Inspection Remarks:

FRONT BOTH SIDE FENDER FRAME,RADIATOR FRAME,WHEEL ARCH,FIREWALL, BOTH SIDE RUNNINGBOARD, FRONT FLOOR REPAIRED

Payment Details

Inspection Performed by 446	Payment Method Cash	Transaction Number 16797890	Service Fees AED 170 Collected on 19/05/2022
Parking Slot No --	Service Name Registration Test	Attempt 1	Received by Talat Abdelmalek Mohammed Elbasher

- ❗ This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.
❗ Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالترخيص الفني للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص

This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.

