





Test Certificate

| | | | |
|---------------------|------------------------|--------------------|-----------------------|
| Site Number | : 840-EMIRATES AUCTION | Plate Code | : 0 |
| Transaction Number | : 19883572 | Plate Category | : PRIVATE |
| Transaction Date | : 02 JUN 2020 09:54:10 | Plate Number | : 118580 EA |
| Queue Number | : 181050 | Import Doc. Ref. | : |
| Chassis Number | : JTEHJ09J555118580 | Manufacturer/Model | : TOYOTA/LAND CRUISER |
| Engine Number | : | Model Year | : 2005 |
| Vehicle Class | : LIGHT VEHICLE | Vehicle Color | : WHITE |
| Service / Indicator | : DSC AUCTION | | |

Statement of Vehicle Condition

| Defect | Result | Remarks |
|---|---|--|
| AUTOMATIC TEST: | | |
| 13 Brake System | | الفرامل |
| 13.04 - Brake Test | Failed | فحص الفرامل |
| 14 Exhaust Gas Test | | الغاز العادم والكربون |
| 14.01 - Exhaust Gas Test | Passed | فحص الغاز العادم-الكربون |
| 16 Side Slip Test | | فحص ميزانية الاطارات |
| 16.01 - Side Slip Test | Passed | فحص ميزانية الاطارات |
| VISUAL TEST: | | |
| 04 Tires Rims | | الاطارات والعجلات |
| 04.01 - Front Left And Right Hands Tires | ALL TIRES 2017 | الاطارات الامامية |
| 05 Body | | الهيكل |
| 05.02 - Paint | BODY & BUMPER SCRATCH | الصبغ |
| 05.05 - Bumpers | FRONT BUMPER REPLACED | الدعامية |
| 05.06 - Roof | SUN ROOF NOT FUNCTION | السقف |
| 05.09 - Front And Rear Windshields | FRONT REPLACED & SPOT CRACK | الزجاج الامامي والخلفي |
| 06 General Items | | الاشياء العامة |
| 06.07 - Extra Warning Lights And Reflectors | CHECK ENGINE LIGHT ON | الانوار التحذيرية والاضافات والمثلث العاكس |
| 06.13 - Exhaust System | MODIFIED | نظام العادم |
| 06.16 - Engine Condition, Smoke | OK | حالة المحرك - الدخان |
| 09 Auction | | الفحص الكامل |
| 09.06 - Chassis Ok | OK | النشاصي جيد |
| 09.11 - Gear Box Oil Leaking | GEAR & TRANSFER CASE OIL LEAK | تهريب زيت الجير |
| 09.14 - Sign Of Front Accident | FRONT BOTH SIDE BUMPER SUPPORT BRACKET DENT | اثر حادث في مقدمة المركبة |
| 09.25 - Body Repainted | | اثر صبغ في المركبة |
| 201 Mvis-Steering And Suspension System | | عجلة القيادة ونظام التوصيلات |
| 201.13 - Stub Axle Assemblies,Boots | FRONT AXLE OIL LEAK | المحور |
| 28 Auction - Tires & Rims | | الاطارات والعجلات |
| 28.01 - Front Left & Right Tires | NEED ALIGNMENT | الاطارات الامامية |
| 99 Others | | أخرى |



Test Certificate

| | | | |
|---------------------|------------------------|--------------------|-----------------------|
| Site Number | : 840-EMIRATES AUCTION | Plate Code | : 0 |
| Transaction Number | : 19883572 | Plate Category | : PRIVATE |
| Transaction Date | : 02 JUN 2020 09:54:10 | Plate Number | : 118580 EA |
| Queue Number | : 181050 | Import Doc. Ref. | : |
| Chassis Number | : JTEHJ09J555118580 | Manufacturer/Model | : TOYOTA/LAND CRUISER |
| Engine Number | : | Model Year | : 2005 |
| Vehicle Class | : LIGHT VEHICLE | Vehicle Color | : WHITE |
| Service / Indicator | : DSC AUCTION | | |

Statement of Vehicle Condition

| | |
|--|-----------|
| 99.1 - Others | 267621 KM |
| The Test Certificate Shows the test Result at the time of inspection only. | |