



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	12 Dec 2021, 18:10:32
Transaction Number	56664290 (CC10006)	Queue Number	312309



Chassis Number	1GNSK8E34BR273923
Engine Number	
Vehicle Class	Car
Manufacturer	Chevrolet
Model	Suburban
Model Year	2011
Color	Silver
Mileage	409938 Km
Fuel Type	Petrol
No. Of Cylinders	8
Specification	GCC Specification

DEFECT	REMARKS	
01 Body		جسم المركبة
01.A Fenders	FRON BOTH SIDE REPAINTED & REAR RIGHT SIDE REPAIRED, REPAINTED	مدكار
01.B Paint	PORTION REPAIRED, REPAINTED & DENTS, SCRATCHES ON BODY	الصبغ
01.C Doors	RIGHT SIDE BOTH REPAIRED & REPAINTED	أبواب
01.D Trunk	REPAIRED & REPAINTED	صندوق
01.E Door Handle & Lock	REAR RIGHT SIDE BROCKEN	مقابض الأبواب والأقفال
01.F Bumper	REPAINTED	دعامية
02 Seats Condition		المقاعد
02.A Seat Condition	FRONT BOTH SIDE COVER DAMAGED	حالة المقاعد
03 Interior Condition		الحالة الداخليه
03.A Dash Board	DASH BOARD & CONSOLE BOX LEATHER PORTION DAMAGED	لوحة القيادة
03.B Mirror	FOLDING NOT WORKING	المرايا
03.C AC Condition	OK	المكيف
03.D Steering Wheel and control buttons	COVER DAMAGED	عجلة القيادة وازرار التحكم

DEFECT	REMARKS	
03.E Sun Visor	RIGHT SIDE MIRROR CRACKED & COVER MISSING	حاجب الشمس
04 Transmission Condition		الجير
04.A Road Test	NOT CHECK	فحص علي الطريق
04.B Gear Box	OK	الجير
05 Lights		الاضاءة
05.A Warning Light	WARNING LIGHT ON IN DISPLAY	ضوء تحذير
05.B Head Light	RIGHT SIDE LOW BEAM NOT WORKING & BOTH SIDE HIGH BEAM NOT WORKING PROPERLY	الاضاءة الرئيسية
05.C Fog light	LEFT SIDE NOT WORKING	كشاف الضباب
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2018 CRACKED	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2018 CRACKED	الاطار الخلفي
07 Engine Condition		المحرك
07.A Engine Condition	OIL LEAK	حالة المحرك
08 Suspension System		ممتص الصدمات
08.A Shock Absorber	REAR RIGHT SIDE LEAK	ممتص الصدمات
08.B Arms	FRONT LOWER ARM BUSHES CRACKED	ازرع
09 Chassis Condition		الشاسي
09.A Chassis	CHASSIS FRAME COMPLETELY RUST PROOFED & RUSTY	الشاسيه
09.B Chassis Number	CHASSIS NUMBER STICKER DAMAGED	رقم القاعدة

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

Test Certificate



Vehicle
Registration



X FAILED

Plate Details :	--
Chassis No :	1GNSK8E34BR273923
Vehicle Make :	CHEVROLET
Vehicle Model :	SUBURBAN
Vehicle Class :	Light Vehicle
Body Type :	STATION
Fuel :	Benzene
Color :	Silver
Drive Direction :	--
Dimensions : (H x W x L)	-- x -- x --
Current Odometer :	409940 Kms.
Origin : United States	Model Year : 2011
Gear Type : Automatic	Engine Size : 6000 CC
Engine No : NIL	Horse Power : --
Axles No : 2	Cylinders : 8
No Of Doors : 4	No Of Seats : 8
G. V. W. : 3200 Kgs.	Empty Weight : 2350 Kgs.

Certificate Number :	5-CAR-2022-15871177
Inspection Date :	11-01-2022
Certificate Print Date :	11-01-2022
Services :	Registration Test
Vehicle Testing Partner :	AG Cars
Vehicle Testing Center :	AG Cars Al Mamzar
Total Time Taken :	13 min 3 sec
Appointment Ref Number :	--
Start Time : 17:43	End Time : 17:56
Lane : 03	Token No. : 242
Attempt : 2	Prints No : 1

Inspection Findings

Defects	Issue	Severity
Dip beams(Low Beams) headlight REPAIR RIGHT SIDE LOW BEAM	Defective	Major
Engine REPAIR ENGINE OIL LEAK	Others (Major)	Major
Front and Rear Windshields CHANGE FRONT WIND SHIELD	Front Cracked/broken (Major)	Major
Tire CHANGE ALL 4 TIRES CRACKS	Cracked	Major
Doors and Locks REPAIR RIGHT SIDE DOOR LOCK&HANDLE DAMAGE	Not open/close properly	Major

Inspection Remarks: UNDERNEATH PARTS GETTING RUSTY.

Payment Details

Inspection Performed by 6463	Payment Method Credit Card	Transaction Number 15871177	Service Fees AED 70 Collected on 11/01/2022
Parking Slot No --	Service Name Registration Test	Attempt 2	Received by Mary Antony

- This is to acknowledge the receipt of AED 70 (in words: Seventy Dirhams Only.), towards the above service.
- Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالترخيص الفني للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص.

This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.

