





Test Certificate

Site Number	: 840-EMIRATES AUCTION	Plate Code	: 0
Transaction Number	: 20036023	Plate Category	: PRIVATE
Transaction Date	: 24 JUN 2020 11:20:43	Plate Number	: 90012 EA
Queue Number	: 188431	Import Doc. Ref.	:
Chassis Number	: 4T1BF1FK5HU690012	Manufacturer/Model	: TOYOTA/CAMRY
Engine Number	:	Model Year	: 2017
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: BLUE
Service / Indicator	: DSC AUCTION		

Statement of Vehicle Condition

Defect	Result	Remarks
AUTOMATIC TEST:		
13 Brake System		الفرامل
13.04 - Brake Test	Passed	فحص الفرامل
14 Exhaust Gas Test		الغاز العادم والكربون
14.01 - Exhaust Gas Test	Passed	فحص الغاز العادم-الكربون
VISUAL TEST:		
02 Steering And Suspension System		عجلة القيادة ونظام التوصيلات
02.15 - Suspension Crack Or Bend, Bushes		التوصيلات
04 Tires Rims		الاطارات والعجلات
04.01 - Front Left And Right Hands Tires		الاطارات الامامية
04.08 - Spare Tires		الاطار الاحتياطي
05 Body		الهيكل
05.03 - Doors		الابواب
05.04 - Fenders		المدكار
05.05 - Bumpers		الدعامية
05.07 - Floor		الارضية
05.08 - Chassis (Frame)		الشاصية
05.12 - Side Safety Frame		الواقبات الجانبية
06 General Items		الاشياء العامة
06.21 - Battery Condition		حالة البطارية
07 Remarks		ملاحظات
07.04 - Others		ملاحظات اخرى
09 Auction		الفحص الكامل
09.09 - Engine And Gear Box Performance Ok	OK	فحص حالة الماكينة والجير
09.14 - Sign Of Front Accident		أثر حادث في مقدمة المركبة
09.16 - Sign Of Side Accident		أثر حادث في جوانب المركبة
09.23 - Air Bag Damaged		المخدة الهوائية لا تعمل
09.25 - Body Repainted		أثر صيغ في المركبة



Test Certificate

Site Number	: 840-EMIRATES AUCTION	Plate Code	: 0
Transaction Number	: 20036023	Plate Category	: PRIVATE
Transaction Date	: 24 JUN 2020 11:20:43	Plate Number	: 90012 EA
Queue Number	: 188431	Import Doc. Ref.	:
Chassis Number	: 4T1BF1FK5HU690012	Manufacturer/Model	: TOYOTA/CAMRY
Engine Number	:	Model Year	: 2017
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: BLUE
Service / Indicator	: DSC AUCTION		

Statement of Vehicle Condition

The Test Certificate Shows the test Result at the time of inspection only.

Test Certificate



PASS

Change possession :	64357134
Chassis No :	4T1BF1FK5HU690012
Vehicle Make :	TOYOTA
Vehicle Model :	CAMRY
Vehicle Class :	Light Vehicle
Body Type :	SALOON
Fuel :	Benzene
Color :	Blue
Drive Direction :	--
Dimensions : (H x W x L) -- x -- x --	
Current Odometer :	67875 Kms.
Origin :	Japan
Gear Type :	--
Engine No :	nil
Axles No :	2
No Of Doors :	4
G. V. W. :	1800 Kgs.
Model Year :	2017
Engine Size :	2500 CC
Horse Power :	185
Cylinders :	4
No Of Seats :	5
Empty Weight :	1385 Kgs.

Certificate Number :	5-TAS-2020-12082449
Inspection Date :	01-07-2020
Certificate Print Date :	01-07-2020
Services :	Registration Test
Vehicle Testing Partner :	Tasjeel
Vehicle Testing Center :	Tasjeel Al Aweer
Total Time Taken :	18 min 39 sec
Appointment Ref Number :	--
Start Time :	13:15
End Time :	13:34
Lane :	03
Token No. :	166
Attempt :	1
Prints No :	1

Carbon footprint



Thank you! You are environment protector

Estimated Vehicle Consumption (Rate in 12 Months)

72 KM	8 L	13 AED	0.1 ton
Distance per year	Fuel consumed per year	Fuel cost per year	Carbon footprint per year

Parameter Readings

Service brake imbalance on front axle 3 %	Service brake imbalance on rear axle 10 %	Parking brake imbalance between LHS and RHS 29 %	Vehicle on Petrol CO Reading 0 %
Vehicle on Petrol HC Reading 2 PPM VOL			

Inspection Remarks:

FRONT RIGHT CHASSIS/BUMPER/BULKHEAD/BONNET?FENDER & FRAME REPAIRED//CCM W.O.2020-06-30-4//REAR SUB-FRAME MINOR DENT // BODY DENT SCRATCHES

Payment Details

Inspection Performed by 62424	Payment Method Cash	Transaction Number 12082449	Service Fees AED 170 Collected on 01/07/2020
Parking Slot No --	Service Name Registration Test	Attempt 1	Received by Mohammed Ahmed Mohsen Albaidhani

This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.

Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص. المؤسسة غير مسؤولة عن الصيانة الفورية للفحص. TASJEEL

