







Test Certificate

Site Number : 840-EMIRATES AUCTION Plate Code : 0

Transaction Number : 21019108 Plate Category : PRIVATE
Transaction Date : 09 SEP 2020 14:58:56 Plate Number : 764 EA

Queue Number : 218303

Chassis Number : JN8FY15Y69X574764 Manufacturer/Model : NISSAN/PATROL

Engine Number :

Vehicle Class

Import Doc. Ref.

Service / Indicator : DSC AUCTION

Statement of Vehicle Condition

			Statement of Vehicle Condition
Defect	Result	Remarks	
AUTOMATIC TEST:			
13 Brake System			نر امل
13.04 - Brake Test	Passed		حص الفر امل
14 Exhaust Gas Test			خاز العادم والكربون
14.01 - Exhaust Gas Test	Passed		حص الغاز العادم-الكربون
VISUAL TEST:			
02 Steering And Suspension System			مجلة القيادة ونظام التوصيلات
02.04 - Steering Ball Joints, Boots		ROMANO SEAL LEAK	صلات عمود عجلة القيادة
02.16 - Engine Mounting		CRACK	بطنرت عمود عجبه العيادة ر اسي المحرك
03 Brake System		CRACK	راسي المحرك ظام الفرامل
·			
03.01 - Brake Efficiency Front Wheels Left And Right Hands		BRAKE ROTORS RUSTY/ BRAKE PADS ALMOST WORN OUT	وة فرامل المحور الامامي
04 Tires Rims		, <u>-</u>	لاطارات والعجلات
04.01 - Front Left And Right Hands Tires		ALL TIRES DOT 2020	لاطارات الامامية
04.07 - Rims		LUG NUT MISSING	رنجات
05 Body			هيكل
05.01 - Rusty		UNDERBODY PORTION RUSTY	صدأ
05.02 - Paint		BODY SCRATCHES & DENTS	صبغ
05.08 - Chassis (Frame)		REAR BOTH SIDE MEMBER INNER BULG CHASSIS PARTLY RUSTY	شاصية ED/
05.09 - Front And Rear Windshields		FRONT WINDSHIELD SPOT CRACKS	لزجاج الامامي والخلفي
05.10 - All Glasses		REAR WINDOWS MALFUNCTION	زجاج الجانبي وزجاج الابواب
06 General Items			لاشياء العامة
06.10 - Mirrors Side View		MALFUNCTION	مرايا الجانبية
06.12 - Seats Condition And Seats Fixing		INTERIOR PARTLY WORN OUT	مقاعد وحالتها وتثبيتها
06.13 - Exhaust System		REWELDED	ظام العادم
06.14 - Transmission Condition		ОК	بالة ناقل الحركة
06.16 - Engine Condition, Smoke		REFITTED/ OIL LEAK/ NO COOLANT IN RESERVOIR	بالة المحرك - الدخان
07 Remarks			لاحظات
07.04 - Others		225763 KMS	لاحظات اخرى





Test Certificate

Site Number : 840-EMIRATES AUCTION Plate Code : 0

Transaction Number : 21019108 Plate Category : PRIVATE

Transaction Date : 09 SEP 2020 14:58:56 Plate Number : 764 EA

Queue Number : 218303 Import Doc. Ref.

Chassis Number : JN8FY15Y69X574764 Manufacturer/Model : NISSAN/PATROL

Engine Number : Model Year : 2009

Vehicle Class : LIGHT VEHICLE Vehicle Color : WHITE

Service / Indicator : DSC AUCTION

Statement of Vehicle Condition

09 Auction لفحص الكامل لفحص الكامل

09.02 - Need Wheel Alignment

09.25 - Body Repainted BODY PORTIONS REPAINTED ثر صبغ في المركبة

The Test Certificate Shows the test Result at the time of inspection only.

Tasjeel is not responsible for any hidden defects.

شهادة الفحص تظهر نتيجة الفحص وقت الفحص فقط

تسجيل غير مسئولة عن العيوب الخفية

Test Certificate









Transfer Certificate: 61641378 Chassis No: JN8FY15Y69X574764 Vehicle Make: NISSAN Vehicle Model: PATROL Vehicle Class: Light Vehicle **Body Type:** STATION Fuel: Benzene Color: White **Drive Direction:** Dimensions : (H x W x L) --x--x--**Current Odometer:** 225766 Kms. Origin: Japan Model Year : 2009 Gear Type : Engine Size: 3500 CC Engine No: TB48058765 Horse Power: Axles No: Cylinders: No Of Doors: 4 No Of Seats:

Certificate Number: 5-TAS-2020-12537193 Inspection Date: 13-09-2020 **Certificate Print Date:** 13-09-2020 Services: Registration Test Vehicle Testing Partner: Tasjeel Vehicle Testing Center: Tasjeel Emirates Auction Total Time Taken: 6 min 46 sec Appointment Ref Number : --Start Time: 12:25 End Time: 12:31 Lane: 01 Token No.: 6 Attempt: 1 Prints No: 1

Carbon footprint

G. V. W. :

3130 Kgs.

ton CO2 2.7 ton 12+

Thank you! You are environment protector

Estimated Vehicle Consumption (Rate last 12 Months)



10622 KM 1093 L Distance per Fuel consumed year per year

Fuel cost per

vear

Carbon footprint per year

Parameter Readings

Service brake imbalance on front axle

5%

Reading 85 PPM VOL Service brake imbalance on rear axle 8%

Empty Weight: 2000 Kgs.

Parking brake imbalance between LHS and RHS 35 %

Vehicle on Petrol CO Reading 0.27 %

Inspection Findings

Vehicle on Petrol HC

Discrepancies Old Value **New Value** Verified Engine Size Discrepancy in Engine Size 3500 4800

Inspection Remarks: BOTH BULK HEAD & REAR QUARTER PANEL REPAIRED BOTH SIDE CHASSIS BULGE & DENT

Payment Details

Inspection Performed by 59460

Parking Slot No

Payment Method VTP Credit Account

Service Name **Registration Test**

Transaction Number

12537193

Attempt

Service Fees

AED 170 Collected on 13/09/2020

Received by

Raul Canceran Galang

1 This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service. Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص. المؤسسة غير مسئولة عن العيوب الغير مرئية و الفحص الفني يتم ظاهريا طبقا لقانون السير و المرور 21 لسنة 1995



This certificate is valid for one transaction only for 30 days from the date of inspection. Company not responsible for any hidden defects and inspection done-According to Traffic law No., 21 year 1995