





### Test Certificate

Site Number	: 840-TASJEEL EM AUCTION	Plate Code	: 0
Transaction Number	: 18585213	Plate Category	: PRIVATE
Transaction Date	: 23 NOV 2019 12:21:52	Plate Number	: 9984 EA
Queue Number	: 120537	Import Doc. Ref.	:
Chassis Number	: 1N4AL3A99DC139984	Manufacturer/Model	: NISSAN/ALTIMA
Engine Number	:	Model Year	: 2013
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: SILVER
Service / Indicator	: DSC AUCTION		

### Statement of Vehicle Condition

Defect	Result	Remarks
AUTOMATIC TEST:		
13 Brake System		الفرامل
13.04 - Brake Test	Passed	فحص الفرامل
14 Exhaust Gas Test		الغاز العادم والكربون
14.01 - Exhaust Gas Test	Passed	فحص الغاز العادم-الكربون
VISUAL TEST:		
01 Lights		الانوار
01.01 - Side Lights		الانوار الجانبية
		FRONT LEFT INDICATOR LIGHT BROKEN
02 Steering And Suspension System		عجلة القيادة ونظام التوصيلات
02.11 - Shock Absorbers		مخمد الصدمات
		REAR COIL SPRING WELDED / VEHICLE BOUNCING WHILE DRIVING
04 Tires Rims		الاطارات والعجلات
04.01 - Front Left And Right Hands Tires		الاطارات الامامية
		ALL TIRE DOT 2017
05 Body		الهيكل
05.04 - Fenders		المدكار
		FRONT FENDERS REFITTED
05.07 - Floor		الارضية
		FLOOR REINFORCEMENT DENT
05.08 - Chassis (Frame)		الشاصية
		REAR RIGHT CHASSIS MEMBER END DENT & FRONT RIGHT CHASSIS MEMBER OUTER SKIRT SCRATCH
06 General Items		الاشياء العامة
06.04 - Horn		الزامور
		DISTORTION NOISE
06.11 - Seat Belts		حزام الامان
		FRONT RIGHT PRETENSIONER MALFUCTION
06.14 - Transmission Condition		حالة ناقل الحركة
		GEAR SHIFTER SWITCH MALFUNCTION
06.16 - Engine Condition, Smoke		حالة المحرك - الدخان
		OIL LEAK FROM ENGINE
09 Auction		الفحص الكامل
09.02 - Need Wheel Alignment		بحاجة الى ميزانية العجلات
		VEHICLE PULLING TO LEFT & STEERING VIBRATION WHILE DRIVING
09.14 - Sign Of Front Accident		اثر حادث في مقدمة المركبة
		FRONT BULK HEAD REFITTED
09.15 - Sign Of Rear Accident		اثر حادث في مؤخرة المركبة
		REAR CRASH BOX DENT
09.24 - Digital Display Damaged/Warning Lights		عطل في لوحة التحكم الالكتروني
		AIR BAG WARNING
09.25 - Body Repainted		اثر صيغ في المركبة
		BODY PORTION REPAINTED



### Test Certificate

Site Number	: 840-TASJEEL EM AUCTION	Plate Code	: 0
Transaction Number	: 18585213	Plate Category	: PRIVATE
Transaction Date	: 23 NOV 2019 12:21:52	Plate Number	: 9984 EA
Queue Number	: 120537	Import Doc. Ref.	:
Chassis Number	: 1N4AL3A99DC139984	Manufacturer/Model	: NISSAN/ALTIMA
Engine Number	:	Model Year	: 2013
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: SILVER
Service / Indicator	: DSC AUCTION		

Statement of Vehicle Condition

The Test Certificate Shows the test Result at the time of inspection only.

# Test Certificate



Possession Certificate : 63843913  
 Chassis No : 1N4AL3A99DC139984  
 Vehicle Make : NISSAN  
 Vehicle Model : ALTIMA  
 Vehicle Class : Light Vehicle  
 Body Type : SALOON  
 Fuel : Benzene  
 Color : Silver  
 Drive Direction : --  
 Dimensions : (H x W x L) -- x -- x --  
 Current Odometer : 225698 Kms.  
 Origin : United States      Model Year : 2013  
 Gear Type : --  
 Engine No : QR2571208...      Engine Size : 3500 CC  
 Axles No : 2      Horse Power : 177  
 No Of Doors : 4      Cylinders : 4  
 G. V. W. : 1700 Kgs.      No Of Seats : 5  
    Empty Weight : 1200 Kgs.

Certificate Number : 5-TAM-2019-11094770  
 Inspection Date : 11-11-2019  
 Certificate Print Date : 11-11-2019  
 Services : Registration Test  
 Vehicle Testing Partner : Tamam  
 Vehicle Testing Center : Tamam Vehicles Testing  
 Total Time Taken : 14 min 27 sec  
 Appointment Ref Number : --  
 Start Time : 17:12      End Time : 17:27  
 Lane : 07      Token No. : 280  
 Attempt : 1      Prints No : 1

### Parameter Readings

Service brake imbalance on front axle 2 %	Service brake imbalance on rear axle 7 %	Parking brake imbalance between LHS and RHS 1 %	Vehicle on Petrol CO Reading 0.56 %
Vehicle on Petrol HC Reading 58 PPM VOL			

### Inspection Findings

Defects	Issue	Severity
Spare Tire		
Arm, mounting, bushes FRONT LOWER ARM BUSHES ✓	Puncture (Major)	Major
Springs (leaf/coil) and shackle pin REAR BS HARD, FIX WITH ORIGINAL	Worn-out bushes	Major
Front Seat belts FRONT RHS	Heated	Major
Seats REAR SEATS	Defective	Major
	Loose mounting bolts or nuts	Major

### Discrepancies

Discrepancies	Old Value	New Value	Verified
Engine Size Discrepancy in Engine Size	3500	2500	

Inspection Remarks: MINOR DENT ON REAR RHS CHASSIS END