Test Certificate









Transfer Certificate: 64535821 ZHWBA37S88LA02629 Chassis No: Vehicle Make: LAMBORGHINI Vehicle Model: MURCIELAGO Vehicle Class: Light Vehicle **Body Type:** SALOON Fuel: Benzene Color: Black **Drive Direction:** Dimensions: (H x W x L) --x--x--**Current Odometer:** 10722 Kms. Origin: Model Year: 2008 **Engine Size:** 6500 CC Gear Type: Engine No: L63702592 Horse Power: 579 Axles No: Cylinders: No Of Doors: 2 No Of Seats: G. V. W.: Empty Weight: 1700 Kgs. 2250 Kas

Certificate Number: 5-TAS-2021-14326100 Inspection Date: 03-06-2021 Certificate Print Date : 03-06-2021 Services: Registration Test Vehicle Testing Partner: Tasjeel Vehicle Testing Center: Tasjeel Al Qusais Total Time Taken: 8 min 27 sec Appointment Ref Number: --Start Time: 13:47 End Time: 13:56 Lane: Token No.: 313

Carbon footprint



Thank you! You are environment protector

Estimated Vehicle Consumption (Rate in 12 Months)



1KM

Distance per

year

Attempt:

1





Prints No: 1



Parameter Readings

Service brake imbalance on front axle

22 %

Service brake imbalance on rear axle 20 %

Parking brake imbalance between LHS and RHS 31% Vehicle on Petrol CO Reading 0%

Vehicle on Petrol HC Reading 10 PPM VOL

Inspection Remarks: UNDER BODY COVERD // F//

Payment Details

Inspection Performed by 71051

Parking Slot No

Payment Method
Cash
Service Name
Registration Test

Transaction Number
14326100
Attempt

Service Fees AED 170 Collected on 03/06/2021

Received by

Saeed Thailakanday Madakandy

- 1 This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.
- 🚯 Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص . المؤسسة غير مسئولة عن العيوب الغير مرئية و الفحص الفني يتم ظاهريا طبقا لقانون السير و المرور 21 لسنة 1995

TASIEEL!! تسجيل

This certificate is valid for one transaction only for 30 days from the date of inspection. Company not responsible for any hidden defects and inspection done-According to Traffic law No., 21 year 1995