





Test Certificate

Site Number	: 840-EMIRATES AUCTION	Plate Code	: 0
Transaction Number	: 20024466	Plate Category	: PRIVATE
Transaction Date	: 22 JUN 2020 11:02:01	Plate Number	: 03640 EA
Queue Number	: 187264	Import Doc. Ref.	:
Chassis Number	: MHKMF53F3GK003640	Manufacturer/Model	: TOYOTA/AVANZA
Engine Number	:	Model Year	: 2016
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: WHITE
Service / Indicator	: DSC AUCTION		

Statement of Vehicle Condition

Defect	Result	Remarks
AUTOMATIC TEST:		
13 Brake System		الفرامل
13.04 - Brake Test	Passed	فحص الفرامل
14 Exhaust Gas Test		الغاز العادم والكربون
14.01 - Exhaust Gas Test	Passed	فحص الغاز العادم-الكربون
16 Side Slip Test		فحص ميزانية الاطارات
16.01 - Side Slip Test	Failed	فحص ميزانية الاطارات
VISUAL TEST:		
02 Steering And Suspension System		عجلة القيادة ونظام التوصيلات
02.06 - Steering Wheel Alignment	NEED WHEEL ALIGNMENT	ميزانية عجلة القيادة
04 Tires Rims		الاطارات والعجلات
04.01 - Front Left And Right Hands Tires	DOT 2019	الاطارات الامامية
04.04 - Rear Left And Right Hand Tires	DOT 2018	الاطارات الخلفية
05 Body		الهيكل
05.04 - Fenders	FRONT FENDER FRAME , WHEEL HOUSING REPAIRED	المدكار
05.07 - Floor	RIGHT SIDE RUNNING BOARD , BACK PANEL , REAR QUARTER PANEL , RR RHS TRIALING ARM BRAKET REPAIRED	الارضية
05.08 - Chassis (Frame)	FRONT RIGHT SIDE CHASSIS REPAIRED	الشاصية
05.12 - Side Safety Frame	BULK HEAD REPAIRED	الواقيات الجانبية
06 General Items		الاشياء العامة
06.12 - Seats Condition And Seats Fixing	INTERIOR PARTLY WORNOUT	المقاعد وحالتها وثبيتها
06.14 - Transmission Condition	GEAR OIL LEAK	حالة ناقل الحركة
06.16 - Engine Condition, Smoke	OK	حالة المحرك - الدخان
07 Remarks		ملاحظات
07.04 - Others	123498 KM	ملاحظات اخرى
09 Auction		الفحص الكامل
09.14 - Sign Of Front Accident		أثر حادث في مقدمة المركبة
09.15 - Sign Of Rear Accident		أثر حادث في مؤخرة المركبة
09.25 - Body Repainted	BODY PORTION REPAIRED	أثر صبغ في المركبة



Test Certificate

Site Number	: 840-EMIRATES AUCTION	Plate Code	: 0
Transaction Number	: 20024466	Plate Category	: PRIVATE
Transaction Date	: 22 JUN 2020 11:02:01	Plate Number	: 03640 EA
Queue Number	: 187264	Import Doc. Ref.	:
Chassis Number	: MHKMF53F3GK003640	Manufacturer/Model	: TOYOTA/AVANZA
Engine Number	:	Model Year	: 2016
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: WHITE
Service / Indicator	: DSC AUCTION		

Statement of Vehicle Condition

The Test Certificate Shows the test Result at the time of inspection only.

Test Certificate



PASS

Change possession :	64330335	
Chassis No :	MHKMF53F3GK003640	
Vehicle Make :	TOYOTA	
Vehicle Model :	AVANZA	
Vehicle Class :	Light Vehicle	
Body Type :	STATION	
Fuel :	Benzene	
Color :	White	
Drive Direction :	--	
Dimensions : (H x W x L) -- x -- x --		
Current Odometer :	123501 Kms.	
Origin :	Indonesia	Model Year :
Gear Type :	--	2016
Engine No :	2NRF523849	Engine Size :
Axles No :	2	1500 CC
No Of Doors :	4	Horse Power :
G. V. W. :	2000 Kgs.	83
		Cylinders :
		4
		No Of Seats :
		7
		Empty Weight :
		1200 Kgs.

Certificate Number :	5-TAS-2020-12047600	
Inspection Date :	24-06-2020	
Certificate Print Date :	24-06-2020	
Services :	Registration Test	
Vehicle Testing Partner :	Tasjeel	
Vehicle Testing Center :	Tasjeel Emirates Auction	
Total Time Taken :	24 min 31 sec	
Appointment Ref Number :	--	
Start Time :	End Time :	
10:37	11:02	
Lane :	Token No. :	
01	4	
Attempt :	Prints No. :	
1	1	

Carbon footprint



Vehicle Consumption (last 12 Months)

37565 KM	2110 L	3419 AED	5.1 ton
Distance per year	Fuel consumed per year	Fuel cost per year	Carbon footprint per year

Parameter Readings

Service brake imbalance on front axle 9 %	Service brake imbalance on rear axle 3 %	Parking brake imbalance between LHS and RHS 0 %	Vehicle on Petrol CO Reading 0.01 %
Vehicle on Petrol HC Reading 0 PPM VOL			

Inspection Remarks:

FRONT RIGHT SIDE FENDER FRAME, APRON, BULK HEAD, A/PILLAR POST, ROCKER PANEL, WHEEL ARC, RUNNING BOARD, REAR RIGHT SIDE QUARTER PANEL, VALANCE PANEL REPAIRED. FRONT RIGHT FRAME MEMBER OUTER SKIRT DENT OLD BODY MINOR DENT SCRATCHES //

Payment Details

Inspection Performed by 34980	Payment Method VTP Credit Account	Transaction Number 12047600	Service Fees AED 170 Collected on 24/06/2020
Parking Slot No --	Service Name Registration Test	Attempt 1	Received by Raul Canceran Galang

This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.
Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص. المؤسسة غير مسؤولة عن العيوب الغير مرئية و الفحص، الفهر، يتم ظاهريا طبقا لقانون السير الصادر في 21 يونيو 2005.

