



## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>19 Apr 2022, 15:06:36</b>
Transaction Number	<b>81544405 (CC10006)</b>	Queue Number	<b>312309</b>



Chassis Number	<b>WDB2401781A001541</b>
Engine Number	
Vehicle Class	<b>Car</b>
Manufacturer	<b>Mercedes</b>
Model	<b>Maybach 63</b>
Model Year	<b>2006</b>
Color	<b>White</b>
Mileage	<b>101763 Km</b>
Fuel Type	<b>Petrol</b>
No. Of Cylinders	<b>12</b>
Specification	<b>GCC Specification</b>

DEFECT	REMARKS	
<b>01 Interior Condition</b>		<b>الحاله الداخليه</b>
01.A AC Condition	OK & AC GRILL ADJUSTMENT BUTTON DAMAGED	المكيف
01.B Door Panel	REAR LEFT SIDE PORTION DAMAGED	لوحة بطانة الباب
01.C Power Window Switch	REAR BOTH SIDE WINDOW CURTAIN NOT WORKING PROPERLY	مفتاح النافذه
01.D Sun Visor	BOTH SIDE GLASS COVER DAMAGED	حاجب الشمس
<b>02 Body</b>		<b>جسم المركبة</b>
02.A Fenders	FRONT BOTH SIDE REPAINTED PORTION REPAIRED & REFITTED	مدكار
02.B Paint	BODY PORTION REPAIRED , REPAINTED & MINOR DENT SCRATCHES	الصبغ
02.C Bonnet	PORTION REPAIRED,REPAINTED & REFITTED,SHOCK STAND NOT WORKING	غطاء المحرك
02.D Sign of front accident		وجود مؤشر لحادث في المقدمة
02.E Other	FRONT RADIATOR SUPPORT ,BULK HEAD ,BUMPER FRAME REPAIRED	اخرى
02.F Door Handle &Lock	DOOR AUTO CLOSING NOT WORKING	مقابض الأبواب والأقفال
<b>03 Seats Condition</b>		<b>المقاعد</b>

DEFECT	REMARKS	
03.A Seat Condition	REAR LEFT SIDE ADJUSTMENT NOT WORKING & FRONT LEFT SIDE SEAT ADJUSTMENT BUTTON MISSING	حالة المقاعد
<b>04 Transmission Condition</b>		<b>الجير</b>
04.A Road Test	NOT CHECK	فحص علي الطريق
04.B Visual Gear Box Condition	SIGN OF MINOR OIL LEAK	حالة الجير النظرى
<b>05 Steering Condition</b>		<b>المقود</b>
05.A Axle	REAR AXLE BOOT CUT	اكسلات
<b>06 Tires and Rims Condition</b>		<b>الاطارات</b>
06.A Front Tyre	BOTH SIDE 2020	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2020	الاطار الخلفي
<b>07 Engine Condition</b>		<b>المحرك</b>
07.A Visual Engine Condition	REFITTED	حالة المحرك النظرى
<b>08 Chassis Condition</b>		<b>الشاسي</b>
08.A Chassis	FRONT BOTH SIDE CHASSIS END REPAIRED	الشاسيه

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

# Test Certificate



Vehicle  
Registration



✓ PASS

Change possession :	66405352
Chassis No :	WDB2401781A001541
Vehicle Make :	MERCEDES
Vehicle Model :	MAYBACH 63
Vehicle Class :	Light Vehicle
Body Type :	SALOON
Fuel :	Benzene
Color :	White
Drive Direction :	Left Hand Side
Dimensions : (H x W x L) :	-- x -- x --
Current Odometer :	101764 Kms.
Origin :	Germany
Model Year :	2006
Gear Type :	Automatic
Engine Size :	6000 CC
Engine No :	28595040...
Horse Power :	--
Axles No :	2
Cylinders :	12
No Of Doors :	4
No Of Seats :	4
G. V. W. :	Empty Weight : 2000 Kgs. 2850 Kgs.

Certificate Number :	5-TAS-2022-16657781
Inspection Date :	24-04-2022
Certificate Print Date :	24-04-2022
Services :	Registration Test
Vehicle Testing Partner :	Tasjeel
Vehicle Testing Center :	Tasjeel Al Qusais
Total Time Taken :	2 min 50 sec
Appointment Ref Number :	--
Start Time :	16:11
End Time :	16:14
Lane :	08
Token No. :	523
Attempt :	2
Prints No :	1

## Carbon footprint



Thank you! You are environment protector

## Estimated Vehicle Consumption (Rate in 12 Months)

5356 KM	552 L	895 AED	1.4 ton
Distance per year	Fuel consumed per year	Fuel cost per year	Carbon footprint per year

Inspection Remarks: FRONT BULK HEAD , BUMPER FRAME , RADIATOR SUPPORT , HOOD REPAIRED/CHANGE REAR AXLE BOOT

## Payment Details

Inspection Performed by 35823 62426 62426	Payment Method Cash	Transaction Number 16657781	Service Fees AED 70 Collected on 24/04/2022
Parking Slot No --	Service Name Registration Test	Attempt 2	Received by Kishore Thekkathu Valappil

1 This is to acknowledge the receipt of AED 70 (in words: Seventy Dirhams Only.), towards the above service.

2 Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالترخيص الفني للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص.

This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.

