

TEST CERTIFICATE

Site Number
Transaction Number

840-Emirates Auctions 67641679 (CC10006) Transaction Date

20 Nov 2021, 17:54:45

Queue Number

312309



Chassis Number WDDLJ9BB5DA060391

Engine Number

Vehicle Class Car

Manufacturer Mercedes

Model CLS 550

Model Year 2013

Color White

Mileage 70703 Km

Fuel Type Petrol

No. Of Cylinders

Specification USA Imported

DEFECT REMARKS

O1 Body		جسم المركبة
01.A Paint	BODY PORTION REPAINTED, PORTION REPAIRED	الصبغ
01.B Fenders	REPAINTED, PORTION REPAIRED&FRONT FENDER REFITIED	مدكار
01.C Doors	FRONT BOTH DOOR REPAINTED ,PORTION REPAIRED	أبواب
01.D Pillars	A/PILLAR OUTER PORTION REPAINTED, REPAIRED	القوائم
O1.E Floor	RIGHT FLOOR REAINFORCEMENT MINOR DENT &FLOOR COVER DAMAGED	الارضية
01.F Bumper	REPAINTED	دعامية
01.G Other	FRONT FENDER FRAME ,BULK HEAD,BUMPER FRAME RADIATOR SUPPORT REPAIRED	اخري
01.H Sign of front accident		وجود مؤشر لحادث في المقدمة
01.I Roof	ROOF HAVE BLACK STICKER PAINT NOT CHECK	السقف
01.J Bonnet	REPAINTED,PORTION REPAIRED,OPENING HANDLE LOOSE ,SHOCK STAND WEAK	غطاء المحرك

02 Tires and Rims Condition

02.A Front TyreBOTH SIDE 2019 CRACKED & WORN OUTBOTH SIDE 2019 & INNER WORN OUT02.B Rear TyreBOTH SIDE 2019 & INNER WORN OUTBOTH SIDE 2019 & INNER WORN OUT02.C Rims ConditionRIMS HAVE MINOR SCRATCHESحالة الجنوط

DEFECT	REMARKS	
02.D Spare Tire &Tools	TOOLS MISSING	الاطار الاحتياطي و العدة
03 Chassis Condition		الشاصي
03.A Chassis	ОК	الشاسيه
04 Engine Condition		المحرك
04.A Engine Condition	OIL LEAK ,REFITIED,ABNORMAL NOISY	حالة المحرك
05 Transmission Condition		الجير
05.A Road Test	NOT CHECK	فحص علي الطريق
05.B Gear Box	MINOR OIL LEAK ,REFITIED	الجير
06 Exhaust System		نظام العادم
06.A Modification	MODIFIED	تعديلات
07 Seats Condition		المقاعد
07.A Seat Belt	ОК	حزام الأمان
07.B Seat Condition	FRONT RIGHT SIDE SEAT ADJUSTMENT NOT WORKING	حالة المقاعد
08 Wipers and Arms		المساحات
08.A Wiper Arm &Blade	WORNOUT	ازرع المساحات والشفرات
09 Interior Condition		الحاله الداخليه
09.A AC Condition	NOT WORKING &CENTER GRILL ADJUSTMENT BUTTON MISSING &NOT WORKING	المكيف
09.B Roof Ceiling	PORTION LOOSED&REAR COVER MISALIGN	بطانه السقف
09.C Audio	FRONT LEFT SIDE DOOR SPEAKER LOOSED	صوتيات
10 Suspension System		ممتص الصدمات
10.A Suspension Subframe	FRONT MINOR DENT	
10.B Other	FRONT LEFT SIDE STABILIZER STABILITY CONTROL LINK BROKEN	اخري
11 Brake Condition		الفرامل
11.A Disc&Drum	GETTING MINOR RUSTY	دسك وطنابير الفرامل
12 Lights		الاضاءة
12.A Head Light	RIGHT SIDE HIGH BEAM NOT WORKING &LENS MINOR FADED	الاضاءة الرئيسية
13 Steering Condition		المقود

 The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's



 شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

3 of 3



- condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate,
 Car Check does not guarantee the vehicle's fitness for registration.

 كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.