







Test Certificate

Import Doc. Ref.

Site Number 840-EMIRATES AUCTION Plate Code 0

Transaction Number 20912018 Plate Category **PRIVATE** Transaction Date 03 SEP 2020 11:28:21 Plate Number 467 EA

Queue Number 214772

Chassis Number JN8AY2ND2H9000467 Manufacturer/Model : NISSAN/ARMADA

Engine Number

Model Year 2017 Vehicle Class LIGHT VEHICLE Vehicle Color **BLACK**

Service / Indicator DSC AUCTION

Statement of Vehicle Condition

		Statement of Vehicle Condition	
Defect	Result	Remarks	
AUTOMATIC TEST:			
13 Brake System			فر امل
13.04 - Brake Test	Passed		حص الفرامل
14 Exhaust Gas Test			غاز العادم والكربون
14.01 - Exhaust Gas Test	Passed		حص الغاز العادم-الكربون
VISUAL TEST:			
02 Steering And Suspension System			عجلة القيادة ونظام التوصيلات
02.15 - Suspension Crack Or Bend, Bushes		SUSPENSION COMPONENTS DENTS	تويصلات
03 Brake System			ظام الفرامل
03.01 - Brake Efficiency Front Wheels Left And Right Hands		BRAKE ROTORS RUSTY/ BRAKE PADS ALMOST WORN OUT	وة فرامل المحور الامامي
04 Tires Rims			لاطارات والعجلات
04.01 - Front Left And Right Hands Tires		ALL TIRES DOT 2016	لاطارات الامامية
05 Body			لهيكل
05.02 - Paint		BODY SCRATCHES & DENTS	لصبغ
05.04 - Fenders		FRONT FENDERS REPLACED	لمدكار
05.05 - Bumpers		MISALIGN	دعامية
05.08 - Chassis (Frame)		FRONT LEFT SIDE MEMBER OUTER DENT / UNDER CHASSIS SCRATCHES & DENTS	اشاصية
06 General Items			لاشياء العامة
06.12 - Seats Condition And Seats Fixing		INTERIOR PARTLY WORN OUT	لمقاعد وحالتها وتثبيتها
06.14 - Transmission Condition		ОК	مالة ناقل الحركة
06.16 - Engine Condition, Smoke		ОК	عالة المحرك - الدخان
07 Remarks			للحظات
07.04 - Others		56016 MILES	للحظات اخرى
09 Auction			فحص الكامل
09.02 - Need Wheel Alignment			حاجة الى ميزانية العجلات
09.14 - Sign Of Front Accident		FENDER FRAME/ BULKHEAD/ RADIATOR SUPPORT REPAIRED/ CRASHBOX DISCONNECTED	ثر حادث في مقدمة المركبة
09.15 - Sign Of Rear Accident		REAR RIGHT QUARTER PANEL REPAIRED	نر حادث في مؤخرة المركبة





Test Certificate

Site Number : 840-EMIRATES AUCTION Plate Code :

Transaction Number : 20912018 Plate Category : PRIVATE

Transaction Date : 03 SEP 2020 11:28:21 Plate Number : 467 EA

Queue Number : 214772

Chassis Number : JN8AY2ND2H9000467 Manufacturer/Model : NISSAN/ARMADA

Engine Number : Model Year

Vehicle Class : LIGHT VEHICLE Vehicle Color : BLACK

Service / Indicator : DSC AUCTION

Statement of Vehicle Condition

2017

09.24 - Digital Display Damaged/Warning Lights SRS AIRBAG LIGHT ON

Import Doc. Ref.

ثر صبغ في المركبة BODY PORTIONS REPAINTED

The Test Certificate Shows the test Result at the time of inspection only.

Tasjeel is not responsible for any hidden defects.

شهادة الفحص تظهر نتيجة الفحص وقت الفحص فقط تسجيل غير مسئولة عن العيوب الخفية

Test Certificate









Possession Certificate: 64547529

Chassis No:

JN8AY2ND2H9000467

Vehicle Make:

NISSAN

Vehicle Model:

ARMADA

Vehicle Class:

Light Vehicle

Body Type:

STATION

Fuel:

Benzene

Color:

Black

Drive Direction:

Dimensions : (H x W x L) --x--x--

Current Odometer:

90152 Kms.

Origin: Gear Type:

Japan

Engine No: NIL

Axles No: 2

No Of Doors: 4

Ġ. V. W. : 2800 Kgs. Model Year:

Engine Size:

Horse Power: --

Cylinders: No Of Seats: 8

Empty Weight: 2000 Kgs.

5600 CC

Certificate Number:

5-TAS-2020-12488663

Inspection Date: Certificate Print Date :

06-09-2020 06-09-2020

Services:

Registration Test

Vehicle Testing Partner:

Tasjeel

Vehicle Testing Center:

Tasjeel Emirates Auction

Total Time Taken:

10 min 9 sec

Appointment Ref Number : --

Start Time: 11:59

Lane:

Attempt:

End Time: 12:09

Token No.: 8

Prints No: 1

Carbon footprint



12+

ton CO2

10488 KM

Distance per

year

1080 L

per year

Fuel consumed

Estimated Vehicle Consumption (Rate in 12 Months)

1750 AED Fuel cost per year

0.01%

2.6 ton

Carbon footprint per year

Parameter Readings

Vehicle on Petrol HC

Service brake imbalance on

Thank you! You are environment protector

front axle

2%

Reading 13 PPM VOL Service brake imbalance on rear axle

0%

Parking brake imbalance between LHS and RHS

3%

Vehicle on Petrol CO Reading

Inspection Remarks:

FRONT LEFT SIDE OUTER CHASSIS MINOR DENT / FRONT FENDER FRAME , RADIATOR SUPPORT FRAME , REAR QUARTER PANEL , TAIL DOOR,REAR CROSS MEMBER REPAIRED,BUMPER REPLACED,MINOR SCRATCHES ON BODY

Payment Details

Parking Slot No

Inspection Performed by

inspection done-According to Traffic law No., 21 year 1995

59460

Payment Method VTP Credit Account

Service Name Registration Test

Transaction Number

Attempt

12488663

Service Fees

AED 170 Collected on 06/09/2020

Received by

Raul Canceran Galang

This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.

Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص . المؤسسة ُغير مسئولة عن العيوب الغير مراّئية و الفحص الفني يتم ظاهريا طبقا

لقانون السير و المرور 21 لسنة 1995

This certificate is valid for one transaction only for 30 days from the date of inspection. Company not responsible for any hidden defects and

