





Test Certificate

Site Number	: 840-EMIRATES AUCTION	Plate Code	: 0
Transaction Number	: 20501033	Plate Category	: PRIVATE
Transaction Date	: 06 AUG 2020 15:55:04	Plate Number	: 095929 EA
Queue Number	: 203272	Import Doc. Ref.	:
Chassis Number	: JTMHU09J1E4095929	Manufacturer/Model	: TOYOTA/LAND CRUISER
Engine Number	:	Model Year	: 2014
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: WHITE
Service / Indicator	: DSC AUCTION		

Statement of Vehicle Condition

Defect	Result	Remarks
AUTOMATIC TEST:		
13 Brake System		الفرامل
13.04 - Brake Test	Passed	فحص الفرامل
14 Exhaust Gas Test		الغاز العادم والكربون
14.01 - Exhaust Gas Test	Passed	فحص الغاز العادم-الكربون
16 Side Slip Test		فحص ميزانية الاطارات
16.01 - Side Slip Test	Passed	فحص ميزانية الاطارات
VISUAL TEST:		
01 Lights		الانوار
01.02 - Tail Lights		الانوار الخلفية RIGHT SIDE TAIL LIGHT LENS PARTLY BROKEN & REVERSE LENS FADED
02 Steering And Suspension System		عجلة القيادة ونظام التوصيلات
02.15 - Suspension Crack Or Bend, Bushes		التوصيلات FRONT LEFT LOWER SUSPENSION BUSH CRACKED
04 Tires Rims		الاطارات والعجلات
04.01 - Front Left And Right Hands Tires		الاطارات الامامية DOT 4612
04.08 - Spare Tires		الاطار الاحتياطي SPARE TIRE MOUNTING BRACKET & REAR DOOR PILLAR RUSTY REPAIRED
05 Body		الهيكل
05.02 - Paint		الصيغ PARTLY DENT/SCRATCHES
05.06 - Roof		السقف PARTLY RUSTY & DENT
05.08 - Chassis (Frame)		الشاصية CHASSIS FRAME & UNDERNEATH COMPONENT RUSTY/PAINTED RUSTPROOF
05.09 - Front And Rear Windshields		الزجاج الامامي والخلفي FRONT SPOT CRACKED
05.10 - All Glasses		الزجاج الجانبي وزجاج الابواب FRONT RIGHT POWER WINDOW & BOTH SIDE MIRROR ADJUSTMENT MULFUNCTION
06 General Items		الاشياء العامة
06.12 - Seats Condition And Seats Fixing		المقاعد وحالتها وتثبيتها DRIVER SEAT PARTLY TORN/STEERING ADJUSTMENT NOT WORKING
06.13 - Exhaust System		نظام العادم CUT & WELDED
06.14 - Transmission Condition		حالة ناقل الحركة OK
06.16 - Engine Condition, Smoke		حالة المحرك - الدخان OIL LEAK



Test Certificate

Site Number	: 840-EMIRATES AUCTION	Plate Code	: 0
Transaction Number	: 20501033	Plate Category	: PRIVATE
Transaction Date	: 06 AUG 2020 15:55:04	Plate Number	: 095929 EA
Queue Number	: 203272	Import Doc. Ref.	:
Chassis Number	: JTMHU09J1E4095929	Manufacturer/Model	: TOYOTA/LAND CRUISER
Engine Number	:	Model Year	: 2014
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: WHITE
Service / Indicator	: DSC AUCTION		

Statement of Vehicle Condition

07 Remarks		ملاحظات
07.04 - Others	342627 KM	ملاحظات اخرى
09 Auction		الفحص الكامل
09.02 - Need Wheel Alignment		بحاجة الى ميزانية العجلات
09.20 - Differential Not Ok	FRONT DIFFIRENTIAL OIL LEAK	عطل في الدفرنش

The Test Certificate Shows the test Result at the time of inspection only.
Tasjeel is not responsible for any hidden defects.

شهادة الفحص تظهر نتيجة الفحص وقت الفحص فقط
تسجيل غير مسؤولة عن العيوب الخفية

Test Certificate



PASS

Plate Details :	--
Chassis No :	JTMHU09J1E4095929
Vehicle Make :	TOYOTA
Vehicle Model :	LAND CRUISER
Vehicle Class :	Light Vehicle
Body Type :	STATION
Fuel :	Benzene
Color :	White, Pearl
Drive Direction :	--
Dimensions : (H x W x L) -- x -- x --	
Current Odometer :	342628 Kms.
Origin : Japan	Model Year : 2014
Gear Type : --	Engine Size : 5700 CC
Engine No : 1GRA926749	Horse Power : 413
Axles No : 2	Cylinders : 6
No Of Doors : 4	No Of Seats : 8
G. V. W. : 2883 Kgs.	Empty Weight : 1900 Kgs.

Certificate Number :	5-TAS-2020-12305549
Inspection Date :	09-08-2020
Certificate Print Date :	09-08-2020
Services :	Registration Test
Vehicle Testing Partner :	Tasjeel
Vehicle Testing Center :	Tasjeel Emirates Auction
Total Time Taken :	14 min 28 sec
Appointment Ref Number :	--
Start Time : 12:41	End Time : 12:55
Lane : 01	Token No. : 8
Attempt : 1	Prints No : 1

Carbon footprint



Take action to protect Dubai environment

Estimated Vehicle Consumption (Rate in 12 Months)

38069 KM	3918 L	6348 AED	9.4 ton
Distance per year	Fuel consumed per year	Fuel cost per year	Carbon footprint per year

Parameter Readings

Service brake imbalance on front axle 5 %	Service brake imbalance on rear axle 3 %	Parking brake imbalance between LHS and RHS 2 %	Vehicle on Petrol CO Reading 0.02 %
Vehicle on Petrol HC Reading 10 PPM VOL			

Inspection Findings

Discrepancies	Old Value	New Value	Verified
Engine Size Discrepancy in Engine Size	5700	4000	

Inspection Remarks: CHASSIS /SUSPENSION & UNDER BODY COMPONENTS RUSTY & PAINTED