



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	25 Dec 2021, 17:53:59
Transaction Number	58108210 (CC10006)	Queue Number	312309



Chassis Number	1GNEK18K1SJ374889
Engine Number	
Vehicle Class	Car
Manufacturer	Chevrolet
Model	Tahoe
Model Year	1995
Color	Gold
Mileage	227827 Km
Fuel Type	Petrol
No. Of Cylinders	8
Specification	USA Imported

DEFECT	REMARKS	
01 Body		جسم المركبة
01.A Fenders	REPAIRED & REPAINTED	مدكار
01.B Doors	REPAIRED & REPAINTED	أبواب
01.C Bonnet	REPAIRED & REPAINTED	غطاء المحرك
01.D Roof	REPAIRED & REPAINTED	السقف
01.E Trunk	REPAIRED & REPAINTED	صندوق
01.F Paint	TOTALLY REPAINTED , REPAIRED & DENTS , SCRATCHES ON BODY	الصبغ
02 Tires and Rims Condition		الاطارات
02.A Front Tyre	BOTH SIDE 2021	الاطار الامامي
02.B Rear Tyre	BOTH SIDE 2021	الاطار الخلفي
03 Wipers and Arms		المساحات
03.A Wiper Arm &Blade	WORN OUT	ازرع المساحات والشفرات
04 Interior Condition		الحاله الداخليه
04.A Mirror	NOT WORKING & LEFT SIDE COVER PORTION DAMAGED	المرايا
04.B Sun Visor	BOTH SIDE MISSING	حاجب الشمس
04.C Dash Board	PORTION DAMAGED	لوحة القيادة

DEFECT	REMARKS	
04.D AC Condition	A/C NOT COOLING	المكيف
05 Seats Condition		المقاعد
05.A Seat Belt	NOT WORKING	حزام الأمان
05.B Seat Condition	BOTH SIDE LOOSE	حالة المقاعد
06 Chassis Condition		الشاسي
06.A Chassis	CHASSIS FRAME COMPLETELY THICK RUST PROOFED & BOTH SIDE PORTION DENT	الشاسيه
06.B Chassis Number	VIN NUMBER ON DOOR DAMAGED, ON DASH BOARD & INNER BOX NOT MATCHING	رقم القاعدة
07 Engine Condition		المحرك
07.A Engine Condition	OIL LEAK	حالة المحرك
07.B Mount	BUSHES CRACKED	كرسي
07.C Modification	AIR FILTER MODIFIED	تعديلات
08 Transmission Condition		الجير
08.A Road Test	NOT CHECK	فحص علي الطريق
08.B Gear Box	OIL LEAK	الجير
09 Lights		الاضاءة
09.A Head Light	RIGHT SIDE LOW & HIGH BEAM NOT WORKING	الاضاءة الرئيسية
10 Steering Condition		المقود
10.A Other	STABILIZER LINK BOOT CUT	اخرى
10.B Tie Rod End	BUSHES CRACKED	مؤخرة الرودادت
10.C Steering Oil	OIL LEAK	زيت المقود
11 Suspension System		ممتص الصدمات
11.A Shock Absorber	WEAK	ممتص الصدمات
12 Brake Condition		الفرامل
12.A Brake Pedal	BRAKE PADEL SPONGY & WEAK	دواسة الفرامل
12.B Hand Brake	NOT WORKING	فرامل اليد

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

Test Certificate



Vehicle
Registration



X FAILED

Plate Details :	--
Chassis No :	1GNEK18K1S374889
Vehicle Make :	CHEVROLET
Vehicle Model :	TAHOE
Vehicle Class :	Light Vehicle
Body Type :	JEEP
Fuel :	Benzene
Color :	Golden
Drive Direction :	--
Dimensions : (H x W x L) :	-- x -- x --
Current Odometer :	366653 Kms.
Origin : United States	Model Year : 1995
Gear Type : Automatic	Engine Size : 6600 CC
Engine No : NIL	Horse Power : 210
Axles No : 2	Cylinders : 8
No Of Doors : 2	No Of Seats : 5
G. V. W. : 3175 Kgs.	Empty Weight : 2121 Kgs.

Certificate Number :	5-TAS-2021-15785836
Inspection Date :	29-12-2021
Certificate Print Date :	29-12-2021
Services :	Registration Test
Vehicle Testing Partner :	Tasjeel
Vehicle Testing Center :	Tasjeel Al Aweer
Total Time Taken :	27 min 7 sec
Appointment Ref Number :	--
Start Time : 13:04	End Time : 13:31
Lane : 03	Token No. : 148
Attempt : 1	Prints No : 1

Parameter Readings

Service brake imbalance on front axle 25 %	Service brake imbalance on rear axle 38 %	Parking brake imbalance between LHS and RHS 34 %	Vehicle on Petrol CO Reading 2.4 %
Vehicle on Petrol HC Reading 2067 PPM VOL			

Inspection Findings

Defects	Issue	Severity
Vehicle on Petrol HC Reading	HC reading more than 800ppm	Major
Vehicle on Petrol HC Reading	HC reading more than 800ppm	Major
Pedal REPAIR BRAKE PEDAL SPONGY	Hard/spongy	Major
Dip beams(Low Beams) headlight REPAIR	Busted bulb	Major
Doors and Locks REPAIR TRUNK DOOR NOT OPEN	Not open/close properly	Major
Service brake imbalance on rear axle	More than 30% imbalance between LHS and RHS	Major

Discrepancies	Old Value	New Value	Verified
Engine Size Discrepancy in Engine Size	6600	5700	

Inspection Remarks: RIGHT SIDE CHASSIS OLD REPAIRED.UNDER BODY & CHASSIS FRAME RUST PROOFED.

Payment Details

Inspection Performed by 37084	Payment Method Cash	Transaction Number 15785836	Service Fees AED 170 Collected on 29/12/2021
Parking Slot No --	Service Name Registration Test	Attempt 1	Received by Hussain Basha Akeel

1 This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.

1 Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالترخيص الفني للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص



This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.