

TEST CERTIFICATE

السقف

Site Number 840-Emirates Auctions Transaction Date 16 Sep 2021, 18:02:20

Transaction Number 89678367 (CC10006) Queue Number 312309



Chassis Number

Ingine Number

Vehicle Class

Car

Vehicle Class Car

Manufacturer Toyota

Model Camry

Model Year 2018

Color Brown

Mileage 48404

 PORTION REPAIRED, REPAINTED

 01.B Paint
 PORTION REPAIRED, REPAINTED & DENTS, SCRATCHES ON BODY

أبواب O1.C Doors PORTION REPAIRED, REPAINTED أبواب O1.D Rusty UNDER BODY PARTS GETTING RUSTY

O1.E Floor REAR BOTH SIDE QUATER PANEL, BACK PANEL, SPARE

WHEEL HOUSING REPAIRED

O1.F Bumper REPAINTED قعامية

01.G Roof PORTION REPAIRED, REPAINTED & SLYDING ROOF

MODIFIED

غطاء المحرك REPAINTED

O1.I Other FRONT FENDER FRAME, BUMPER FRAME , RADITOR
SUPPORT , BULK HEAD REPAIRED

الشاصي 02 Chassis Condition

O2.A Chassis ExtensionREAR BOTH SIDE REPLACED02.B ChassisFRONT BOTH SIDE REPAIRED

03 Engine ConditionOK03.A OtherOK

O4 Seats Condition عدالمقاعد

O4.A Other OK

DEFECT	REMARKS	
05 Transmission Condition		الجير
05.A Gear Box	OIL LEAK	الجير
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2018	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2018	الاطار الخلفي
07 Wipers and Arms		المساحات
07.A Other	OK	اخري
08 Lights		الاضاءة
08.A Head Light	ОК	الاضاءة الرئيسية
08.B Other	OK	اخري
09 Brake Condition		الفرامل
09.A Caliber Brake	GETTING RUSTY	جهاز الفرامل
10 Interior Condition		الاجزاء الداخلية
10.A Other	ОК	اخري
10.B Mirror	OK	المرايا
10.C AC Condition	OK	المكيف

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

Test Certificate









Plate Details: 3 65309 Sharjah Private Chassis No: JTNBF9HKXJ3006451 Vehicle Make: TOYOTA Vehicle Model: CAMRY Vehicle Class: Light Vehicle **Body Type:** SALOON Fuel: Benzene Color: **Drive Direction:** Dimensions: (H x W x L) --x--x--**Current Odometer:** 48405 Kms. Origin: Japan Model Year: 2018 2400 CC **Engine Size:** Gear Type: Automatic Engine No: Horse Power: 180 2AR1922073 Axles No: Cylinders: No Of Doors: 4 No Of Seats: G. V. W. : Empty Weight: 1475 Kgs. 1850 Kgs.

rear axle

3 %

Certificate Number: 5-TAS-2021-15062674 Inspection Date: 21-09-2021 **Certificate Print Date:** 21-09-2021 Services: Registration Test Vehicle Testing Partner: Tasjeel Vehicle Testing Center: Tasjeel Al Aweer Total Time Taken: 24 min 2 sec Appointment Ref Number : --Start Time: 9:47 End Time: 10:11 Token No.: 107 Lane: Prints No: 1 Attempt : 1

Parameter Readings

Service brake imbalance on front axle

2%

Vehicle on Petrol HC Reading 92 PPM VOL

Parking brake imbalance Service brake imbalance on

between LHS and RHS

Vehicle on Petrol CO Reading 0.27 %

Inspection Findings

Defects	Issue	Severity
Battery fix battery clamp properly	Unsecure	Major
Warning triangle keep	Missing	Major
Tinted remove dark tinting	Dark	Major
Gear/Differential repair	Oil leaking continuously	Major
Rear registration plate lamps repair	Defective	Major
Steering Boots and Ball Joints repair front left steering boot	Worn-out or missing boot(s) (Major)	Major
Tie-rod, Bushes, Center Link	Excessive wear or defective tie-rod, bushes or link	Major
change front both side link bushes		
Axles fix front both axle boot clip properly and clean for recheck	Clips, locks or pin missing	Major
Chassis remove front and rear fender cover and under cover/ clean proper	Others (Major) rly for recheck	Major

Inspection Remarks: bulk head ,fender frame , apron , rear chassis extension and compartment panel repaired



Payment Details Inspection Performed by

Payment Method

Transaction Number 15062674

Service Fees AED 170 Collected on 21/09/2021
 Parking Slot No
 Service Name
 Attempt
 Received by

 - Registration Test
 1
 Sittu Paloth Sreesan Paloth

1 This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.

Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.
TA
تستخدم هذه الشهادة حصرا في العمليات الخاصة بالترخيص الفني للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية
ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال
30.



This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.