







Test Certificate

Import Doc. Ref.

Site Number 840-EMIRATES AUCTION Plate Code : 0

: PRIVATE Transaction Number 24358980 Plate Category Transaction Date 20 FEB 2021 16:15:39 Plate Number 012664 EA

299720 Queue Number

: TOYOTA/HI ACE Chassis Number JTGJS02PX80012664 Manufacturer/Model

Engine Number

Vehicle Class

Model Year 2008 LIGHT VEHICLE Vehicle Color : WHITE

Service / Indicator DSC AUCTION

Defect	Result	Remarks	
	Resuit	Remarks	
AUTOMATIC TEST:			
13 Brake System			لفر امل
13.04 - Brake Test	Passed		حص الفر امل
VISUAL TEST:			
01 Lights			لانوار
01.04 - Head Lights		RIGHT SIDE FADED & MOISTURE	لانوار الامامية
02 Steering And Suspension System			عجلة القيادة ونظام التوصيلات
02.15 - Suspension Crack Or Bend, Bushes		SUSPENSION BUSHES CRACK	لتويصلات
02.17 - Gear Box Mounting		MOUNTING CRACK	كراسي ناقل الحركة
04 Tires Rims			لاطارات والعجلات
04.01 - Front Left And Right Hands Tires		TIRES 2019	لاطار ات الامامية
04.08 - Spare Tires		NOT AVAILABLE	لاطار الاحتياطي
05 Body			لهيكل
05.01 - Rusty		SUSPENSION & UNDER BODY COMPONENTS RUSTY (CORRODED)	لصدأ
05.03 - Doors		TAIL DOOR PILLAR & BACK PANEL REPAIRED	لابو اب
05.08 - Chassis (Frame)		REAR BOTH SIDE FRAME MEMBER REPAIRED & PARTLY RUSTED	لشاصية
05.10 - All Glasses		LEFT WINDOW NOT CLOSING	لزجاج الجانبي وزجاج الابواب
06 General Items			لاشياء العامة
06.12 - Seats Condition And Seats Fixing		INTERIOR PARTLY WORN OUT	لمقاعد وحالتها وتثبيتها
06.14 - Transmission Condition		OIL LEAK/GEAR DEFECTIVE (REVERSE GEAR NOT ENGAGE)	حالة ناقل الحركة
06.15 - Clutch		CLUTCH DEFFECTIVE (PEDAL SPONGY	الكاتش
06.16 - Engine Condition, Smoke		ENGINE RE-FITTED & OIL LEAKING	حالة المحرك - الدخان
07 Remarks			ملاحظات
07.04 - Others		699353 KM	للحظات اخرى
09 Auction			لفحص الكامل
09.02 - Need Wheel Alignment			حاجة الى ميز انية العجلات
09.15 - Sign Of Rear Accident			ثر حادث في مؤخرة المركبة عطل في المكيف
09.18 - A/C Not Cooling			عطل في المكيف





Test Certificate

Site Number : 840-EMIRATES AUCTION Plate Code

Transaction Number : 24358980 Plate Category : PRIVATE

Transaction Date : 20 FEB 2021 16:15:39 Plate Number : 012664 EA

Queue Number : 299720

Chassis Number : JTGJS02PX80012664 Manufacturer/Model : TOYOTA/HI ACE

Engine Number :

Vehicle Class : LIGHT VEHICLE Vehicle Color : WHITE

Service / Indicator : DSC AUCTION

Statement of Vehicle Condition

2008

09.24 - Digital Display Damaged/Warning Lights CHECK ENGINE LIGHT ON

09.25 Rody Repairted RODY PORTIONS REPAINTED

Import Doc. Ref.

Model Year

09.25 - Body Repainted BODY PORTIONS REPAINTED و المركبة

The Test Certificate Shows the test Result at the time of inspection only.

Tasjeel is not responsible for any hidden defects.

شهادة الفحص تظهر نتيجة الفحص وقت الفحص فقط تسجيل غير مسئولة عن العيوب الخفية

Test Certificate









Plate Details: JTGJS02PX80012664 Chassis No: Vehicle Make: TOYOTA Vehicle Model: HIACE Vehicle Class: Light Bus **Body Type:** Light Bus Fuel: Diesel Color: White **Drive Direction: Dimensions**: (H x W x L) --x--x--**Current Odometer:** 699355 Kms. Origin: Japan Model Year: 2008 Engine Size: 2700 CC Gear Type: --Engine No: 1721111 Horse Power: 150 Axles No: Cylinders: No Of Doors: 3 No Of Seats: 15 G. V. W. : Empty Weight: 1010 Kgs. 1020 Kgs.

Certificate Number :	5-TAS-2021-13679427					
Inspection Date :	25-02-2021					
Certificate Print Date :	25-02-2021					
Services :	Registration Test					
Vehicle Testing Partner:	Tasjeel					
Vehicle Testing Center:	Tasjeel Warsan					
Total Time Taken: 15 min 15 sec						
Appointment Ref Number:						
Start Time: 14:49	End Time: 15:04					
Lane: 01	Token No.: 205					
Attempt: 1	Prints No: 1					

Parameter Readings

Service brake imbalance on front axle 14 %

Service brake imbalance on rear axle 24 %

Parking brake imbalance between LHS and RHS 18 % **Turbo K-Value** 0.45 PPM VOL

Severity

Inspection Findings

Defects

Discrepancies	Old Value New	Value	Verified
Fire extinguisher (for commercial) KEEP 2 KG	Missing	Major	
First Aid Box/Medical kit (commercial)	Missing	Major	
Weight and Capacity Sticker FIX BOTH SIDE DOOR WEIGHT STICKER	Not available on both front doors	Major	
Vehicle Floor REPAIR FRONT LEFT SIDE FLOOR AND REAR BOTH SIDE VAL	Damaged/heavily corroded ANCE PANEL RUSTY HOLE	Major	
Bulkhead/Cross member CHANGE RADIATOR LOWER FRAME RUSTY HOLE	Heavily corroded	Major	
Doors and Locks TAIL DOOR NOT OPEN	Not open/close properly	Major	
Stop lamps REPAIR STOP LAMB NOT WORKING	Bulb busted	Major	
Engine REPAIR	Oil leaking continuously	Major	
Direction-indicator lamps REAR LEFT SIDE NOT WORKING	Bulb busted	Major	
Warning triangle	Missing	Major	
Gear/Differential REPAIR	Oil leaking continuously	Major	
CHANGE BOTH SIDE LOWER ARM RUSTY HOLE	arm		
Arm, mounting, bushes	Rusted or corroded arm mounting	, or Major	
Dip beams(Low Beams) headlight CLEAN RIGHT SIDE HEAD LIGHT FADED	Lens cracked, broken or faded	Major	

Issue

Inspection Remarks: MINOR DENT AND SCRATCHES ON BODY, AVOID UNDER BODY PARTS GETTING RYSTY

Seats Incorrect Number of Seats

12

34875	Cash	13679427	AED 170 Collected on 25/02/2021	
Parking Slot No	Service Name	Attempt	Received by	
	Registration Test	1	Jalaludheen Thekkechali	

- This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.
- Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.
 المؤسسة غير مسئولة عن العيوب الفير مرئية و الفحص الفني يتم ظاهريا طبقا
 TASEEL لقانون السير و المرور 21 لسنة 1995 This certificate is valid for one transaction only for 30 days from the date of inspection. Company not responsible for any hidden defects and



inspection done-According to Traffic law No., 21 year 1995