

03.B Mount

04 Transmission Condition

TEST CERTIFICATE

كرسي

الجير

Site Number 840-Emirates Auctions Transaction Date 17 Jul 2022, 14:56:31

Transaction Number 53141600 (CC10006) Queue Number 312309



Chassis Number **2FMDK4JC0DBB15032**

Engine Number

Vehicle Class Car

Manufacturer Ford

Model Edge

Model Year 2013

Color Red

Mileage **392865 Km**

Fuel Type Petrol

No. Of Cylinders

Specification USA Imported

DEFECT REMARKS

جسم المركبة		O1 Body
الصبغ	BODY PORTION REPAIRED , REPAINTED & MINOR DENT ,SCRATCHES	01.A Paint
الارضية	UNDER BODY PARTS & SUSPENTION, FLOOR, CHASSIS RUSTY & VEHICLE SIGN OF FLODING	01.B Floor
مدكار	FRONT RIGHT SIDE PORTION REPAINTED & FRONT LEFT SIDE REPAIRED, REPAINTED, REFITTED	01.C Fenders
غطاء المحرك	REPAIRED, REPAINTED & REFITTED	01.D Bonnet
أبواب	FRONT LEFT SIDE PORTION REPAIRED, REPAINTED	01.E Doors
الاضاءة		02 Lights
الاشارات	FRONT RIGHT SIDE INDICATOR NOT WORKING	02.A Indicator & Hazard light
ضوء تحذير	WARNING LIGHTS ON IN DISPLAY	02.B Warning Light
الاضاءة الرئيسية	BOTH SIDE LOW,HIGH BEAM NOT WORKING PROPERLY	02.C Head Light
المحرك		03 Engine Condition
حالة المحرك النظرى	MINOR OIL LEAK & REFITTED	03.A Visual Engine Condition

MOUNT BUSH CRACKED

DEFECT	REMARKS	
04.A Visual Gear Box Condition	MINOR OIL LEAK & REFITTED	حالة الجير النظرى
04.B Road Test	NOT CHECK	فحص علي الطريق
04.C Gear Box Mount	MOUNT BUSH CRACKED	كرسي الجير
05 Suspension System		ممتص الصدمات
05.A Ball Joint	BOOT CUT	مفصل كروي
05.B Arms	FRONT LOWER ARM BUSH CRACKED	ازرع
05.C Other	STABILIZER LINK BOOT CUT	اخري
06 Steering Condition		المقود
06.A Tie Rod End	BOOT CUT	مؤخرة الرودات
07 Chassis Condition		الشاصي
07.A Chassis	BOTH SIDE CHASSIS RUSTY WEAK	الشاسيه
07.B Chassis Number	CHASSIS NUMBER MANUFACTUR STICKER DAMAGED	رقم القاعدة
08 Tires and Rims Condition		الاطارات
08.A Front Tyre	BOTH SIDE 2019 CRACKED	الاطار الامامي
08.B Rear Tyre	BOTH SIDE 2019 CRACKED, WORN OUT	الاطار الخلفي
09 Interior Condition		الحاله الداخليه
09.A AC Condition	NOT COOLING	المكيف
10 Brake Condition		الفرامل
10.A Brake Pedal	SPONGY WEAK	دواسة الفرامل

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate,
 Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا
 تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من

Test Certificate









Plate Details :

5:			
	2FMDK4JC0DBB15032		
e :	F	ORD	
el:	E	DGE	
s :	Light Vehicle		
	STATION		
	Benzene		
	Red		
on :	-	-	
: (H x W x L)		-xx	
meter :	39	92910 Kms.	
Canada		Model Year:	2013
Automatic		Engine Size:	3500 CC
NIL		Horse	285
2		Power :	
4		Cylinders:	6
		No Of Seats:	5
2000 Kgs.		Empty Weight:	1600 Kgs.
	e: el: s: con: con: conda Automatic NIL 2 4	2	2FMDK4JCODBB15 e: FORD el: EDGE s: Light Vehicle STATION Benzene Red On: : (H x W x L)xx meter: 392910 Kms. Canada Model Year: Automatic Engine Size: NIL Horse Power: Cylinders: No Of Seats: Empty

Certificate	Number :	5-TAS-2022-17391184				
Inspection Date :			11-08-2022			
Certificate	Print Date :	11-08-2022				
Services :		Registration Test				
Vehicle Te	sting Partner:	Tasjeel				
Vehicle Te	sting Center:	Tasjeel Al Aweer				
Total Time	e Taken:	6 min 26 sec				
Appointme Number :	ent Ref					
Start	15:00		End Time:	15:07		
Time :			Token No.:	178		
Lane:	02		Prints No :	1		
Attempt :	2	_				

Parameter Readings

Service brake imbalance on front axle rear axle
14 % 8 %

Inspection Findings

Defects	Issue	Severity
Pedal BRAKE PEDAL SPONGY	Hard/spongy	Major
Battery	Unsecure	Major
Tire CHANGE ALL	Ply exposed	Major

Inspection Remarks: Rear differential removed, under body floor rust proofed.

Payment Details

 Inspection Performed by
 Payment Method
 Transaction Number
 Service Fees

 32858
 2ash
 17391184
 AED 70 Collected on 11/08/2022

 35063
 Parking Slot No
 Service Name
 Attempt
 Received by

 - Registration Test
 2
 Sittu Paloth Sreesan Paloth

- 1 This is to acknowledge the receipt of AED 70 (in words: Seventy Dirhams Only.), towards the above service.
- Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.
 تستخدم هذه الشهادة حصرا في العمليات الخاصة بالترخيص الفني للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية
 ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أُصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال
 30. يوم من تاريخ الفحص

TASIEEL

This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.