



### Test Certificate

Site Number	: 840-EMIRATES AUCTION	Plate Code	: 0
Transaction Number	: 26058486	Plate Category	: PRIVATE
Transaction Date	: 04 MAY 2021 13:34:55	Plate Number	: 030829 EA
Queue Number	: 329918	Import Doc. Ref.	:
Chassis Number	: MR0EX12G5A2030829	Manufacturer/Model	: TOYOTA/HILUX
Engine Number	:	Model Year	: 2010
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: SILVER
Service / Indicator	: DSC AUCTION		

### Statement of Vehicle Condition

Defect	Result	Remarks
AUTOMATIC TEST:		
14 Exhaust Gas Test		الغاز العادم والكربون
14.01 - Exhaust Gas Test	Passed	فحص الغاز العادم-الكربون
VISUAL TEST:		
02 Steering And Suspension System		عجلة القيادة ونظام التوصيلات
02.04 - Steering Ball Joints, Boots		وصلات عمود عجلة القيادة
		BOTH SIDE STEERING BOOT CRACK& OIL LEAK
04 Tires Rims		الاطارات والعجلات
04.01 - Front Left And Right Hands Tires		الاطارات الامامية
		TIRES 2019
05 Body		الهيكل
05.01 - Rusty		الصدأ
		CHASSIS & UNDER BODY COMPONENTS RUSTY
05.02 - Paint		الصبغ
		BODY SCRATCH & DENT
05.05 - Bumpers		الدعامية
		FRONT BUMPER MISALIGN
05.08 - Chassis (Frame)		الشاصية
		FRONT BOTH SIDE CHASSIS END REPAIRED
05.12 - Side Safety Frame		الواقبات الجانبية
		BULKHEAD/RADIATOR SUPPORT & FENDER FRAME REPAIRED
06 General Items		الاشياء العامة
06.12 - Seats Condition And Seats Fixing		المقاعد وحالتها وتثبيتها
		INTERIOR PARTLY WORN OUT
07 Remarks		ملاحظات
07.04 - Others		ملاحظات اخرى
		579884 KM / BONNET REPLACED
09 Auction		الفحص الكامل
09.02 - Need Wheel Alignment		بحاجة الى ميزانية العجلات
09.09 - Engine And Gear Box Performance Ok	OK	فحص حالة الماكينة والجير
09.10 - Engine Oil Leaking	OIL LEAK	تهريب زيت المحرك
09.14 - Sign Of Front Accident		أثر حادث في مقدمة المركبة
09.25 - Body Repainted		أثر صبغ في المركبة

The Test Certificate Shows the test Result at the time of inspection only.  
Tasjeel is not responsible for any hidden defects.

شهادة الفحص تظهر نتيجة الفحص وقت الفحص فقط  
تسجيل غير مسؤولة عن العيوب الخفية

# Test Certificate



X FAILED

Plate Details :	--
Chassis No :	MR0EX12G5A2030829
Vehicle Make :	TOYOTA
Vehicle Model :	HILUX
Vehicle Class :	Light Vehicle
Body Type :	PICK-UP
Fuel :	Benzene
Color :	Silver
Drive Direction :	--
Dimensions : (H x W x L) :	-- x -- x --
Current Odometer :	579886 Kms.
Origin :	Thailand
Model Year :	2010
Gear Type :	--
Engine Size :	2694 CC
Engine No :	5022095
Horse Power :	200
Axles No :	2
Cylinders :	4
No Of Doors :	4
No Of Seats :	5
G. V. W. :	2500 Kgs.
Empty Weight :	1497 Kgs.

Certificate Number :	5-TAS-2021-14149701
Inspection Date :	06-05-2021
Certificate Print Date :	06-05-2021
Services :	Registration Test
Vehicle Testing Partner :	Tasjeel
Vehicle Testing Center :	Tasjeel Emirates Auction
Total Time Taken :	15 min 29 sec
Appointment Ref Number :	--
Start Time :	11:58
End Time :	12:14
Lane :	01
Token No. :	8
Attempt :	1
Prints No. :	1

## Parameter Readings

Service brake imbalance on front axle	Service brake imbalance on rear axle	Parking brake imbalance between LHS and RHS	Vehicle on Petrol CO Reading
4 %	24 %	8 %	0.32 %
Vehicle on Petrol HC Reading			
128 PPM VOL			

## Inspection Findings

Defects	Issue	Severity
Dip beams( Low Beams) headlight <b>CLEAN LEFT SIDE LENS FADED</b>	Lens cracked, broken or faded	Major
Front Seat belts <b>REPAIR FRONT RIGHT SEAT BELT DEFECTIVE</b>	Defective	Major
Warning triangle	Missing	Major
Gear/Differential <b>REPLACE GEARBOX MOUNTS CRACK</b>	Worn out rubber mountings (Major)	Major
Steering Boots and Ball Joints <b>REPLACE BOTH SIDE STEERING BOOTS &amp; FIX FLUID LEAK</b>	Worn-out or missing boot(s) (Major)	Major
Bumper <b>FIX FRONT BUMPER PROPERLY</b>	Misaligned (Major)	Major

## Inspection Remarks:

FRONT BOTH SIDE CHASSIS END REPAIRED/ BULKHEAD/RADIATOR SUPPORT & FENDER FRAME REPAIRED/ ENGINE MINOR OIL LEAK/ BODY MINOR SCRATCHES & DENTS/ UNDER BODY MINOR RUSTY

## Payment Details

Inspection Performed by	Payment Method	Transaction Number	Service Fees
74791	VTP Credit Account	14149701	AED 170 Collected on 06/05/2021
Parking Slot No	Service Name	Attempt	Received by
--	Registration Test	1	Raul Canceran Galang

This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.

Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص. المؤسسة غير مسئولة عن العيوب الغير مرئية و الفحص الفني يتم ظاهريا طبقا لقانون السير و المرور 21 لسنة 1995

This certificate is valid for one transaction only for 30 days from the date of inspection. Company not responsible for any hidden defects and

