



## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>02 Aug 2022, 13:33:10</b>
Transaction Number	<b>14531688 (CC10006)</b>	Queue Number	<b>312309</b>



Chassis Number	<b>1ZVBP8AMXE5327212</b>
Engine Number	
Vehicle Class	<b>Car</b>
Manufacturer	<b>Ford</b>
Model	<b>Mustang</b>
Model Year	<b>2014</b>
Color	<b>Black</b>
Mileage	<b>150912 Miles</b>
Fuel Type	<b>Petrol</b>
No. Of Cylinders	<b>6</b>
Specification	<b>USA Imported</b>

DEFECT	REMARKS	
<b>01 Body</b>		<b>جسم المركبة</b>
01.A Paint	BODY REPAINTED,PORTION REPAIRED,MINOR DENT ,SCRATCHES	الصبغ
01.B Fenders	FRONT REFITTED	مدكار
01.C Bonnet	REFITTED	غطاء المحرك
01.D Pillars	BOTH SIDE B/PILLAR REPIRED	القوائم
01.E Sign of side accident		وجود مؤشر لحادث في الجانب
01.F Bumper	MISALIGN	دعامية
01.G Sign of back accident		وجود مؤشر لحادث في الخلف
01.H Floor	BACK PANEL REAR RIGHT SIDE QUARTER PANEL WHEEL ARCH REPAIRED	الارضية
<b>02 Interior Condition</b>		<b>الحاله الداخليه</b>
02.A AC Condition	RIGHT SIDE LOW COOLING	المكيف
02.B Other	GEAR SHIFTING LEVER DUST COVER MISSING	اخرى
02.C Power Window Switch	RIGHT SIDE NOT WORKING PROPERLY	مفتاح النافذه
<b>03 Tires and Rims Condition</b>		<b>الاطارات</b>
03.A Front Tyre	BOTH SIDE 2022	الاطار الامامي

DEFECT	REMARKS	
03.B Rear Tyre	BOTH SIDE 2021	الاطار الخلفي
<b>04 Transmission Condition</b>		<b>الجير</b>
04.A Road Test	NOT CHECK	فحص علي الطريق
04.B Visual Gear Box Condition	MINOR OIL LEAK	حالة الجير النظري
04.C Gear Box Mount	MOUNT RUBBER CRACKED	كرسي الجير
04.D DIFFERENTIAL	REAR DIFFRENTIAL OIL LEAK	الدفرنشل
<b>05 Engine Condition</b>		<b>المحرك</b>
05.A Visual Engine Condition	MINOR OIL LEAK	حالة المحرك النظري
05.B Mount	MOUNT RUBBER CRACKED	كرسي
<b>06 Suspension System</b>		<b>ممتص الصدمات</b>
06.A Arms	LOWER ARM BUSHES CRACKED	ازرع
06.B Ball Joint	BOOT CRACKED	مفصل كروي
<b>07 Steering Condition</b>		<b>المقود</b>
07.A Tie Rod End	BOOT CRACKED	مؤخرة الرودادت
<b>08 Seats Condition</b>		<b>المقاعد</b>
08.A Seat Condition	FRONT SEATS PORTION DAMAGED	حالة المقاعد
<b>09 Chassis Condition</b>		<b>الشاسي</b>
09.A Chassis	REAR RIGHT SIDE CHASSIS DETACHED&TWISTED	الشاسيه

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

# Test Certificate



Vehicle  
Registration



X FAILED

Change possession :	66737114
Chassis No :	1ZVBP8AMXE5327212
Vehicle Make :	FORD
Vehicle Model :	MUSTANG
Vehicle Class :	Light Vehicle
Body Type :	Coupe
Fuel :	Benzene
Color :	Black
Drive Direction :	--
Dimensions : (H x W x L)	-- x -- x --
Current Odometer :	242874 Kms.
Origin : United States	Model Year : 2014
Gear Type : Automatic	Engine Size : 3600 CC
Engine No : NIL	Horse 305
Axles No : 2	Power :
No Of 2	Cylinders : 6
Doors :	No Of Seats : 4
G. V. W. : 2000 Kgs.	Empty 1655 Kgs.
	Weight :

Certificate Number :	5-TAS-2022-17330991		
Inspection Date :	03-08-2022		
Certificate Print Date :	03-08-2022		
Services :	Registration Test		
Vehicle Testing Partner :	Tasjeel		
Vehicle Testing Center :	Tasjeel Al Aweer		
Total Time Taken :	9 min 53 sec		
Appointment Ref Number :	--		
Start Time :	9:50	End Time :	10:00
Lane :	01	Token No. :	117
Attempt :	2	Prints No. :	1

## Inspection Findings

Defects	Issue	Severity
Tinted remove front windshield faded tint	Dark	Major
Paint repaint body paint faded portions	Others (Minor)	Minor
Engine repair engine oil leak	Others (Major)	Major
Bumper front bumper fix properly	Unsecure	Major

Inspection Remarks: REAR LEFT QUARTER PANEL REPAIRED // MINOR DENT AND SCRATCHES ON BODY

## Payment Details

Inspection Performed by 3104	Payment Method Cash	Transaction Number 17330991	Service Fees AED 70 Collected on 03/08/2022
Parking Slot No --	Service Name Registration Test	Attempt 2	Received by Sittu Paloth Sreesan Paloth

1 This is to acknowledge the receipt of AED 70 (in words: Seventy Dirhams Only.), towards the above service.

2 Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالترخيص الفني للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص



This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.