



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	11 Aug 2022, 17:52:32
Transaction Number	94191406 (CC10006)	Queue Number	312309



Chassis Number	JTEHJ09J535084265
Engine Number	
Vehicle Class	Car
Manufacturer	Toyota
Model	Land Cruiser
Model Year	2003
Color	White
Mileage	155319 Km
Fuel Type	Petrol
No. Of Cylinders	6
Specification	GCC Specification

DEFECT	REMARKS	
01 Lights		الاضاءة
01.A Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
02 Interior Condition		الحاله الداخليه
02.A AC Condition	NOT WORKING	المكيف
02.B Dash Board	PORTION CRACKED	لوحة القيادة
02.C Mirror	CENTER LOOSE	المرآيا
03 Body		جسم المركبة
03.A Paint	BODY TOTALY REPAINTED PORTION REPAIRED,MINOR DENTS SCRATCHES ON BODY ,,	الصبغ
03.B Roof	REPAINTED PORTION REPAIRED	السقف
03.C Sign of side accident		وجود مؤشر لحادث في الجانب
03.D Fenders	FRONT REFITTED REAR BOTH SIDE REPAIRED REPAINTED	مدكار
03.E Bonnet	REPAIRED REAPINTED REFITTED	غطاء المحرك
03.F Sign of front accident		وجود مؤشر لحادث في المقدمة
03.G Doors	REPAINTED PORTION REPAIRED	أبواب
03.H Other	FRONT BUMPER FRAME BULK HEAD FENDER FRAME RADIATOR SUPPORT REPAIRED	اخرى

DEFECT	REMARKS	
04 Engine Condition		المحرك
04.A Visual Engine Condition	MINOR OIL LEAK REFITTED	حالة المحرك النظري
04.B Smoke	BLACK SMOKE	دخان
04.C Mount	MOUNT RUBBER CUT	كرسي
05 Steering Condition		المقود
05.A Tie Rod End	BOOT CUT	مؤخرة الرودادات
05.B Steering Oil	MINOR OIL LEAK	زيت المقود
05.C Axle	BOOT CUT	اكسلات
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2019 CRACKED	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2019 CRACKED	الاطار الخلفي
07 Transmission Condition		الجير
07.A Visual Gear Box Condition	MINOR OIL LEAK REFITTED	حالة الجير النظري
07.B Gear Box Mount	MOUNT RUBBER CUT	كرسي الجير
07.C Road Test	NOT CHECKED	فحص علي الطريق
08 Chassis Condition		الشاسي
08.A Chassis	FRONT LEFT SIDE CHASSIS END OUTER MOUNT AREA REPAIRED	الشاسيه
09 Wipers and Arms		المساحات
09.A Wiper Arm & Blade	REAR MISSING	ازرع المساحات والشفرات

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

Test Certificate



Vehicle
Registration



✗ FAILED

Change possession :	65837824
Chassis No :	JTEHJ09J535084265
Vehicle Make :	TOYOTA
Vehicle Model :	LAND CRUISER
Vehicle Class :	Light Vehicle
Body Type :	STATION
Fuel :	Benzene
Color :	White
Drive Direction :	--
Dimensions : (H x W x L)	-- x -- x --
Current Odometer :	155310 Kms. ✗
Previous Odometer Reading :	236639 Kms.
Origin : Japan	Model Year : 2003
Gear Type : Automatic	Engine Size : 4500 CC
Engine No : 1FZ0583835	Horse : 323
Axles No : 2	Power :
No Of : 4	Cylinders : 6
Doors :	No Of Seats : 8
G. V. W. : 2500 Kgs.	Empty Weight : 2356 Kgs.

Certificate Number :	5-TAS-2022-16933187		
Inspection Date :	06-06-2022		
Certificate Print Date :	14-08-2022		
Services :	Registration Test		
Vehicle Testing Partner :	Tasjeel		
Vehicle Testing Center :	Tasjeel Al Aweer		
Total Time Taken :	9 min 34 sec		
Appointment Ref Number :	--		
Start Time :	14:32	End Time :	14:41
Lane :	02	Token No. :	196
Attempt :	1	Prints No :	2

Parameter Readings

Service brake imbalance on front axle	Service brake imbalance on rear axle	Parking brake imbalance between LHS and RHS	Vehicle on Petrol CO Reading
2 %	1 %	0 %	2.75 %
Vehicle on Petrol HC Reading			
258 PPM VOL			

Inspection Findings

Defects	Issue	Severity
Dip beams(Low Beams) headlight RIGHT SIDE LOW BEAM	Defective	Major
Direction-indicator lamps	Defective	Major
Engine WHITE SMOKE	Excessive oil smoke	Major

Discrepancies	Old Value	New Value	Verified
Odometer Device Odometer Reading Change	Authorized	Replaced	

Inspection Remarks:

FRONT CHASSIS END , BODY BRACKET , BULKHEAD , FENDER FRAME , REAR BACK PANEL, BOTH SIDE QUARTER PANEL REPAIRED. MINOR DENTS AND SCRATCHES ON BODY. //



Odometer Record

Replace Events Date

06/06/2022

Payment Details

Inspection Performed by	Payment Method	Transaction Number	Service Fees
71051	Cash	16933187	AED 170 Collected on 06/06/2022
Parking Slot No	Service Name	Attempt	Received by
--	Registration Test	1	Hussain Basha Akeel

- 1 This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.
1 Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالترخيص الفني للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أعراض البيع أو الشراء خلاف عملية ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال



30 يوم من تاريخ الفحص

This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.