



## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>12 May 2022, 11:44:29</b>
Transaction Number	<b>51445695 (CC10006)</b>	Queue Number	<b>312309</b>



Chassis Number	<b>JMYLRV93W8J712162</b>
Engine Number	
Vehicle Class	<b>Car</b>
Manufacturer	<b>Mitsubishi</b>
Model	<b>Pajero</b>
Model Year	<b>2008</b>
Color	<b>Black</b>
Mileage	<b>182805 Km</b>
Fuel Type	<b>Petrol</b>
No. Of Cylinders	<b>6</b>
Specification	<b>GCC Specification</b>

DEFECT	REMARKS	
<b>01 Engine Condition</b>		<b>المحرك</b>
01.A Smoke	WHITE SMOKE	دخان
01.B Visual Engine Condition	OIL LEAK & ABNORMAL NOISY	حالة المحرك النظري
01.C Mount	BUSHES CUT	كرسي
<b>02 Tires and Rims Condition</b>		<b>الاطارات</b>
02.A Rear Tyre	BOTH SIDE 2018	الاطار الخلفي
02.B Front Tyre	BOTH SIDE 2018	الاطار الامامي
<b>03 Transmission Condition</b>		<b>الجير</b>
03.A Visual Gear Box Condition	SHIFT LEVER BUTTON NOT WORKING & DUST COVER MISSING	حالة الجير النظري
03.B Road Test	NOT CHECK	فحص علي الطريق
<b>04 Lights</b>		<b>الاضاءة</b>
04.A Tail Light	LEFT SIDE BROKEN	الانارة
<b>05 Interior Condition</b>		<b>الحاله الداخليه</b>
05.A AC Condition	NOT WORKING & GRAIL DAMAGED	المكيف
05.B Dash Board	DASH BOARD PORTION DAMAGED & DISPLAY MISSING	لوحة القيادة

DEFECT	REMARKS	
<b>06 Body</b>		<b>جسم المركبة</b>
06.A Paint	DENTS, SCRATCHES ON BODY	الصبغ
06.B Bumper	PORTION DAMAGED	دعامية
<b>07 Steering Condition</b>		<b>المقود</b>
07.A Steering Oil	MINOR OIL LEAK	زيت المقود
07.B Steering Boot	BOOT CUT	ربلة المقود
<b>08 Chassis Condition</b>		<b>الشاسي</b>
08.A Chassis	OK	الشاسيه

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.