





Test Certificate

Site Number	: 840-EMIRATES AUCTION	Plate Code	: 0
Transaction Number	: 23078323	Plate Category	: PRIVATE
Transaction Date	: 21 DEC 2020 10:20:04	Plate Number	: 509231 EA
Queue Number	: 268710	Import Doc. Ref.	:
Chassis Number	: VF37ENFU9FJ509231	Manufacturer/Model	: PEUGEOT/PARTNER
Engine Number	:	Model Year	: 2015
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: WHITE
Service / Indicator	: DSC AUCTION		

Statement of Vehicle Condition

Defect	Result	Remarks
AUTOMATIC TEST:		
13 Brake System		الفرامل
13.04 - Brake Test	Passed	فحص الفرامل
14 Exhaust Gas Test		الغاز العادم والكربون
14.01 - Exhaust Gas Test	Passed	فحص الغاز العادم-الكربون
16 Side Slip Test		فحص ميزانية الاطارات
16.01 - Side Slip Test	Passed	فحص ميزانية الاطارات
VISUAL TEST:		
02 Steering And Suspension System		عجلة القيادة ونظام التوصيلات
02.08 - Power Steering Pump	OIL LEAK	المضخة الهيدرولكية للمقود
04 Tires Rims		الاطارات والعجلات
04.01 - Front Left And Right Hands Tires	FRONT TIRES DOT 2018/ REAR TIRES DOT 2017 & 2016/ FRONT TIRES WORN OUT	الاطارات الامامية
04.08 - Spare Tires	MISSING	الاطار الاحتياطي
05 Body		الهيكل
05.02 - Paint	BODY SCRATCH & DENT	الصبغ
05.05 - Bumpers	FRONT BUMPER REPAIRED	الدعامية
05.07 - Floor	UNDER FLOORING & FLOOR REINFORCEMENTS DENT	الارضية
05.08 - Chassis (Frame)	REAR RIGHT SIDE MEMBER END DENT	الشاصية
06 General Items		الاشياء العامة
06.08 - Interior Lights	INTERIOR PARTLY WORN OUT	الانوار الداخلية
06.14 - Transmission Condition	OIL LEAK	حالة ناقل الحركة
06.16 - Engine Condition, Smoke	MISFIRING/ DELAY STARTING	حالة المحرك - الدخان
06.20 - Fuel Tank	LEAK	خزان الوقود
07 Remarks		ملاحظات
07.04 - Others	236855 KM BONNET ROD MISSING	ملاحظات اخرى
09 Auction		الفحص الكامل
09.15 - Sign Of Rear Accident		أثر حادث في مؤخرة المركبة
09.16 - Sign Of Side Accident		أثر حادث في جوانب المركبة



Test Certificate

Site Number	: 840-EMIRATES AUCTION	Plate Code	: 0
Transaction Number	: 23078323	Plate Category	: PRIVATE
Transaction Date	: 21 DEC 2020 10:20:04	Plate Number	: 509231 EA
Queue Number	: 268710	Import Doc. Ref.	:
Chassis Number	: VF37ENFU9FJ509231	Manufacturer/Model	: PEUGEOT/PARTNER
Engine Number	:	Model Year	: 2015
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: WHITE
Service / Indicator	: DSC AUCTION		

Statement of Vehicle Condition

09.25 - Body Repainted	BODY PORTIONS REPAINTED	أثر صيغ في المركبة
<p>The Test Certificate Shows the test Result at the time of inspection only. Tasjeel is not responsible for any hidden defects.</p> <p style="text-align: right;">شهادة الفحص تظهر نتيجة الفحص وقت الفحص فقط تسجيل غير مسئولة عن العيوب الخفية</p>		

Test Certificate



X FAILED

Plate Details :	--
Chassis No :	VF37ENFU9FJ509231
Vehicle Make :	PEUGEOT
Vehicle Model :	PARTNER
Vehicle Class :	Light Vehicle
Body Type :	VAN
Fuel :	Benzene
Color :	White, Advertisement Stiker, Red
Drive Direction :	--
Dimensions : (H x W x L)	-- x -- x --
Current Odometer :	236855 Kms.
Origin : Spain	Model Year : 2015
Gear Type : --	Engine Size : 1294 CC
Engine No : 10FX8C350...	Horse Power : --
Axles No : 2	Cylinders : 4
No Of Doors : 4	No Of Seats : 2
G. V. W. : 1900 Kgs.	Empty Weight : 1250 Kgs.

Certificate Number :	5-TAS-2020-13227957
Inspection Date :	23-12-2020
Certificate Print Date :	23-12-2020
Services :	Registration Test
Vehicle Testing Partner :	Tasjeel
Vehicle Testing Center :	Tasjeel Emirates Auction
Total Time Taken : 16 min 30 sec	
Appointment Ref Number :	--
Start Time : 10:13	End Time : 10:30
Lane : 01	Token No. : 4
Attempt : 1	Prints No. : 1

Parameter Readings

Service brake imbalance on front axle 9 %	Service brake imbalance on rear axle 4 %	Parking brake imbalance between LHS and RHS 9 %	Vehicle on Petrol CO Reading 0 %
Vehicle on Petrol HC Reading 12 PPM VOL			

Inspection Findings

Defects	Issue	Severity
Reflector Triangle	Not Available	Major
Fuel tank and pipings repair fuel tank leak	Leaking	Major
Steering Box repair steering pump oil leak	Continuous or excessive oil leak	Major

Discrepancies	Old Value	New Value	Verified
Paint Removed Advertisement	White, Advertisement Stiker, Red	White	

Inspection Remarks: REAR RIGHT SIDE MEMBER END DENT

Payment Details

Inspection Performed by 59460	Payment Method VTP Credit Account	Transaction Number 13227957	Service Fees AED 170 Collected on 23/12/2020
Parking Slot No --	Service Name Registration Test	Attempt 1	Received by Raul Canceran Galang

- ① This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.
② Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص. المؤسسة غير مسؤولة عن العيوب الغير مرئية و الفحص الفني يتم ظاهريا طبقا لقانون السير و المرور 21 لسنة 1995
This certificate is valid for one transaction only for 30 days from the date of inspection. Company not responsible for any hidden defects and inspection done-According to Traffic law No., 21 year 1995

