



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	15 Jan 2023, 14:06:50
Transaction Number	76116566 (CC10009)	Queue Number	656728



Chassis Number	SCBFE63W7CC075928
Engine Number	
Vehicle Class	Car
Manufacturer	Bentley
Model	Continental
Model Year	2012
Color	Silver
Mileage	40532 Km
Fuel Type	Petrol
No. Of Cylinders	12
Specification	GCC Specification

DEFECT	REMARKS	
01 Transmission Condition		الجير
01.A Road Test	NOT CHECK	فحص علي الطريق
01.B Gear Box Mount	MOUNT CRACK	كرسي الجير
01.C Visual Gear Box Condition	SIGN OF MINOR OIL LEAK	حالة الجير النظرى
02 Body		جسم المركبة
02.A Bonnet	SHOCK WEAK & PORTION REPAIRED REPAINTED	غطاء المحرك
02.B Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENT,SCRATCHES	الصبغ
02.C Fenders	FRONT BOTH SIDE REPAIRED, REPAINTED & REFITTED	مدكار
02.D Floor	FLOOR CHASSIS COVERED CHECKED VISIBLE AREA ,RIGHT SIDE FLOOR PORTION DENT	الارضية
02.E Trunk	NOT WORKING PROPERLY & REFITTED	صندوق
02.F Sign of side accident		وجود مؤشر لحادث في الجانب
02.G Doors	FRONT RIGHT SIDE REPAIRED REPAINTED	أبواب
02.H Sign of front accident		وجود مؤشر لحادث في المقدمة
03 Chassis Condition		الشاسي
03.A Chassis	OK/CHASSIS PORTION COVERED CHECKED VISIBLE AREA	الشاسيه

DEFECT	REMARKS	
	ONLY	
03.B Chassis Number	FRONT LEFT SIDE CHASSIS NUMBER STICKER PORTION FADED	رقم القاعدة
04 Steering Condition		المقود
04.A Steering Boot	BOOT CUT	ربلة المقود
04.B Steering Oil	LEAK	زيت المقود
04.C Tie Rod End	BOOT CUT	مؤخرة الرودادات
05 Engine Condition		المحرك
05.A Mount	MOUNT CRACK	كرسي
05.B Visual Engine Condition	MINOR OIL LEAK	حالة المحرك النظري
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2020	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2020	الاطار الخلفي
07 Engine Cooling System		نظام تبريد المحرك
07.A Coolant tank	WATER LEAK	خزان التبريد
08 Interior Condition		الحالة الداخليه
08.A Mirror	RIGHT SIDE FOLDING NOT WORKING	المرايا
08.B AC Condition	LEFT SIDE AUTO SWITCH NOT WORKING , RIGHT SIDE OK	المكيف
09 Suspension System		ممتص الصدمات
09.A Arms	LOWER ARM BUSHES CRACKED	ازرع
09.B Ball Joint	BOOT CUT	مفصل كروي
10 Lights		الاضاءة
10.A Warning Light	WARNING LIGHT ON IN DISPLAY	ضوء تحذير

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.