





Test Certificate

Site Number	: 840-EMIRATES AUCTION	Plate Code	: 0
Transaction Number	: 27872774	Plate Category	: PRIVATE
Transaction Date	: 15 JUL 2021 10:39:39	Plate Number	: 000216 EA
Queue Number	: 368189	Import Doc. Ref.	:
Chassis Number	: JTEGS54M67A000216	Manufacturer/Model	: TOYOTA/PREVIA
Engine Number	:	Model Year	: 2007
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: WHITE
Service / Indicator	: DSC AUCTION		

Statement of Vehicle Condition

Defect	Result	Remarks
AUTOMATIC TEST:		
13 Brake System		الفرامل
13.04 - Brake Test	Passed	فحص الفرامل
14 Exhaust Gas Test		الغاز العادم والكربون
14.01 - Exhaust Gas Test	Passed	فحص الغاز العادم-الكربون
16 Side Slip Test		فحص ميزانية الاطارات
16.01 - Side Slip Test	Failed	فحص ميزانية الاطارات
VISUAL TEST:		
02 Steering And Suspension System		عجلة القيادة ونظام التوصيلات
02.05 - Steering Coupling, Column	NOISY	ثنائي توصلة المقود
02.13 - Stub Axle Assemblies, Boots	RIGHT SIDE INNER AXLE BOOT CRACK	المحور
04 Tires Rims		الاطارات والعجلات
04.01 - Front Left And Right Hands Tires	TIRES 2019	الاطارات الامامية
05 Body		الهيكل
05.02 - Paint	BODY SCRATCH & DENT & ROOF PARTLY RUSTY	الصبغ
05.05 - Bumpers	FRONT BUMPER SUPPORT & CRASH BOX REPAIRED	الدعامية
05.07 - Floor	BACK PANEL DENT	الارضية
05.08 - Chassis (Frame)	FRONT BOTH SIDE FRAME MEMBER END REPAIRED	الشاصية
05.09 - Front And Rear Windshields	FRONT WINDSHIELD REPLACED & CRACK	الزجاج الامامي والخلفي
05.12 - Side Safety Frame	BULKHEAD /RADIATOR SUPPORT & FENDER FRAME REPAIRED	الواقيات الجانبية
06 General Items		الاشياء العامة
06.01 - Wiper Blades	WIPER BLADES WORN OUT	ماسحات الزجاج الامامي
06.09 - Mirrors Rear View	REAR VIEW MIRROR DETACHED	المرآيا الداخلية
06.14 - Transmission Condition	OIL LEAK	حالة ناقل الحركة
06.16 - Engine Condition, Smoke	ENGINE BLACK SMOKE & OIL LEAK	حالة المحرك - الدخان
06.20 - Fuel Tank	FUEL TANK DENT	خزان الوقود
07 Remarks		ملاحظات
07.04 - Others	302227 KM	ملاحظات اخرى



Test Certificate

Site Number	: 840-EMIRATES AUCTION	Plate Code	: 0
Transaction Number	: 27872774	Plate Category	: PRIVATE
Transaction Date	: 15 JUL 2021 10:39:39	Plate Number	: 000216 EA
Queue Number	: 368189	Import Doc. Ref.	:
Chassis Number	: JTEGS54M67A000216	Manufacturer/Model	: TOYOTA/PREVIA
Engine Number	:	Model Year	: 2007
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: WHITE
Service / Indicator	: DSC AUCTION		

Statement of Vehicle Condition

09 Auction		الفحص الكامل
09.02 - Need Wheel Alignment		بحاجة الى ميزانية العجلات
09.14 - Sign Of Front Accident		أثر حادث في مقدمة المركبة
09.15 - Sign Of Rear Accident		أثر حادث في مؤخرة المركبة
09.16 - Sign Of Side Accident		أثر حادث في جوانب المركبة
09.24 - Digital Display Damaged/Warning Lights	AFS & AIR BAG LIGHT ON	عطل في لوحة التحكم الالكتروني
09.25 - Body Repainted		أثر صيغ في المركبة
<p>The Test Certificate Shows the test Result at the time of inspection only. Tasjeel is not responsible for any hidden defects.</p>		
<p>شهادة الفحص تظهر نتيجة الفحص وقت الفحص فقط تسجيل غير مسؤولة عن العيوب الخفية</p>		

Test Certificate



Vehicle
Registration



X FAILED

Possession Certificate : 65527245

Chassis No : JTEGS54M67A000216

Vehicle Make : TOYOTA

Vehicle Model : PREVIA

Vehicle Class : Light Vehicle

Body Type : STATION

Fuel : Benzene

Color : White

Drive Direction : --

Dimensions : (H x W x L) -- x -- x --

Current Odometer : 302228 Kms.

Origin : Japan Model Year : 2007

Gear Type : -- Engine Size : 3500 CC

Engine No : 2AZ 0330276 Horse Power : 162

Axles No : 2 Cylinders : 6

No Of Doors : 4 No Of Seats : 7

G. V. W. : Empty Weight : 1800 Kgs.
2600 Kgs.

Certificate Number : 5-TAS-2021-14639040

Inspection Date : 17-07-2021

Certificate Print Date : 17-07-2021

Services : Registration Test

Vehicle Testing Partner : Tasjeel

Vehicle Testing Center : Tasjeel Emirates Auction

Total Time Taken :
12 min 31 sec

Appointment Ref Number : --

Start Time : 14:55

End Time : 15:07

Lane : 01

Token No. : 7

Attempt : 1

Prints No : 1

Parameter Readings

Service brake imbalance on
front axle
2 %

Service brake imbalance on
rear axle
5 %

Parking brake imbalance
between LHS and RHS
0 %

Vehicle on Petrol CO
Reading
2.25 %

Vehicle on Petrol HC
Reading
195 PPM VOL

Inspection Findings

Defects	Issue	Severity
Engine ENGINE BLACK SMOKE & OIL LEAK	Others (Major)	Major
Reflector Triangle	Not Available	Major
Side/rear view mirror FIX REAR VIEW MIRROR DETACHED	Cracked/broken (Major)	Major

Inspection Remarks: FRONT BOTH SIDE FRAME MEMBER END REPAIRED FRONT BUMPER SUPPORT & CRASH BOX REPAIRED

Payment Details

Inspection Performed by
59460

Payment Method
VTP Credit Account

Transaction Number
14639040

Service Fees
AED 170 Collected on 17/07/2021

Parking Slot No
--

Service Name
Registration Test

Attempt
1

Received by
Raul Canceran Galang

1 This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.

1 Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص. المؤسسة غير مسئولة عن العيوب الغير مرئية و الفحص الفني يتم ظاهريا طبقا لقانون السير و المرور 21 لسنة 1995

This certificate is valid for one transaction only for 30 days from the date of inspection. Company not responsible for any hidden defects and inspection done-According to Traffic law No., 21 year 1995

